



End-of-Sale and End-of-Life Announcement for the Cisco ONS 15600 Series OC-48/STM-16 Long-Reach Modules

Cisco Systems® announces the end-of-sale and end-of-life dates for the Cisco® ONS 15600 Series OC-48/STM-16 Long-Reach Modules. The last day to order the affected product is November 28, 2006. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) until November 27, 2011. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product. Table 2 lists the product part numbers affected by this announcement.

Existing customers are not required to migrate to the Cisco ONS 15600 Series Any Service Any Port (ASAP) modules, which include part numbers 15600-ASAP-CC, 15600-ASAP-4PIO, and ONS-SE-2G-L2. Customers requiring OC-48/STM-16 long-haul or long-reach optics are encouraged to migrate to Cisco ONS 15600 Release 5.x (SONET) or 8.x (SDH) or later and replace with the Cisco 15600 Series ASAP modules. Information about the replacement products can be found at:

http://www.cisco.com/en/US/products/hw/optical/ps4533/products_data_sheet0900aecd80217d48.html. Table 2 provides relevant information for migrating to the replacement product.

Table 1. End-of-Life Milestones and Dates for the Cisco ONS 15600 Series OC-48/STM-16 Long-Reach Modules

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	May 30, 2006
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	November 28, 2006
Last Ship Date	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	February 26, 2007
End of Routine Failure Analysis Date	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	November 28, 2007
End of New Service Attachment Date	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	November 28, 2007
End of Service Contract Renewal Date	The last date to extend or renew a service contract for the product.	February 23, 2011
Last Date of Support	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	November 27, 2011

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
15600-48L16LR1550	OC-48, LR, 1550, 16 Ckt, MTP	15600-ASAP-4PIO=	Single Any Slot Any Port IO board with 4 empty SFP/PPM slots
15600-48L16LR1550	OC-48, LR, 1550, 16 Ckt, MTP	15600-ASAP-CC=	Any Slot Any Port Carrier Card, plugs into any IO slots
15600-48L16LR1550	OC-48, LR, 1550, 16 Ckt, MTP	ONS-SE-2G-L2=	SFP – OC-48/STM-16, LR2, L-16.2, 1550 nm, EXT-TEMP
15600-48L16LR1550=	OC-48, LR, 1550, 16 Ckt, MTP	15600-ASAP-4PIO	Single Any Slot Any Port IO board with 4 empty SFP/PPM slots

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
15600-48L16LR1550=	OC-48, LR, 1550, 16 Ckt, MTP	15600-ASAP-CC	Any Slot Any Port Carrier Card, plugs into any IO slots
15600-48L16LR1550=	OC-48, LR, 1550, 16 Ckt, MTP	ONS-SE-2G-L2	SFP – OC-48/STM-16, LR2, L-16.2, 1550 nm, EXT-TEMP

Product Migration Options

The recommended replacement for the Cisco ONS 15600 Series OC-48/STM-16 Long-Reach Modules is the Cisco ONS 15600 Series Any Service Any Port (ASAP) Modules.

Information about the replacement items can be found at:

http://www.cisco.com/en/US/products/hw/optical/ps4533/products_data_sheet0900aecd80217d48.html. Currently there are no customers required to trade in products listed in Table 2.

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

Customers may be able to continue to purchase the end-of-sale product through the Cisco Authorized Refurbished Equipment program. Refurbished units of the end-of-sale product are available in limited supply for sale in certain countries on a first-come, first-served basis. For information about the refurbished equipment program, go to:

http://www.cisco.com/en/US/ordering/or6/order_finance_and_payments_concept_home.html.

For More Information

For more information about the Cisco ONS 15600 Series OC-48/STM-16 Long-Reach Modules, visit

http://www.cisco.com/en/US/products/hw/optical/ps4533/prod_eol_notices_list.html.

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/prod_end_of_life.html.

To subscribe to receive end-of-life/end-of-sale information, go to: <http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>.

**Corporate Headquarters**

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters

Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems, Inc.
168 Robinson Road
#28-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the **Cisco Website at www.cisco.com/go/offices.**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica
Croatia • Cyprus • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR
Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico
The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia
Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan
Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2006 Cisco Systems, Inc. All rights reserved. Cisco, Cisco Systems, and the Cisco Systems logo are registered trademarks or trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0601R) XX/LW10XXX

