



# ONS 15808 Software and Firmware Matrix

[TAC Notice: What's Changing on TAC Web](#)

Document ID: 30020

Help us help you.

Cisco has announced the end of sales for the Cisco ONS 15808. For more information, see [EOS and EOL Announcement for ONS 15808 DWDM Platform](#).

Please rate this document.

- Excellent
- Good
- Average
- Fair
- Poor

This document solved my problem.

- Yes
- No
- Just browsing

Suggestions for improvement:

(256 character limit)

Send

## Contents

- [Introduction](#)
- [Prerequisites](#)
- [Requirements](#)
- [Components Used](#)
- [Conventions](#)
- [Cisco ONS 15808 Software and Firmware Matrix](#)
- [NetPro Discussion Forums - Featured Conversations](#)
- [Related Information](#)

## Introduction

This matrix defines the firmware versions that support ONS 15808 hardware versions, and also the software versions available for this card.

## Prerequisites

### Requirements

There are no specific requirements for this document.

### Components Used

The information in this document is based on the Cisco ONS 15808 Releases 2.0 through 2.2.

The information in this document was created from the devices in a specific lab environment. All of the devices used in this document started with a cleared (default) configuration. If your network is live, make sure that you understand the potential impact of any command.

### Conventions

For more information on document conventions, refer to the [Cisco Technical Tips Conventions](#).

## Cisco ONS 15808 Software and Firmware Matrix

Product ID / FW Board Name	Software Version	ONS 15808	Downloadable	Traffic Affecting

		Release 2.0	Release 2.1	Release 2.2		
<b>CPLT</b>						
SW-LCI-3.0-2.0	3.0.0	-	-	-	-	-
<b>CPTK</b>						
SW-LCI-3.0-2.0	2.0.0	-	-	-	-	-
<b>CWD</b>						
CWD	1.0.0	Yes	No	No		
	1.1.0	Yes	Yes	No		
	1.2.0	No	Yes	Yes		
<b>CTM</b>						
CTM	3.0.0				-	-
	3.1.0	Yes				
	3.2.0	Yes				
	4.0.0	Yes	Yes			
	4.1.0	Yes	Yes			
	4.6.0	Yes	Yes	Yes		
	5.0.0	No	Yes	Yes		
<b>TL1 Agent</b>						
CMP-TL1A-2.x	2.0.0	No	No	No	Yes	No
	2.1.0	Yes	No	No		
	2.3.0	No	Yes	No		
	2.4.0	No	No	Yes		
<b>SCC Master</b>						
APP_CMP_SCC	2.0.1	No	No	No	Yes	No
	2.0.2	Yes	Yes	Yes		
<b>SCC Slave</b>						
APP_SLAVE_SCC	2.1.1	Yes	Yes	Yes	Yes	No
	2.1.3	Yes	Yes	Yes		
<b>Common Parts</b>						
BOOT_68K	1.1.0	Yes	Yes	Yes	No	
	1.2.0	Yes	Yes	Yes		
LOADER_68K	1.1.0	Yes	Yes	Yes	No	
	1.2.0	Yes	Yes	Yes		
<b>OSCM</b>						
APP_OSCM_SCC_SLAVE	1.0.0	Yes	Yes	Yes	Yes	No
	1.0.1	Yes	Yes	Yes		
APP_OSCM_SCC	1.0.0	Yes	Yes	Yes	Yes	No
	1.0.1	Yes	Yes	Yes		
<b>UDC</b>						
APP_UDC_SCC	1.0.0	Yes	Yes	Yes	Yes	No
	1.0.1	Yes	Yes	Yes		
<b>SCU</b>						
APP_SCU_SCC	1.0.0	Yes	Yes	Yes	Yes	No

	1.0.1	Yes	Yes	Yes		
<b>AIU</b>						
APP_AIU_SCC	1.0.0	Yes	Yes	Yes	Yes	No
	1.0.1	Yes	Yes	Yes		
<b>SNS</b>						
APP_SNS_SCC	1.0.0	Yes	Yes	Yes	Yes	No
	1.0.1	Yes	Yes	Yes		
<b>SNH</b>						
APP_SNH_SCC	1.0.0	Yes	Yes	Yes	Yes	No
	1.0.1	Yes	Yes	Yes		
<b>TT-2.5G-XXX</b>						
APPL_WCM_25F	1.1.1	Yes	Yes	Yes	Yes	No
	1.2.0	Yes	Yes	Yes		
	1.2.1	-	Yes	Yes		
<b>LT-2.5G-XXX</b>						
APPL_LEM_25F	1.1.1	Yes	Yes	Yes	Yes	No
	1.2.0	Yes	Yes	Yes		
	1.2.1	-	Yes	Yes		
<b>RT-2.5G</b>						
APPL_RXT_25F	1.1.1	Yes	Yes	Yes	Yes	No
	1.2.0	Yes	Yes	Yes		
	1.2.1	-	Yes	Yes		
<b>TT-10G-XXX</b>						
APPL_WCM_10F	1.1.1	Yes	Yes	Yes	Yes	No
	1.2.0	Yes	Yes	Yes		
<b>LT-10G-XXX</b>						
APPL_LEM_10F	1.1.1	Yes	Yes	Yes	Yes	No
	1.2.0	Yes	Yes	Yes		
<b>RT-10G</b>						
APPL_RXT_10F	1.1.1	Yes	Yes	Yes	Yes	No
	1.2.0	Yes	Yes	Yes		
<b>OBA_C</b>						
APPL_OBA_C	1.0.0	Yes	Yes	Yes	Yes	No
	1.1.0	Yes	Yes	Yes		
<b>OPA_C</b>						
APPL_OPA_C	1.0.0	Yes	Yes	Yes	Yes	No
	1.1.0	Yes	Yes	Yes		
<b>BCS-LH</b>						
APPL_BCS-ELH	1.1.0	Yes	Yes	Yes	Yes	No
<b>OEP-C</b>						
APPL_OEP-C	1.0.0	Yes	Yes	Yes	Yes	No
	1.1.0	Yes	Yes	Yes		
<b>OECP-C</b>						
	1.0.0	Yes	Yes	Yes	Yes	No

APPL_OECP-C	1.1.0	Yes	Yes	Yes		
<b>40MD-C-O/E</b>						
APPL_40MD	1.0.0	Yes	Yes	Yes	Yes	No
	1.1.0	Yes	Yes	Yes		
<b>OAD-8-C</b>						
APPL_OAD-8-C	1.0.0	Yes	Yes	Yes	Yes	No
	1.1.0	Yes	Yes	Yes		
<b>OCP</b>						
APPL_OSU_SCC	1.0.14	Yes	Yes	Yes	Yes	No
	1.0.15	Yes	Yes	Yes		
<b>OA-ELH</b>						
APPL_OA-ELH	1.0.0	Yes	Yes	Yes		
<b>OP-ELH</b>						
APPL_OP-ELH	1.0.0	Yes	Yes	Yes		
<b>ORP-ELH-1/2</b>						
APPL_ORP-ELH	1.0.0	Yes	Yes	Yes		
<b>OECP-L</b>						
APPL_OECP-L	1.0.0	Yes	Yes	Yes		
<b>20MD-L-O/E</b>						
APPL_20MD	1.0.0	Yes	Yes	Yes		
<b>TT-10G-Syxx</b>						
APPL_WCM_10S	1.0.0	Yes	Yes	Yes		
	1.0.1	Yes	Yes	Yes		
<b>LT-10G-Syxx</b>						
APPL_LEM_10S	1.0.0	Yes	Yes	Yes		
	1.0.1	Yes	Yes	Yes		
<b>RT-10G-S</b>						
APPL_RXT_10S	1.0.0	Yes	Yes	Yes		
	1.0.1	Yes	Yes	Yes		
<b>BT-10E-Lyxx</b>						
APPL_10GE	1.0.1	Yes	Yes	Yes		
	1.1.0	Yes	Yes	Yes		

### Legend

- "No"—The software or firmware version is not managed by column Software Version.
- "Yes"—This firmware version has been tested with the column Software Version, or the product version has been tested.
- "-"—Not applicable.

## NetPro Discussion Forums - Featured Conversations

Networking Professionals Connection is a forum for networking professionals to share questions, suggestions, and information about networking solutions, products, and technologies. The featured links are some of the most recent conversations available in this technology.

[NetPro Discussion Forums - Featured Conversations for Optical](#)

Service Providers: Optical Networking
<a href="#">Gigabit Ethernet Design for LAN</a> - Feb 23, 2005 <a href="#">DS1 Port Switch To Protect ?</a> - Feb 18, 2005 <a href="#">need help locating CTM IDL files (release 5.0)</a> - Feb 18, 2005 <a href="#">Display line companding VISM v3.1</a> - Feb 17, 2005 <a href="#">GBIC Laser Issue</a> - Feb 10, 2005
Service Providers: Metro
<a href="#">Metro 3750 DC Question</a> - Feb 24, 2005 <a href="#">Q-in-Q support for PVST+</a> - Feb 23, 2005 <a href="#">Optical Design question. Ring, Star or Hybrid?</a> - Feb 18, 2005 <a href="#">Native VLAN tagging work-around?</a> - Feb 17, 2005 <a href="#">Using policy-map in 4500 switches</a> - Feb 16, 2005

---

## Related Information

- [Optical Product Support Pages](#)
- [Technical Support - Cisco Systems](#)

---

<a href="#">Home</a>	<a href="#">How to Buy</a>	<a href="#">Login</a>	<a href="#">Profile</a>	<a href="#">Feedback</a>	<a href="#">Site Map</a>	<a href="#">Help</a>
----------------------	----------------------------	-----------------------	-------------------------	--------------------------	--------------------------	----------------------

All contents are Copyright © 1992-2005 Cisco Systems, Inc. All rights reserved. [Important Notices](#) and [Privacy Statement](#).

---

Updated: Feb 24, 2005

Document ID: 30020

---