

IGX 8400 BTM and NTM Trunk Error Definitions and Troubleshooting Information

Document ID: 8608

- Introduction**
- Prerequisites**
 - Requirements
 - Components Used
 - Conventions
- Trunk Error Definitions**
- Related Information**

Introduction

This document defines trunk errors reported by the Cisco IGX 8400 Series Switch broadband trunk module (BTM) and the network trunk module (NTM) for Cisco WAN Switching System Software (SWSW) Release 9.2 and later.

Prerequisites

Requirements

There are no specific requirements for this document.

Components Used

The information in this document is based on these software and hardware versions:

- BTM
- NTM
- Cisco WAN SWSW Release 9.2 and later

The information in this document was created from the devices in a specific lab environment. All of the devices used in this document started with a cleared (default) configuration. If your network is live, make sure that you understand the potential impact of any command.

Conventions

For more information on document conventions, refer to the Cisco Technical Tips Conventions.

Trunk Error Definitions

Refer to these documents to access information about the various trunk error definitions and troubleshooting information for SWSW Release 9.2 and later:

- IGX 8400 BTM Trunk Error Troubleshooting and Definitions
- IGX 8400 NTM Trunk Error Definitions
- IGX 8400 UXM Trunk Error Troubleshooting and Definitions

Note: Trunk errors reported by the NTM are similar to those reported by the IPX network trunk card (NTC) for switch software release 9.1 and earlier. The IPX is not supported by SWSW Release 9.2 and later.

Related Information

- [How to Distinguish Between Different IGX NTM Models](#)
 - [Processor, Trunk, and Alarm Card Types](#)
 - [WAN Switching Network Synchronization Fundamentals](#)
 - [International Telecommunication Union, Recommendation G.704](#)
 - [Cisco WAN Switching Solutions – Cisco Documentation](#)
 - [Guide to New Names and Colors for WAN Switching Products](#)
 - [Downloads – WAN Switching Software](#)
 - [Technical Support – Cisco Systems](#)
-

[Contacts & Feedback](#) | [Help](#) | [Site Map](#)

© 2009 – 2010 Cisco Systems, Inc. All rights reserved. [Terms & Conditions](#) | [Privacy Statement](#) | [Cookie Policy](#) | [Trademarks of Cisco Systems, Inc.](#)

Updated: Apr 17, 2009

Document ID: 8608
