

Release Notes for Cisco WBPN Wireless-N Bridge for Phone Adapters Firmware Version 1.0.1

April 11, 2012

Contents

This document includes the following topics:

- Resolved Issues in Release 1.0.1
- Known Issues in Release 1.0.1
- Related Information

Release Notes

Resolved Issues in Release 1.0.1

Ref Number	Description
CSCtt09009	Issue—The WBPN sends DHCP and ARP (I2 and I3) broadcasts on all virtual Access Points (APs). It should send packets only on the SSID with which it is associated.
	Resolution —WBPN is working as designed in the specifications.
CSCtu17101	Issue—The WBPN radio does not adjust to lower data rates when collisions or retransmits occur.
	Resolution —WBPN is working as designed in the specifications.
CSCtx77967	Issue—The default time zone for Network Time Protocol (NTP) should be Pacific. The current default time zone is Taiwan.
	Resolution—Changed default time zone.
CSCtu17107	Issue —The WBPN aggregates real-time packets, such as voice packets.
	Resolution —WBPN is working as designed in the specifications.
various	Corrected terminology and errors in display windows.

Known Issues in Release 1.0.1

There are no known issues in this release.

Related Information

Support		
Cisco Small Business Support Community	www.cisco.com/go/smallbizsupport	
Cisco Small Business Support and Resources	www.cisco.com/go/smallbizhelp	
Phone Support Contacts	www.cisco.com/en/US/support/ tsd_cisco_small_business _support_center_contacts.html	
Cisco Small Business Firmware Downloads	www.cisco.com/go/software Select a link to download firmware for Cisco Small Business Products. No login is required.	
Product Documentation		
Cisco WBPN	www.cisco.com/go/spabridge	
Cisco SPA50X Phones	www.cisco.com/go/spa500phones	
Cisco SPA30X Phones	www.cisco.com/go/300phones	
Cisco Small Business		
Cisco Partner Central for Small Business (Partner Login Required)	www.cisco.com/web/partners/sell/smb	
Cisco Small Business Home	www.cisco.com/smb	

Cisco and the Cisco Logo are trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and other countries. A listing of Cisco's trademarks can be found at www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1005R)

© 2012 Cisco Systems, Inc. All rights reserved.

78-20767-01