



New and Changed Information for the Cisco Nexus 2000 Series

This chapter provides release specific information for each new and changed feature in the *Cisco Nexus 2000 Series Fabric Extender Software Configuration Guide*.

To check for additional information about Cisco NX-OS Release 4.1(3)N1(1), see the *Cisco Nexus 5000 Series and Cisco Nexus 2000 Series Release Notes, 31/July/2009* available at the following Cisco website: <http://www.cisco.com/c/en/us/support/switches/nexus-2000-series-fabric-extenders/products-release-notes-list.html>.

- [New and Changed Features for Release 4.1\(3\)N1\(1\), page 1](#)

New and Changed Features for Release 4.1(3)N1(1)

This table summarizes the new and changed features for the *Cisco Nexus 2000 Series Fabric Extender Software Configuration Guide* for Cisco NX-OS Release 4.1(3)N1(1), and tells you where they are documented.

Feature	Description	Changed in Release	Where Documented
vPC	Added a description of virtual Port Channels (vPC).	4.1(3)N1(1)	Virtual Port Channels
	Added configuration steps to upgrade the Fabric Extender when configured in a vPC.		Upgrading the Fabric Extender in a vPC Topology
Locator beacon LED	The locator beacon LED is enabled or disabled with a new command.	4.1(3)N1(1)	Enabling the Fabric Extender Locator LED

