



New and Changed Information

- [New and Changed Information](#), on page 1

New and Changed Information

New and Changed Information in Cisco UCS Manager, Release 4.0(2a)

This section provides information on new feature and changed behavior in Cisco UCS Manager, Release 4.0(2a).

Table 1: New Features and Changed Behavior in Cisco UCS Manager, Release 4.0(2a)

Feature	Description	Where Documented
NVMe OOB support for new SIOC with PCIe slots	Cisco UCS S3260 systems support NVMe OOB for the new server SIOC, UCS-S3260-PCISIOC, with S3260 M5 servers.	New SIOC with PCIe Slots
Cisco UCS VIC 1495	In Cisco UCS Manager Release 4.0(2a), Cisco UCS VIC 1495 are supported on Cisco UCS 6300 Series Fabric Interconnect with new generation SIOC.	Connectivity Matrix

New and Changed Information in Cisco UCS Manager, Release 4.0(1a)

This section provides information on new feature and changed behavior in Cisco UCS Manager, Release 4.0(1a).

Table 2: New Features and Changed Behavior in Cisco UCS Manager, Release 4.0(1a)

Feature	Description	Where Documented
New SIOC with PCIe Slots	Cisco UCS S3260 systems support a new server SIOC, UCS-S3260-PCISIOC, with S3260 M5 servers.	New SIOC with PCIe Slots

Feature	Description	Where Documented
Cisco UCS 6454 Fabric Interconnect	This release introduces Cisco UCS 6454 Fabric Interconnect that support 10/25 Gigabit ports in the fabric with 40/100 Gigabit uplink ports.	Cisco UCS S3260 System Architectural Overview
Cisco UCS VIC 1455	In Cisco UCS Manager Release 4.0(1a), Cisco UCS VIC 1455 are supported on Cisco UCS 6454 Fabric Interconnect with new generation SIOC.	Connectivity Matrix