

# Release Notes for Cisco ASR 901 Series Aggregation Services Router for Cisco IOS Release 15.5(1)S2

#### First Published Date: May 2015

This release notes is for the Cisco ASR 901 Series Aggregation Services Router for Cisco IOS Release 15.5(1)S2 and contains the following sections:

- Introduction, page 1
- System Specifications and Memory Details, page 2
- New and Changed Information, page 3
- Supported MIBs, page 4
- Caveats, page 4
- Troubleshooting, page 5
- Related Documentation, page 5
- Services and Support, page 6

### Introduction

The Cisco ASR 901 Series Aggregation Services Router is a cell-site access platform specifically designed to aggregate and transport mixed-generation radio access network (RAN) traffic. The router is used at the cell site edge as a part of a 2G, 3G, or 4G RAN.

The Cisco ASR 901 router helps enable a variety of RAN solutions by extending IP connectivity to devices using Global System for Mobile Communications (GSM), General Packet Radio Service (GPRS), Node Bs using High Speed Packet Access (HSPA) or Long Term Evolution (LTE), base transceiver stations (BTSs) using Enhanced Data Rates for GSM Evolution (EDGE), Code Division Multiple Access (CDMA), CDMA-2000, EVDO, or WiMAX, and other cell-site equipment.

It transparently and efficiently transports cell-site voice, data, and signaling traffic over IP using traditional T1 and E1 circuits, as well as alternative backhaul networks such as Carrier Ethernet and DSL, Ethernet in the First Mile (EFM), and WiMAX. It also supports standards-based Internet



Engineering Task Force (IETF) Internet protocols over the RAN transport network, including those standardized at the Third-Generation Partnership Project (3GPP) for IP RAN transport. Custom designed for the cell site, the Cisco ASR 901 router features a small form factor, extended operating temperature, and cell-site DC input voltages.

Table 1 lists the Cisco ASR 901 1G Router model versions.

Table 1 Cisco ASR 901 1G Router Models

Power Source	TDM + Ethernet Version	Ethernet Version
DC Power	• A901-12C-FT-D	• A901-12C-F-D
	• A901-4C-FT-D	• A901-4C-F-D
AC Power	• none	• none

Table 2 lists the Cisco ASR 901 10G Router model versions.

Table 2 Cisco ASR 901 10G Router Models

Power Source	TDM + Ethernet Version	Ethernet Version
DC Power	• A901-6CZ-FT-D	• A901-6CZ-F-D
		• A901-6CZ-FS-D
AC Power	• A901-6CZ-FT-A	• A901-6CZ-F-A
		• A901-6CZ-FS-A



Some of the Cisco ASR 901 models have port based licensing. For more details, see the Licensing chapter in Cisco ASR 901 Series Aggregation Services Router Software Configuration Guide.

## **System Specifications and Memory Details**

Table 3 lists the supported system configurations and memory details for the Cisco ASR 901 router:

Table 3 Cisco IOS Release 15.5(1)S2 Memory Details

Platform	Software Image	Flash Memory	DRAM Memory	Runs From
Cisco ASR 901 Series Aggregation Services Router TDM version	asr901-universalk9-mz	128 MB	512 MB	RAM
Cisco ASR 901 Series Aggregation Services Router, Ethernet version	asr901-universalk9-mz	128 MB	512 MB	RAM
Cisco ASR 901 Series Aggregation Services Router, IPsec enabled Ethernet version	asr901sec-universalk9.m z	256 MB	512 MB	RAM

#### **Determining the Software Version**

To determine the image and version of Cisco IOS software running on your Cisco ASR 901 router, log in to the router and enter the **show version** command in the EXEC mode:

The following example shows output from Cisco ASR 901 router that supports normal IOS software.

```
ASR901_1> show version

Cisco IOS Software, 901 Software (ASR901-UNIVERSALK9-M), Version 15.5(1)S2, RELEASE SOFTWARE (fc1)

Technical Support: http://www.cisco.com/techsupport
Copyright (c) 1986-2015 by Cisco Systems, Inc.
Compiled Tue 26-May-15 07:10 by prod_rel_team
```

The following example shows output from Cisco ASR 901 Series Aggregation Services Router, IPsec enabled Ethernet version.

```
node6> show version

Cisco IOS Software, 901 Software (ASR901SEC-UNIVERSALK9-M), Version 15.5(1)S2, RELEASE SOFTWARE (fc1)

Technical Support: http://www.cisco.com/techsupport
Copyright (c) 1986-2015 by Cisco Systems, Inc.
Compiled Tue 26-May-15 07:00 by prod_rel_team
```

## **New and Changed Information**

- New Hardware Features in Release 15.5(1)S2, page 3
- New Software Features in Release 15.5(1)S2, page 3
- Supported MIBs, page 4

### **New Hardware Features in Release 15.5(1)S2**

There are no new hardware features for Cisco IOS Release 15.5(1)S2.

#### **New Software Features in Release 15.5(1)S2**

There are no new software features for Cisco IOS Release 15.5(1)S2.

#### **Supported MIBs**

To see the list of MIBS supported on this release, go to the following URL and search using the Image Name: http://tools.cisco.com/ITDIT/MIBS/MainServlet

#### **Caveats**

Caveats describe unexpected behavior in Cisco IOS software releases. Severity 1 caveats are the most serious caveats, severity 2 caveats are less serious, and severity 3 caveats are the least serious of these three severity levels. Only select severity 3 caveats are listed.

This section contains the following topics:

- Bug Search Tool
- Open Caveats
- Resolved Caveats

### **Bug Search Tool**

The Caveats section only includes the bug ID and a short description of the bug. For details on the symptoms, conditions, and workaround for a particular bug you must use the Bug Search Tool.

Use the following link to access the tool: https://tools.cisco.com/bugsearch/search

You will be prompted to log into Cisco.com. After successful login, the Bug Search Tool page opens. Use the Help link in the Bug Search Tool to obtain detailed help.

### **Open Caveats**

This section provides information about the open caveats for the Cisco ASR 901 router running Cisco IOS Release 15.5(1)S2.

ldentifier	Description
CSCuu22054	untagged EVC does not pass traffic
CSCuu28678	ASR901: AIS on TDM AC does not trigger L-bit to be set in SAToP CW
CSCuu28735	ASR901: Incoming SAToP packets with L-bit are ignored after CEM flap

#### **Resolved Caveats**

This section provides information about the resolved caveats for the Cisco ASR 901 router running Cisco IOS Release 15.5(1)S2.

ldentifier	Description
CSCus23299	cli 'showmon' in ROMMON prompt is not displaying upgraded rommon version
CSCus53173	Disable Rommon Auto Downgrade
CSCur89149	syslog (POWER FAILURE/UP) not seen during power cycling agora POE boards
CSCur59496	ASR901: Slave acting as Master for another slave and sending packets

## **Troubleshooting**

The following sections describe troubleshooting commands you can use with the router.

#### **Collecting Data for Router Issues**

To collect data for reporting router issues, issue the following command:

• show tech-support—Displays general information about the router if it reports a problem.

#### **Collecting Data for ROMMON Issues**

To collect data for ROMMON issues, issue the following command while in the EXEC mode:

• **show rom-monitor**—Displays currently selected ROM monitor.



If you contact Cisco support for assistance, we recommend that you provide any crashinfo files stored in flash memory. For more information about crashinfo files, see

http://www.cisco.com/en/US/products/hw/routers/ps167/products\_tech\_note09186a00800a6743.shtml.

### **Related Documentation**

Documents related to the Cisco ASR 901 Series Aggregation Services Router include the following:

- Cisco ASR 901 Series Aggregation Services Router Hardware Installation Guide
- Cisco ASR 901 Series Aggregation Services Router Software Configuration Guide
- Regulatory Compliance and Safety Information for Cisco ASR 901 Series Aggregation Services Routers
- Cisco ASR 901 Series Aggregation Services Router Series MIB Specifications Guide

To access the related documentation on Cisco.com, go to:

 Cisco ASR 901 1G Router home page: http://www.cisco.com/en/US/partner/products/ps12077/tsd\_products\_support\_series\_home.html  Cisco ASR 901 10G Router home page: http://www.cisco.com/c/en/us/support/routers/asr-901-10g-series-aggregation-services-routers/tsd-products-support-series-home.html

# **Services and Support**

For information on obtaining documentation, using the Cisco Bug Search Tool (BST), submitting a service request, and gathering additional information, see *What's New in Cisco Product Documentation* at: http://www.cisco.com/c/en/us/td/docs/general/whatsnew/whatsnew.html.

Subscribe to *What's New in Cisco Product Documentation*, which lists all new and revised Cisco technical documentation as an RSS feed and delivers content directly to your desktop using a reader application. The RSS feeds are a free service.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <a href="https://www.cisco.com/go/trademarks">www.cisco.com/go/trademarks</a>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Release Notes for Cisco ASR 901 Aggregation Series Router for Cisco IOS Release 15.5(1)S2

© 2015, Cisco Systems, Inc All rights reserved.