



New and Changed Information

This *Cisco MDS 9100 Series Hardware Installation Guide* applies to all the Cisco MDS SAN-OS releases.

[Table 1](#) lists the new and changed features available with each Cisco MDS SAN-OS release for the Cisco MDS 9100 Series.

Table 1 Documented Features for the Cisco MDS 9100 Series

| Feature | Description | Changed in Release | Where Documented |
|--|---|----------------------|--|
| Cisco MDS Fibre Channel Bladeswitch overview | Description of the Cisco MDS Fibre Channel Bladeswitch for IBM BladeCenter. | 3.3(1a) | Product Overview chapter. |
| Cisco MDS 9134 Switch overview | Description of NPIV support. | 3.2(2c) | Product Overview chapter. |
| Cisco MDS 9124 Switch overview | Description of NPIV support. | 3.2(2c) | Product Overview chapter. |
| Cisco MDS 9134 Switch overview | Description and illustrations of the 32-port 4-Gbps and 2-port 10-Gbps Cisco MDS 9134 Switch. | 3.2(1) | Product Overview chapter. |
| Cisco MDS 9134 Switch installation | Description and illustrations of installing the Cisco MDS 9134 Switch and removing it. | 3.2(1) | Installing the Cisco MDS 9100 Series chapter. |
| Cisco MDS 9134 Switch specifications | Switch specifications for the Cisco MDS 9134 Switch, including power supply requirements, heat dissipation specifications, and X2 Transceiver Specifications. | 3.2(1) | Technical Specifications appendix. |
| Cisco MDS 9124 Switch | Additional illustrations of the 24-port Cisco MDS 9124 Switch. | Not release specific | Installing the Cisco MDS 9100 Series chapter. |
| Troubleshooting | Troubleshooting chapter removed. | Not release specific | For troubleshooting information, see the Cisco MDS 9000 Family Troubleshooting Guide . |

Table 1 Documented Features for the Cisco MDS 9100 Series (continued)

| Feature | Description | Changed in Release | Where Documented |
|----------------------------------|---|---------------------------|--|
| Cisco MDS 9124 Switch | The 24-port Cisco MDS 9124 Switch. | 3.1(1) | This guide. |
| Rear-facing chassis installation | Chassis installation for a cabinet with insufficient front side clearance. | Not release specific | Installing the Switch in a Cabinet with Insufficient Front Clearance, page 2-11. |
| Jumper power cord | Jumper power cord available for use in cabinet. | Not release specific | Jumper Power Cord, page C-5. |
| Telco and EIA Shelf Bracket Kit | A 2-RU shelf bracket kit that allows single-user installation and installation in a Telco rack. | Not release specific | Cisco MDS 9000 Family Telco and EIA Shelf Bracket, page A-3. |
| Console port to modem connection | Support for connecting the console port on the Cisco MDS 9100 Series to a modem. | 1.2(2a) | Connecting the Console Port, page 3-1. |
| Cisco MDS 9100 Series | The 20-port Cisco MDS 9120 Switch and the 40-port Cisco MDS 9140 Switch. | 1.2(1a) | This guide. |