



New and Changed Information

Table 1 summarizes the new and changed features supported by messages described in this version of the *Cisco MDS 9000 Family System Messages Reference*. For more information about a specific feature, refer to the *Cisco MDS 9000 Family CLI Configuration Guide* and *Cisco MDS 9000 Family Fabric Manager Configuration Guide*.

Table 1 *New and Changed Features and Related System Messages*

Feature	Description	Changed in Release	Where Documented
SYSTEMHEALTH	Added messages for SYSTEMHEALTH feature.	3.3(1a)	“SYSTEMHEALTH Messages” section on page 2-397
SME_CPP	Added messages for SME_CPP.	3.2(2c)	“SME_CPP Messages” section on page 2-307
CFS,DPVM, DMM-SLOT#,IPS, ISAPI, NPV, RADIUS	Added messages for CFS, IP services, ISAPI, NPV, RADIUS, DPVM, DMM-SLOT# feature.	3.2(1)	“CFS Messages” section on page 2-25 “IPS Messages” section on page 2-135 “ISAPI Messages” section on page 2-160 “NPV Messages” section on page 2-206 “RADIUS Messages” section on page 2-280 “DPVM Messages” section on page 2-45 “DMM-SLOT# Messages” section on page 2-43

Send documentation comments to mdsfeedback-doc@cisco.com

Table 1 *New and Changed Features and Related System Messages*

Feature	Description	Changed in Release	Where Documented
CFS, IPS, IVR, LICMGR	Added messages for CFS, IP services, IVR, and the license Manager	3.0(3)	“CFS Messages” section on page 2-25, “IPS Messages” section on page 2-135,, “IVR Messages” section on page 2-167, and “LICMGR Messages” section on page 2-191
ACLTCAM-2 BIOS_DAEMON 2 BOOTVAR-3 CALLHOME-3 CERT ENROLL	Added or modified messages for ACLs, BIOS, boot variables, Call Home, and digital certificates.	3.0(2) 3.0(1)	“ACLTCAM Messages” section on page 2-10, “BIOS_DAEMON Messages” section on page 2-14, “BOOTVAR Messages” section on page 2-15, “CALLHOME Messages” section on page 2-19, and “CERT ENROLL Messages” section on page 2-24
IPS, IVR, PORT, and RSCN	Added or modified messages for IPS,IVR,PORT, and RSCN.	2.1(2)	“IPS Messages” section on page 2-135, “IVR Messages” section on page 2-167, “PORT Messages” section on page 2-233, and “RSCN Messages” section on page 2-290
ILC_HELPER	Supports intelligent linecard helper messages.	2.1(1a)	ILC_HELPER Messages, page 125
NASB	Supports NASB messages..	2.1(1a)	“NASB Messages” section on page 2-204
New messages	Incremental messages added to IPSEC and DPVM.	2.0(2b)	“System Messages and Recovery Procedures for the Cisco MDS 9000 Family” section on page 2-1
BIOS_DAEMON	Supports BIOS_DAEMON messages.	2.0(1b)	“BIOS_DAEMON Messages” section on page 2-14
Cisco Fabric Services (CFS)	Supports CFS messages.	2.0(1b)	“CFS Messages” section on page 2-25

Send documentation comments to mdsfeedback-doc@cisco.com

Table 1 ***New and Changed Features and Related System Messages***

Feature	Description	Changed in Release	Where Documented
DEVICE-ALIAS	Supports DEVICE-ALIAS messages.	2.0(1b)	“DEVICE-ALIAS Messages” section on page 2-37
Dynamic Port VSAN Membership (DPVM)	Supports DPVM messages.	2.0(1b)	“DPVM Messages” section on page 2-45
DSTATS	Supports DSTATS messages.	2.0(1b)	“DSTATS Messages” section on page 2-48
Internet Key Exchange (IKE)	Supports IKE messages.	2.0(1b)	“IKE Messages” section on page 2-122,
IP security (IPSEC)	Supports IPSEC messages.	2.0(1b)	“IPsec Messages” section on page 2-157
Resource management (RM)	Supports RM messages.	2.0(1b)	“RM Messages” section on page 2-289
SFC	Supports SFC messages.	2.0(1b)	“SFC Messages” section on page 2-306
SCSI targets	Supports SCSI-TARGET messages.	2.0(1b)	“SCSI target Messages” section on page 2-296
VFC	Supports VFC messages.	2.0(1b)	“SFC Messages” section on page 2-306

Send documentation comments to mdsfeedback-doc@cisco.com