

Cisco MDS 9250i Multiservice Fabric Switch Overview

This chapter describes the Cisco MDS 9250i Multiservice Fabric Switch and includes these topics:

- Introduction, page 1-1
- Chassis Description, page 1-2
- Cisco MDS 9250i Integrated Supervisor Module, page 1-3
- Fan Modules, page 1-5
- Power Supplies, page 1-6
- Supported Transceivers, page 1-7

Introduction

The Cisco MDS 9250i Multiservice Fabric Switch (DS-C9250I-K9) is an optimized platform for deploying high-performance SAN extension solutions, distributed intelligent fabric services, and cost-effective multiprotocol connectivity for both open systems and mainframe environments.

The Cisco MDS 9250i switch is an ideal solution for local office and remote branch-office SANs and also in large-scale SANs operating the Cisco MDS 9700 and 9500 Series Multilayer director platforms.

The Cisco MDS 9250i switch offers 40 autosensing 2-, 4-, 8-, and 16-Gbps line-rate Fibre Channel ports, eight 10-Gigabit Ethernet Fibre Channel over Ethernet (FCoE) ports, and two 10-Gigabit Ethernet IP storage services ports in a fixed two-rack-unit (2RU) form factor.

The Cisco MDS 9250i switch can be deployed in the existing native Fibre Channel networks, which ensures protection of your investments in storage networks. Two 1- and 10-gigabit ports support Small Computer System Interface over IP (iSCSI) storage services. By using the eight 10 Gigabit Ethernet FCoE ports, the Cisco MDS 9250i switch can be attached to the directly connected FCoE and Fibre Channel storage devices. The Cisco MDS 9250i switch supports multi-tiered unified network fabric connectivity directly over FCoE. The Cisco MDS 9250i switch has front-to-back airflow and comes with a set of storage services for Fibre Channel and FCoE SANs with FCIP, IO accelerator (IOA), and data mobility migration (DMM).

The Cisco SAN Extension over IP application package license is enabled as standard on the two fixed 1/10 Gigabit Ethernet IP storage services ports, enabling features such as Fibre Channel over IP (FCIP) and compression on the switch without additional licenses.

The Cisco MDS 9250i switch is shipped with the following:

- Hot-swappable, 2+1 redundant power supplies
- Hot-swappable, 1+1 redundant fan tray with integrated temperature and power management
- Hot-swappable SFP+ optics

Figure 1-1 Cisco MDS 9250i Switch Front View





Figure 1-2 Cisco MDS 9250i Switch Rear View



Chassis Description

The Cisco MDS 9250i switch has a nonremovable supervisor module with 40 integrated 16-Gbps FC ports and eight 10-Gigabit Ethernet Fibre Channel over Ethernet (FCoE) ports.

The Cisco MDS 9250i switch also has these additional modules:

• 2-port 1- and 10-gigabit Ethernet IP storage services module

- USB port on the front panel for code uploads, configuration file backups, log dumps, and report capture
- A nonremovable interface module (located on the left side of the integrated supervisor module), which provides one RS-232 console port and one MGMT 10/100 Ethernet port for the integrated supervisor module
- Three power supplies that are redundant by default
- Two hot-swappable fans that are redundant by default

Cisco MDS 9250i Integrated Supervisor Module

The nonremovable Cisco MDS 9250i integrated supervisor module provides the control and management functions of the Cisco MDS 9250i Multiservice Fabric switch, and it includes 40 integrated 16-Gbps Fibre Channel switching ports and eight 10-Gigabit Ethernet Fibre Channel over Ethernet (FCoE) port modules.


The Cisco MDS 9250i integrated supervisor module has a PowerPC 8572E processor. It also has an internal CompactFlash card that provides 4 GB of storage for software images. The NVRAM consists of a battery, a battery controller and 512 Kx16 SRAM. SRAM used to store event logs, core dumps that are required to be stored after a power cycles.

Front Panel LEDs

The front panel of the Cisco MDS 9250i switch has the following LEDs:

- Status LED
- P/S LED
- FAN LED

Figure 1-3 Cisco MDS 9250i Ports and LEDs



1	CONSOLE Debug Port	6	USB Port
2	10G iSCSI/FC Ports	7	STATUS LED

3	FCoE Ports	8	P/S LED
4	Fibre Channel Ports	9	FAN LED
5	MGMT ETH Port	10	CONSOLE Port

The LEDs on the supervisor module indicate the status of the supervisor module, power supplies, and the system as a whole. Table 1-1 describes the LEDs.


Table 1-1 Cisco MDS 9250i Switch Front Panel LEDs

LED	Status	Description			
STATUS	Green	All diagnostics pass. The module is operational (normal initialization sequence).			
	Orange	The module is booting or running diagnostics (normal initialization sequence)			
		An over-temperature condition has occurred. (A minor temperature threshold has been exceeded during environmental monitoring.)			
	Red	One of the following occurred:			
	blinking	• The diagnostic test failed.			
		 The module is not operational because a fault occurred during the initialization sequence. 			
		An over-temperature condition has occurred. (A major temperature threshold has been exceeded during environmental monitoring.)			
	Red	The power is on, but it did not boot up the Diag or iSAN image.			
P/S	Green	Power supply is OK.			
	Red	Power supply failed.			
	Off	The module is not receiving power.			
FAN	Green	Power supply is OK.			
	Red	Power supply failed.			
	Off	The FAN module is not receiving power.			
LINK	Red	The Ethernet port is connected to a device.			
	Off	The Ethernet port is not connected to a device.			
ACT	Orange blinking	Data is being transmitted through this interface.			
	Off	Not data is being transmitted.			
1-48	Green	The link is up.			
	Green blinking	The link is up and traffic is passing through the port.			
	Off	The port has been shut down.			

Fan Modules

The Cisco MDS 9250i switch has two fan trays that are installed vertically at the back of the chassis. Each fan module can be removed while the other fan module continues to move air through the chassis.





One fan can fail without affecting the thermal performance of the system. Redundant fan controllers and other internal mechanisms are in place to ensure that any single fan tray does not go down.

If any single fan fails, the system continues to operate under all conditions. Two fan failures might cause alarms from ASIC when the temperature exceeds the threshold. At $104^{\circ}F$ ($40^{\circ}C$) or less, a single fan tray can be removed and the system can continue to operate long enough to allow for replacement of a failed fabric module or fan tray.

Power Supplies


The Cisco MDS 9250i Multiservice Fabric switch supports the following types of power supplies:

- 300-W AC power supply (AC input and DC output)
- 300-W DC power supply (DC input and DC output)

The Cisco MDS 9250i Multiservice Fabric switch supports up to three hot-swappable 300-W AC power supplies (AC input) (DS-C50I-300AC).

When connected to 220 VAC, the 300-W AC power supplies (DS-C50I-300AC) for the Cisco MDS 9250i switch provide an output power of 300 W to power the modules and fans. When connected to a 110 VAC power system, the power supply provides approximately 300 W. In this case, and if the power supplies are used in redundant rather than combined mode, they might not provide adequate power, depending on the number of modules loaded in the chassis.

Figure 1-5 Cisco MDS 9250i Switch 300-W AC Power Supply



Each power supply module monitors its output voltage and provides the status to the supervisor. The power supply modules also provide information about local fans, power, shutdown control, and E2PROM to the supervisor.

Supported Transceivers

The Cisco MDS 9250i switch supports these transceivers: 1000BASE-T, RJ-45, 8-Gbps SW/LW, LC Enhanced Small Form-Factor Pluggable (SFP+), 10-Gbps SW/LW, LC SFP+, 10-GbE SR/LR/ER, LC, SFP+, and 16-Gbps SW/LW LC SFP+.

Fibre Channel SFP+ Transceivers

The Fibre Channel SFP+ transceivers are field-replaceable and hot-swappable. You can use any combination of SFP+ transceivers that are supported by the switch. The only restrictions are that SWL transceivers must be paired with SWL transceivers, and LWL transceivers must be paired with LWL transceivers, and the cable must not exceed the stipulated cable length for reliable communications.

For more information about a specific Cisco SFP+ transceiver, see the "SFP+ Transceiver Specifications" section on page B-3. SFP+ transceivers can be ordered separately or with the Cisco MDS 9250i switch.



Use only Cisco transceivers in the Cisco MDS 9250i switch. Each Cisco transceiver is encoded with model information that enables the switch to verify that the transceiver meets the requirements for the switch.

Supported Transceivers