

Release Notes for Cisco SLM2008 8-Port Gigabit Smart Switch with PD and AC Power Firmware Version 2.0.0.10

December 2009

These release notes describe changes in the SLM2008 firmware version 2.0.0.10.

Contents

This document includes the following topics:

- [Changes Since Cisco SLM2008 8-Port Gigabit Smart Switch with PD and AC Power Firmware Version 1.0.1](#)
- [Related Information](#)

Changes Since Cisco SLM2008 8-Port Gigabit Smart Switch with PD and AC Power Firmware Version 1.0.1

Device web user interface was updated and problems were fixed.

GUI

The switch's web-based configuration utility now reflects the Cisco Small Business style.

Other Updates

The following problems were fixed in firmware version 2.0.0.10:

- Web browser availability. Firmware upgrade notice for Mozilla Firefox users only.

When upgrading firmware using the Firefox browser, user has to click the Proceed button twice to see the progress bar.

- If the administrator closes the web browser directly and does not click Log Out, the switch cannot be managed by a different management IP address until the web admin session times out.

The default timeout period is 300 seconds or when the administrator accesses the utility and clicks Log Out. Until the web session times out, the administrator can directly access the switch (without going through the login process) when opening a new web session using the same management IP address and log out has not occurred from the previous session.

This issue is resolved for the Microsoft Internet Explorer browser and does not include a resolution for Mozilla Firefox.

- STP Bridge ID value not correct.

Firmware version 1.0.1 adds a VLAN ID value to the Bridge ID and does not follow the STP standards.

Resolution: Removed VLAN ID from Bridge ID in this firmware version.

Related Information

Support	
Cisco Small Business Support Community	www.cisco.com/go/smallbizsupport
Online Technical Support and Documentation (Login Required)	www.cisco.com/support
Phone Support Contacts	www.cisco.com/en/US/support/tsd_cisco_small_business_support_center_contacts.html
Software Downloads (Login Required)	Go to: http://www.cisco.com/public/sw-center/index.shtml and enter the model number in the Software Search box.
Product Documentation	
Cisco Small Business SLM2008 8-Port Gigabit Smart Switch with PD and AC Power	www.cisco.com/en/US/products/ps9994/tsd_products_support_series_home.html
Cisco Small Business	
Cisco Partner Central for Small Business (Partner Login Required)	www.cisco.com/web/partners/sell/smb
Cisco Small Business Home	www.cisco.com/smb
Marketplace	www.cisco.com/go/marketplace

Release Notes

CCDE, CCENT, CCSI, Cisco Eos, Cisco HealthPresence, Cisco Ironport, the Cisco logo, Cisco Lumin, Cisco Nexus, Cisco Nurse Connect, Cisco Stackpower, Cisco StadiumVision, Cisco TelePresence, Cisco Unified Computing System, Cisco WebEx, DCE, Flip Channels, Flip for Good, Flip Mino, Flip Video, Flip Video (Design), Flipshare (Design), Flip Ultra, and Welcome to the Human Network are trademarks; Changing the Way We Work, Live, Play, and Learn, Cisco Store, and Flip Gift Card are service marks; and Access Registrar, Aironet, AsyncOS, Bringing the Meeting To You, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, CCVP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Collaboration Without Limitation, EtherFast, EtherSwitch, Event Center, Fast Step, Follow Me Browsing, FormShare, GigaDrive, HomeLink, Internet Quotient, IOS, iPhone, iQuick Study, IronPort, the IronPort logo, LightStream, Linksys, MediaTone, MeetingPlace, MeetingPlace Chime Sound, MGX, Networkers, Networking Academy, Network Registrar, PCNow, PIX, PowerPanels, ProConnect, ScriptShare, SenderBase, SMARTnet, Spectrum Expert, StackWise, The Fastest Way to Increase Your Internet Quotient, TransPath, WebEx, and the WebEx logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0907R)

© 2009 Cisco Systems, Inc. All rights reserved.

OL-20273-01