

Release Notes for Cisco TrustSec 3.0 General Deployability 2013 Release

Published: March 1, 2013

The most current version of this document is available at the following URL:

http://www.cisco.com/en/US/docs/switches/lan/trustsec/release/notes/rn_cts_crossplat.html

Contents

This document contains the following sections:

- [New Features, Supported Hardware and Software](#)
- [Cisco TrustSec How-To Documents](#)
- [Caveats - TrustSec 3.0 General Availability 2013 Release](#)
- [Related Documentation](#)

New Features, Supported Hardware and Software

For a complete table of features, platforms, and IOS images supported in the TrustSec 3.0 release, see the *Cisco TrustSec 3.0 Product Bulletin* at the following URL:

<http://www.cisco.com/en/US/netsol/ns1051/index.html>

See also, the Matrix of Cisco TrustSec-Enabled Infrastructure at the following URL:

http://www.cisco.com/en/US/solutions/ns170/ns896/ns1051/trustsec_matrix.html

Cisco TrustSec How-To Documents

TrustSec “How-to” Configuration Guides are classified in the following sections:

- Section 1: Introduction, BootStrapping and Universal Configurations
- Section 2: Deployment Modes
- Section 3: Profiling, Using Cisco ISE and BYOD
- Section 4: Security Group Tagging (SGA) and More

Find all Cisco TrustSec “How-To” documents at the following URL:

http://www.cisco.com/en/US/solutions/ns340/ns414/ns742/ns744/landing_DesignZone_TrustSec.html

Caveats - TrustSec 3.0 General Availability 2013 Release

Open Caveats

Cisco Catalyst 3750-X Series Switches

Release notes for Catalyst 3750-X Series switches:

http://www.cisco.com/en/US/products/ps10745/prod_release_notes_list.html

Identifier	Technology	Software Release	Description
CSCud33133	CTS	15.0(2)SE	RBACL list is requested even if SG gen-id didn't change.
CSCud38033	CTS	15.0(2)SE	No peer policy requested when link is CTS Manual.

Cisco Catalyst 4500 Series Switches

Release notes for Catalyst 4500 Series switches:

http://www.cisco.com/en/US/products/hw/switches/ps4324/prod_release_notes_list.html

Identifier	Technology	Software Release	Description
CSCud97768	CTS	IOS XE 3.3.0SG	CTS link is not established when cts manual is set a with policy dynamic identity.

Cisco Catalyst 6500 Series Switches

Release notes for Catalyst 6500 Series switches:

http://www.cisco.com/en/US/products/hw/switches/ps708/prod_release_notes_list.html

Identifier	Technology	Software Release	Description
CSCud33412	CTS	15.1(1)SY	RBACL gen-id is not shown correctly in the show cts rbacl command.
CSCud66895	CTS	15.1(1)SY	Authorization success counter in CTS interfaces doesn't increase as expected.
CSCud95127	EAP	15.1(1)SY	Catalyst 6K crashes when cts change-password procedure is interrupted.

Cisco Nexus 1000V Series Switches

Release notes for Nexus 1000V Series switches:

http://www.cisco.com/en/US/products/ps9902/prod_release_notes_list.html

Identifier	Technology	Software Release	Description
CSCud06240	SVS	4.2(1)SV2(1.1)	Could not establish SXP connection after reset- FCS-security
CSCuc94663	SVS	4.2(1)SV2(1.1)	HA installation creates confusion.
CSCuc94677	SVS	4.2(1)SV2(1.1)	Cannot perform a switchover if using simple password and duplicated domain.

Cisco Nexus 7000 Series Switches

Release notes for Nexus 7000 Series switches:

http://www.cisco.com/en/US/products/ps9402/prod_release_notes_list.html

Identifier	Technology	Software Release	Description
CSCud28769	CTS	6.1	IP to SGT mapping learned through SXP should be preferred to CLI configuration.

Related Documentation

Document Title	TrustSec Topics
Cisco TrustSec Switch Configuration Guide	<ul style="list-style-type: none"> TrustSec feature configurations for Cisco Catalyst series switches System error messages
Cisco Secure Access Control System	
Cisco Secure Access Control System Release Notes	Open and resolved caveats, referred to as Known and Resolved issues in Cisco ACS documentation

Document Title	TrustSec Topics
Cisco Secure Access Control System End-User Guides	Cisco Security Group Access configurations for Cisco ACS 5.1 and more recent releases
Cisco Identity Services Engine	
Release Notes for Cisco Identity Services Engine	Open and resolved caveats
Cisco Identity Services Engine User Guide	Configuring Cisco Security Group Access policies
Catalyst 3000 Series Switches	
Release Notes for Catalyst 3560 and 3750 Switches	Open and resolved caveats
Catalyst 3560 Software Configuration Guides	802.1x configuration procedures
Catalyst 3750 Switch Software Configuration Guides	
Catalyst 3750-X Switch Software Configuration Guides	<ul style="list-style-type: none"> • 802.1x configuration procedures • SXP • MACsec
Catalyst 4500 Series Switches	
Release Note for the Catalyst 4500 Series Switch	Open and resolved caveats
Catalyst 4500 Series Switch Software Configuration Guides	802.1x configuration procedures
Catalyst 6500 Series Switches	
Catalyst 6500 Series Release Notes	Open and resolved caveats
Catalyst 6500 Series Software Configuration Guides	802.1x and TrustSec configuration procedures
Nexus 1000V Series Switches	
Cisco Nexus 1000V Series Switches Release Notes	Open and resolved caveats
Cisco Nexus 1000V Security Configuration Guide	TrustSec configurations.
Nexus 7000 Series Switches	
Cisco Nexus 7000 Series Switches Release Notes	Open and resolved caveats
Cisco Nexus 7000 Series Switches Configuration Guides	<ul style="list-style-type: none"> • TrustSec feature configurations for Cisco Nexus 7000 Series switches, Release 4.1 and more recent releases • 802.1x configuration procedures

Cisco IOS Software Documentation

Cisco IOS Document Title	TrustSec Topics
Cisco TrustSec Configuration Guide Cisco IOS XE Release 3S	Router-based SXP configuration
Cisco IOS Master Command List, All Releases	802.1x; SXP

