



# Release Notes for Cisco Unified Videoconferencing 3500 MCU Release 5.0.1

---

**Revised: October 3, 2006, OL-11468-01**

These release notes describe the new features and caveats for all versions of Cisco Unified Videoconferencing 3515 MCU, Cisco Unified Videoconferencing 3545 MCU and Cisco Unified Videoconferencing 3545 EMP release 5.0.1.

You can access the latest software upgrades and release notes for all versions of Cisco Unified Videoconferencing 3500 MCU on Cisco Connection Online (CCO) at the following URL:

<http://cisco.com/kobayashi/sw-center/sw-video.shtml>

## Contents

These release notes discuss the following topics:

- [Introduction, page 2](#)
- [System Requirements, page 2](#)
- [Related Documentation, page 2](#)
- [New and Changed Information, page 2](#)
- [Resolved Caveats for Cisco Unified Videoconferencing 3500 MCU Release 5.0.1, page 3](#)
- [Open Caveats for Cisco Unified Videoconferencing 3500 MCU Release 5.0.1, page 6](#)
- [Troubleshooting, page 8](#)
- [Obtaining Documentation, page 8](#)
- [Documentation Feedback, page 9](#)
- [Cisco Product Security Overview, page 9](#)
- [Product Alerts and Field Notices, page 11](#)
- [Obtaining Technical Assistance, page 11](#)
- [Obtaining Additional Publications and Information, page 13](#)



---

**Corporate Headquarters:**  
**Cisco Systems, Inc., 170 West Tasman Drive, San Jose, CA 95134-1706 USA**

© 2006 Cisco Systems, Inc. All rights reserved.

# Introduction

The Cisco Unified Videoconferencing 3500 MCU is a high performance multipoint video conferencing and media processing system that provides extensive audio and video processing capabilities and web-based conference monitoring and management. The Cisco Unified Videoconferencing 3500 MCU supports a wide range of telephony protocols and media communication networks and is fully interoperable with other video conferencing network devices.

## System Requirements

Cisco Unified Videoconferencing 3500 MCU Release 5.0.1 only operates with the following products:

- Cisco Unified Videoconferencing 3515 MCU12
- Cisco Unified Videoconferencing 3515 MCU24
- Cisco Unified Videoconferencing 3545 MCU
- Cisco Unified Videoconferencing 3545 EMP

You cannot install version 5.0.1 on older IP/VC products, including the Cisco IP/VC 3511 and 3540 MCU.

## Compatibility Matrix and Supported Upgrades

### Upgrading from a previous build of MCU version 5.x

#### Procedure

---

- Step 1** Use the MCU Upgrade Utility to burn the latest version onto the MCU card.  
After burning, the Upgrade Utility will reset the platform.
- Step 2** After reset, the latest version is installed on the MCU.
- 

## Related Documentation

- *Administrator Guide for Cisco Unified Videoconferencing 3515 MCU12 and MCU24 Release 5.0*
- *Administrator Guide for Cisco Unified Videoconferencing 3545 MCU Release 5.0.*

## New and Changed Information

The following section describes new features and changes that are pertinent to this release of Cisco Unified Videoconferencing 3500 MCU.

- A single Cisco Unified Videoconferencing 3500 MCU can now support up to 96 simultaneous SCCP calls. To enable full SCCP capacity, allocate all MCU ports to SCCP by selecting “all” in the “Ports allocated to SCCP” drop-down list in the Protocols > SCCP window. Selecting “all” allocates the ports of all EMP units currently registered to the MCU to SCCP calls.

When selecting “all” in the “Ports allocated to SCCP” drop-down list, ensure that you disable the H.323 and SIP protocols to prevent the creation of H.323 and SIP calls.



**Note** An EMP unit that has registered to the MCU since the last MCU reset will not be allocated to SCCP calls until the MCU is reset again.

- MCU video services can be configured to display a welcome screen to participants as they join a conference. The welcome text, text color, background color and display duration are all configurable from the Advanced Video Settings screen.

## Resolved Caveats for Cisco Unified Videoconferencing 3500 MCU Release 5.0.1

You can find the latest resolved caveat information for Cisco Unified Videoconferencing 3500 MCU Release 5.0.1 by using Bug Toolkit, which is an online tool that is available for customers to query defects according to their own needs.



**Tip**

You need an account with Cisco.com (Cisco Connection Online) to use the Bug Toolkit to find open and resolved caveats of any severity for any release.

To access the Bug Toolkit, log on to [http://www.cisco.com/cgi-bin/Support/Bugtool/launch\\_bugtool.pl](http://www.cisco.com/cgi-bin/Support/Bugtool/launch_bugtool.pl).

This section includes the following topics:

- [Using Bug Toolkit, page 3](#)
- [Saving Bug Toolkit Queries, page 5](#)

## Using Bug Toolkit

To access Bug Toolkit, you need the following items:

- Internet connection
- Web browser
- Cisco.com user ID and password

To use Bug Toolkit, follow this procedure.



**Note**

Cisco CallManager is used in this procedure as an example. You will want to replace Cisco CallManager with the name of the product for which you are searching for bug information.

## Procedure

- Step 1** To access the Bug Toolkit, go to [http://www.cisco.com/cgi-bin/Support/Bugtool/launch\\_bugtool.pl](http://www.cisco.com/cgi-bin/Support/Bugtool/launch_bugtool.pl). Log on with your Cisco.com user ID and password.
- Step 2** Click the **Launch Bug Toolkit** hyperlink.
- Step 3** If you are looking for information about a specific caveat, enter the ID number in the “Enter known bug ID:” field.
- To view all caveats for Cisco CallManager, go to the “Search for bugs in other Cisco software and hardware products” section, and enter **Cisco CallManager** in the Product Name field. Alternatively, you can scroll through the product name list and click **Cisco CallManager**.
- Step 4** Click **Next**. The Cisco CallManager search window displays.
- Step 5** Choose the filters to query for caveats. You can choose any or all of the available options:

**a.** Choose the Cisco CallManager version:

- Choose the major version for the major releases (such as, 4.1, 4.0, 3.3).  
A major release contains significant new features, enhancements, architectural changes, and/or defect fixes.
- Choose the revision for more specific information; for example, choosing major version 4.1 and revision version 3 queries for release 4.1(3) caveats.  
A revision (maintenance) release primarily contains defect fixes to address specific problems, but it may also include new features and/or enhancements.

**b.** Choose the Features or Components to query; make your selection from the “Available” list and click Add to place your selection in the “Limit search to” list.

- To query for all Cisco CallManager caveats for a specified release, choose “All Features” in the left window pane.



**Note** The default value specifies “All Features” and includes all of the items in the left window pane.

- To query only for Cisco CallManager-related caveats, choose “ciscocm” and then click **Add**.
- To query only for phone caveats, choose “ciscocm-phone” and then click **Add**.
- To query only for gateway caveats, choose “voice-gateway” and then click **Add**.

**c.** Enter keywords to search for a caveat title and description, if desired.



**Note** To make queries less specific, use the All wildcard for the major version/revision, features/components, and keyword options.

**d.** Choose the Set Advanced Options, including the following items:

- Bug Severity level—The default specifies 1-3.
- Bug Status Group—Check the **Fixed** check box for resolved caveats.
- Release Note Enclosure—The default specifies Valid Release Note Enclosure.

**e.** Click **Next**.

Bug Toolkit returns the list of caveats on the basis of your query.

- You can modify your results by submitting another query and using different criteria.
- You can save your query for future use. See the [“Saving Bug Toolkit Queries” section on page 5](#).

**Note**

For detailed online help with Bug Toolkit, click **Help** on any Bug Toolkit window.

## Saving Bug Toolkit Queries

Bug Toolkit allows you to create and then save your queries to monitor a specific defect or network situation. You can edit a saved search at any time to change the alert conditions, the defects being watched, or the network profile.

Follow this procedure to save your Bug Toolkit queries.

### Procedure

- 
- Step 1** Perform your search for caveats, as described in the [“Using Bug Toolkit” section on page 3](#).
- Step 2** In the search result window, click the **This Search Criteria** button that displays at the bottom of the window.
- A new window displays.
- Step 3** In the Name of saved search field, enter a name for the saved search.
- Step 4** Under My Bug Groups, use one of the following options to save your defects in a bug group:
- Click the **Existing group** radio button and choose an existing group name from the drop-down list box.
  - Click the **Create new group named:** radio button and enter a group name to create a new group for this saved search.

**Note**

This bug group will contain the bugs that are identified by using the search criteria that you have saved. Each time that a new bug meets the search criteria, the system adds it to the group that you chose.

Bug Toolkit saves your bugs and searches, and makes them available through the My Stuff window. (The My Stuff window allows you to view, create, and/or modify existing bug groups or saved searches. Choose the My Stuff link to see a list of all your bug groups.)

- Step 5** Under Email Update Options, you can choose to set optional e-mail notification preferences if you want to receive automatic updates of a bug status change. Bug Toolkit provides the following options:
- **Do NOT send me any email updates**—If you choose this default setting, Bug Toolkit does not send e-mail notifications.
  - **Send my updates to:**—Click the radio button to choose this option to send e-mail notifications to the user ID that you enter in this field. Additional notification options include
    - **Updates as they occur**—Bug Toolkit provides updates that are based on status change.
    - **Weekly summaries**—Bug Toolkit provides weekly summary updates.

- **Apply these email update options to all of my saved searches**—Check this check box to use these e-mail update options for all of your saved searches.

**Step 6** To save your changes, click **Save**.

**Step 7** A window displays the bug group(s) that you have saved. From this window, you can click a bug group name to see the bugs and the saved searches; you can also edit the search criteria.

## Open Caveats for Cisco Unified Videoconferencing 3500 MCU Release 5.0.1

This section describes possible unexpected behaviors by Cisco Unified Videoconferencing 3500 MCU Release 5.0.1, sorted by component. Unless otherwise noted, these caveats apply to all Cisco Unified Videoconferencing 3500 MCU 5.0 releases up to and including Cisco Unified Videoconferencing 3500 MCU 5.0.1.

You can find the latest resolved caveat information for Cisco Unified Videoconferencing 3500 MCU Release 5.0.1 by using Bug Toolkit, which is an online tool that is available for customers to query defects according to their own needs.



**Tip**

You need an account with Cisco.com (Cisco Connection Online) to use the Bug Toolkit to find open and resolved caveats of any severity for any release.

To access the Bug Toolkit, log on to [http://www.cisco.com/cgi-bin/Support/Bugtool/launch\\_bugtool.pl](http://www.cisco.com/cgi-bin/Support/Bugtool/launch_bugtool.pl).

MCU known issues are included in the following categories:

- [Endpoint Information Display in MCU Conference Control, page 6](#)
- [H.243, page 7](#)
- [Encryption, page 7](#)
- [Configuration, page 7](#)
- [Video Quality, page 7](#)
- [Audio Quality, page 7](#)
- [H.239, page 7](#)
- [Cascading, page 8](#)
- [SCCP, page 8](#)
- [T.120, page 8](#)

### Endpoint Information Display in MCU Conference Control

- The information icon for participants in child conferences does not function. Clicking on it does not perform any action.
- SIF resolutions may appear as CIF resolutions on the statistics page.

**H.243**

- If the H.323 registration mode is set to gateway when enabling H.243, then in cascaded conferences endpoints appear twice in the conference control. To resolve this, either disable H.243 or change H.323 registration mode to MCU.




---

**Note** Changing the H.323 registration mode to MCU may cause interoperability issues with the Cisco IOS H.323 Gatekeeper.

---

- The H.243 conference control may not function with some ISDN endpoints that are connected through a gateway.
- When H.243 is enabled, Far End Camera Control (FECC) to some TANDBERG endpoints may not function. To resolve this, disable H.243.
- Chair Control cannot be taken from the endpoint menu via H.243 commands in conferences which are assigned with a chair PIN code. Chair Control can be taken via the MCU DTMF conference control menus.

**Encryption**

- Encryption does not function with TANDBERG endpoints that support both AES and DES and that are configured to only enable DES. To resolve this, enable AES in the endpoint.
- To fully utilize MCU port capacity when working with encryption, we recommend that you set the encryption mode to "Encryption required" in your service definition.

**Configuration**

- Using '0' as the service prefix causes unpredicted results. Refrain from using '0' as the service prefix.

**Video Quality**

- Joining more than 12 4CIF endpoints into a full-screen conference may result in significant delays.

**Audio Quality**

- When using G.722, static background noise may occasionally occur when endpoints are muted.

**H.239**

- In cascaded conferences with H.239, keep only one presentation open at any given time and close all other presentations. Using simultaneous presenters in a cascaded conference may result in the display of more than one presentation to participants.
- Enabling H.243 in the Settings > Conference Control section may cause H.239 interoperability issues with Aethra endpoints.
- Some ISDN endpoints connected to the MCU via a gateway may fail to send the presentation channel when using H.239 XGA.
- When working with H.239 XGA in a conference including Sony and Polycom or Sony and TANDBERG endpoints, the presentation video from the Polycom or TANDBERG endpoint may not appear on the Sony endpoint.

## Cascading

- In a cascaded conference, the conference control of the child conference does not indicate the identity of the active speaker. A workaround is to view the conference from the parent MCU that does display this correctly.

## SCCP

- When connecting Sony PCS1 in SCCP mode using H.264, video may not open. A workaround is to use H.263 when connecting Sony PCS1 using SCCP.
- Using the TANDBERG Transfer button in an SCCP conference with only one participant results in a video freeze or no video. This does not happen in conferences with more than one participant.
- We recommend that you do not change SCCP settings in the Protocols > SCCP screen while there are ongoing SCCP calls.
- The video display to some attendees may not show all the participants when you invite more than three attendees to an SCCP conference. To solve this issue, disable the No self-see feature.
- In SCCP conferences, video channels are closed and may fail to reopen when you use the hold/resume mechanism.

## T.120

- T.120 does not function across cascaded conferences.
- The Join Data Conference button on the MCU conference control page allows users to join T.120 data conferences from the computer running the conference control. This button is currently not available in version 5.0 and will be re-added in a later patch.

# Troubleshooting

- When the Windows Start Navigation sound is enabled, a continuous clicking sound is heard when the Conference Control interface automatically refreshes. Disable this sound in the Sounds and Multimedia configuration of the Control Panel.
- The Conference Control web interface operates in polling mode with updates every 10 seconds. To refresh information on the screen, reselect the tab you are currently viewing. Pressing the browser Refresh button causes you to exit from the Conference Control and displays the login screen.
- The Conference Control and Login screens are best viewed in full screen mode (1024 x 768 fps).
- The MCU allows you to open multiple Conference Control browser screens at the same time. It is recommended that you close screens in which you are not currently working to avoid confusion and performing operations on the wrong conference.

# Obtaining Documentation

Cisco documentation and additional literature are available on Cisco.com. This section explains the product documentation resources that Cisco offers.

## Cisco.com

You can access the most current Cisco documentation at this URL:

<http://www.cisco.com/techsupport>

You can access the Cisco website at this URL:

<http://www.cisco.com>

You can access international Cisco websites at this URL:

[http://www.cisco.com/public/countries\\_languages.shtml](http://www.cisco.com/public/countries_languages.shtml)

## Product Documentation DVD

The Product Documentation DVD is a library of technical product documentation on a portable medium. The DVD enables you to access installation, configuration, and command guides for Cisco hardware and software products. With the DVD, you have access to the HTML documentation and some of the PDF files found on the Cisco website at this URL:

<http://www.cisco.com/univercd/home/home.htm>

The Product Documentation DVD is created monthly and is released in the middle of the month. DVDs are available singly or by subscription. Registered Cisco.com users can order a Product Documentation DVD (product number DOC-DOCDVD= or DOC-DOCDVD=SUB) from Cisco Marketplace at the Product Documentation Store at this URL:

<http://www.cisco.com/go/marketplace/docstore>

## Ordering Documentation

You must be a registered Cisco.com user to access Cisco Marketplace. Registered users may order Cisco documentation at the Product Documentation Store at this URL:

<http://www.cisco.com/go/marketplace/docstore>

If you do not have a user ID or password, you can register at this URL:

<http://tools.cisco.com/RPF/register/register.do>

## Documentation Feedback

You can provide feedback about Cisco technical documentation on the Cisco Technical Support & Documentation site area by entering your comments in the feedback form available in every online document.

## Cisco Product Security Overview

Cisco provides a free online Security Vulnerability Policy portal at this URL:

[http://www.cisco.com/en/US/products/products\\_security\\_vulnerability\\_policy.html](http://www.cisco.com/en/US/products/products_security_vulnerability_policy.html)

From this site, you will find information about how to do the following:

- Report security vulnerabilities in Cisco products
- Obtain assistance with security incidents that involve Cisco products
- Register to receive security information from Cisco

A current list of security advisories, security notices, and security responses for Cisco products is available at this URL:

<http://www.cisco.com/go/psirt>

To see security advisories, security notices, and security responses as they are updated in real time, you can subscribe to the Product Security Incident Response Team Really Simple Syndication (PSIRT RSS) feed. Information about how to subscribe to the PSIRT RSS feed is found at this URL:

[http://www.cisco.com/en/US/products/products\\_psirt\\_rss\\_feed.html](http://www.cisco.com/en/US/products/products_psirt_rss_feed.html)

## Reporting Security Problems in Cisco Products

Cisco is committed to delivering secure products. We test our products internally before we release them, and we strive to correct all vulnerabilities quickly. If you think that you have identified a vulnerability in a Cisco product, contact PSIRT:

- For emergencies only — [security-alert@cisco.com](mailto:security-alert@cisco.com)

An emergency is either a condition in which a system is under active attack or a condition for which a severe and urgent security vulnerability should be reported. All other conditions are considered nonemergencies.

- For nonemergencies — [psirt@cisco.com](mailto:psirt@cisco.com)

In an emergency, you can also reach PSIRT by telephone:

- 1 877 228-7302
- 1 408 525-6532



### Tip

We encourage you to use Pretty Good Privacy (PGP) or a compatible product (for example, GnuPG) to encrypt any sensitive information that you send to Cisco. PSIRT can work with information that has been encrypted with PGP versions 2.x through 9.x.

Never use a revoked encryption key or an expired encryption key. The correct public key to use in your correspondence with PSIRT is the one linked in the Contact Summary section of the Security Vulnerability Policy page at this URL:

[http://www.cisco.com/en/US/products/products\\_security\\_vulnerability\\_policy.html](http://www.cisco.com/en/US/products/products_security_vulnerability_policy.html)

The link on this page has the current PGP key ID in use.

If you do not have or use PGP, contact PSIRT to find other means of encrypting the data before sending any sensitive material.

# Product Alerts and Field Notices

Modifications to or updates about Cisco products are announced in Cisco Product Alerts and Cisco Field Notices. You can receive Cisco Product Alerts and Cisco Field Notices by using the Product Alert Tool on Cisco.com. This tool enables you to create a profile and choose those products for which you want to receive information.

To access the Product Alert Tool, you must be a registered Cisco.com user. (To register as a Cisco.com user, go to this URL: <http://tools.cisco.com/RPF/register/register.do>) Registered users can access the tool at this URL: <http://tools.cisco.com/Support/PAT/do/ViewMyProfiles.do?local=en>

## Obtaining Technical Assistance

Cisco Technical Support provides 24-hour-a-day award-winning technical assistance. The Cisco Technical Support & Documentation website on Cisco.com features extensive online support resources. In addition, if you have a valid Cisco service contract, Cisco Technical Assistance Center (TAC) engineers provide telephone support. If you do not have a valid Cisco service contract, contact your reseller.

## Cisco Technical Support & Documentation Website

The Cisco Technical Support & Documentation website provides online documents and tools for troubleshooting and resolving technical issues with Cisco products and technologies. The website is available 24 hours a day at this URL:

<http://www.cisco.com/techsupport>

Access to all tools on the Cisco Technical Support & Documentation website requires a Cisco.com user ID and password. If you have a valid service contract but do not have a user ID or password, you can register at this URL:

<http://tools.cisco.com/RPF/register/register.do>



### Note

Use the **Cisco Product Identification Tool** to locate your product serial number before submitting a request for service online or by phone. You can access this tool from the Cisco Technical Support & Documentation website by clicking the **Tools & Resources** link, clicking the **All Tools (A-Z)** tab, and then choosing **Cisco Product Identification Tool** from the alphabetical list. This tool offers three search options: by product ID or model name; by tree view; or, for certain products, by copying and pasting **show** command output. Search results show an illustration of your product with the serial number label location highlighted. Locate the serial number label on your product and record the information before placing a service call.



### Tip

Displaying and Searching on Cisco.com

If you suspect that the browser is not refreshing a web page, force the browser to update the web page by holding down the Ctrl key while pressing F5.

To find technical information, narrow your search to look in technical documentation, not the entire Cisco.com website. On the Cisco.com home page, click the **Advanced Search** link under the Search box

and then click the **Technical Support & Documentation** radio button.

To provide feedback about the Cisco.com website or a particular technical document, click **Contacts & Feedback** at the top of any Cisco.com web page.

---

## Submitting a Service Request

Using the online TAC Service Request Tool is the fastest way to open S3 and S4 service requests. (S3 and S4 service requests are those in which your network is minimally impaired or for which you require product information.) After you describe your situation, the TAC Service Request Tool provides recommended solutions. If your issue is not resolved using the recommended resources, your service request is assigned to a Cisco engineer. The TAC Service Request Tool is located at this URL:

<http://www.cisco.com/techsupport/servicerequest>

For S1 or S2 service requests, or if you do not have Internet access, contact the Cisco TAC by telephone. (S1 or S2 service requests are those in which your production network is down or severely degraded.) Cisco engineers are assigned immediately to S1 and S2 service requests to help keep your business operations running smoothly.

To open a service request by telephone, use one of the following numbers:

Asia-Pacific: +61 2 8446 7411

Australia: 1 800 805 227

EMEA: +32 2 704 55 55

USA: 1 800 553 2447

For a complete list of Cisco TAC contacts, go to this URL:

<http://www.cisco.com/techsupport/contacts>

## Definitions of Service Request Severity

To ensure that all service requests are reported in a standard format, Cisco has established severity definitions.

**Severity 1 (S1)**—An existing network is “down” or there is a critical impact to your business operations. You and Cisco will commit all necessary resources around the clock to resolve the situation.

**Severity 2 (S2)**—Operation of an existing network is severely degraded, or significant aspects of your business operations are negatively affected by inadequate performance of Cisco products. You and Cisco will commit full-time resources during normal business hours to resolve the situation.

**Severity 3 (S3)**—Operational performance of the network is impaired while most business operations remain functional. You and Cisco will commit resources during normal business hours to restore service to satisfactory levels.

**Severity 4 (S4)**—You require information or assistance with Cisco product capabilities, installation, or configuration. There is little or no effect on your business operations.

# Obtaining Additional Publications and Information

Information about Cisco products, technologies, and network solutions is available from various online and printed sources.

- The *Cisco Product Quick Reference Guide* is a handy, compact reference tool that includes brief product overviews, key features, sample part numbers, and abbreviated technical specifications for many Cisco products that are sold through channel partners. It is updated twice a year and includes the latest Cisco channel product offerings. To order and find out more about the *Cisco Product Quick Reference Guide*, go to this URL:

<http://www.cisco.com/go/guide>

- Cisco Marketplace provides a variety of Cisco books, reference guides, documentation, and logo merchandise. Visit Cisco Marketplace, the company store, at this URL:

<http://www.cisco.com/go/marketplace/>

- Cisco Press publishes a wide range of general networking, training, and certification titles. Both new and experienced users will benefit from these publications. For current Cisco Press titles and other information, go to Cisco Press at this URL:

<http://www.ciscopress.com>

- *Packet* magazine is the magazine for Cisco networking professionals. Each quarter, *Packet* delivers coverage of the latest industry trends, technology breakthroughs, and Cisco products and solutions, as well as network deployment and troubleshooting tips, configuration examples, customer case studies, certification and training information, and links to scores of in-depth online resources. You can subscribe to *Packet* magazine at this URL:

<http://www.cisco.com/packet>

- *Internet Protocol Journal* is a quarterly journal published by Cisco Systems for engineering professionals involved in designing, developing, and operating public and private internets and intranets. You can access the *Internet Protocol Journal* at this URL:

<http://www.cisco.com/ipj>

- Networking products offered by Cisco Systems, as well as customer support services, can be obtained at this URL:

<http://www.cisco.com/en/US/products/index.html>

- Networking Professionals Connection is an interactive website where networking professionals share questions, suggestions, and information about networking products and technologies with Cisco experts and other networking professionals. Join a discussion at this URL:

<http://www.cisco.com/discuss/networking>

- “What’s New in Cisco Documentation” is an online publication that provides information about the latest documentation releases for Cisco products. Updated monthly, this online publication is organized by product category to direct you quickly to the documentation for your products. You can view the latest release of “What’s New in Cisco Documentation” at this URL:

<http://www.cisco.com/univercd/cc/td/doc/abtnicd/136957.htm>

- World-class networking training is available from Cisco. You can view current offerings at this URL:

<http://www.cisco.com/en/US/learning/index.html>

This document is to be used in conjunction with the documents listed in the “[Related Documentation](#)” section.

CCVP, the Cisco logo, and Welcome to the Human Network are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn is a service mark of Cisco Systems, Inc.; and Access Registrar, Aironet, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, Follow Me Browsing, FormShare, GigaDrive, HomeLink, Internet Quotient, IOS, iPhone, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, iQuick Study, LightStream, Linksys, MeetingPlace, MGX, Networkers, Networking Academy, Network Registrar, PIX, ProConnect, ScriptShare, SMARTnet, StackWise, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0711R)

Copyright © 2006 Cisco Systems, Inc. All rights reserved.