

End-of-Sale and End-of-Life Announcement for the CiscoWorks LAN Management Solution (LMS) 2.1

1316

Cisco Systems® announces the end-of-sale and end-of life dates for the CiscoWorks LAN Management Solution (LMS) 2.1. The last day to order the CiscoWorks LAN Management Solution (LMS) 2.1 is May 15, 2003. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the CiscoWorks LAN Management Solution (LMS) 2.1. Table 2 lists the product part numbers affected by this announcement.

Table 1. End-of-Life Milestones and Dates for the CiscoWorks LAN Management Solution (LMS) 2.1

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	April 15, 2003
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	May 15, 2003
Last Date of Support: SW	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	May 15, 2006

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description
CWLMS-1.2-MR-K9	Minor Release; Requires existing LMS 1.x WIN/SOL-May 02
CWLMS-2.1-K9	LAN Management 2.1 for WIN/SOL; CM, DFM, RME, RTM, CV
CWLMS-2.1-MR-K9	Minor Release; Requires existing LMS 2.0 WIN/SOL-May 02
CWLMS-2.1-SR-K9	Service Release Only; Req. existing LMS 2.0 WIN/SOL-May 02
CWLMS-2.1-P1-K9	Cross Bundle Discount for RWAN users adding LMS 2.1 WIN/SOL
CWLMS-2.1-UP-K9	UPGRADE to LMS2.1 for WIN/SOL from CWSI 2.x,SNMS 1.x,LMS 1.x

Product Migration Options

Customers are encouraged to migrate to the CiscoWorks LAN Management Solution (LMS) 2.2 for Windows and Solaris.

CiscoWorks LAN Management Solution (LMS) 2.2 provides a robust set of applications for maintaining, monitoring, and troubleshooting Cisco Campus networks. This solution complements the Cisco AVVID architecture by addressing the management needs of converged data, voice, and video networks.

Key features of LMS 2.2 and the update kits are:

- Enhancements to the CiscoWorks Server replacing its CD One naming with "Common Services"
- Support for new devices, Cisco IOS® releases and roll up of past incremental device updates (IDUs)
- Support for Windows 2000 Advanced Server and updates to existing operating system support
- Minor updates and improvements made in all LMS applications
- Combined update kit for LMS 1.X and 2.X users

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

For More Information

For more information about the CiscoWorks LAN Management Solution (LMS) 2.1, visit <http://www.cisco.com/go/lms> or contact your local account representative, or send an e-mail to lms-pm@cisco.com.

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/prod_end_of_life.html

To subscribe to receive end-of-life/end-of-sale information, go to: <http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>

**Americas Headquarters**

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA

www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems, Inc.
168 Robinson Road
#28-01 Capital Tower
Singapore 068912

www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Europe Headquarters

Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands

www-europe.cisco.com
Tel: +31 0 800 020 0791
Fax: +31 0 20 357 1100

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

©2006 Cisco Systems, Inc. All rights reserved. CCVP, the Cisco logo, and the Cisco Square Bridge logo are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn is a service mark of Cisco Systems, Inc.; and Access Registrar, Aironet, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, Follow Me Browsing, FormShare, GigaDrive, GigaStack, HomeLink, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, iQuick Study, LightStream, Linksys, MeetingPlace, MGX, Networking Academy, Network Registrar, Packet, PIX, ProConnect, RateMUX, ScriptShare, SlideCast, SMARTnet, StackWise, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0609R)