



END-OF-SALE AND END-OF-LIFE ANNOUNCEMENT FOR THE CISCO ONS 15454 OC-192 LONG-REACH/STM-64 LONG-HAUL 1550-NM OPTICS CARDS

Cisco Systems® announces the end-of-sale and end-of-life dates for the Cisco® ONS 15454 OC-192 long-reach (LR)/STM-64 long-haul (LH) 1550-nm optics cards, with part numbers 15454-OC192LR1550 and 15454E-L64.2-1-HS. The last day to order these Cisco ONS 15454 OC-192 optics cards is January 27, 2005. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) until January 27, 2010. Table 1 describes the end-of-life milestones, definitions, and dates for the Cisco ONS 15454 OC-192 optics cards. Table 2 lists the product part numbers affected by this announcement.

Customers are encouraged to migrate to the latest Cisco ONS 15454 OC-192LR/STM-64H optics cards, with part numbers OC192-LR2 and L64.2-1-HS, which provide design enhancements for improved reliability and manufacturability. Information about the replacement products can be found at: <http://www.cisco.com/en/US/products/hw/modules/ps2831/ps4474/index.html>.

Table 3 provides relevant information for migrating from the existing Cisco ONS 15454 OC-192 optics cards to the replacement optics cards.

Table 1 End-of-Life Milestones and Dates for the Cisco ONS 15454 OC-192LR/STM-64LH Optics Cards, Versions OC192-LR2 and L64.2-1-HS

Milestone	Definition	Date
End-of-life announcement date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	July 27, 2004
End-of-sale date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	January 27, 2005
Last shipment date	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	April 27, 2005
End of routine failure analysis date	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	January 27, 2006
End of new service attachment date	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	January 27, 2006
End of service contract renewal date	The last date to extend or renew a service contract for the product. The extension or renewal period cannot extend beyond the last date of support.	October 27, 2009
Last date of support	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	January 27, 2010

Table 2 Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description
15454-OC192LR1550	OC-192/STM-64 optics card, long-reach/long-haul, 1550 nm, Cisco ONS 15454 SONET/ANSI system
15454-OC192LR1550=	OC-192/STM-64 optics card, long-reach/long-haul, 1550 nm, Cisco ONS 15454 SONET/ANSI system, spare
15454E-L64.2-1-HS	STM-64 optics card, long-haul, 1550 nm, Cisco ONS 15454 SDH/ETSI system
15454E-L64.2-1-HS=	STM-64 optics card, long-haul, 1550 nm, Cisco ONS 15454 SDH/ETSI system, spare

PRODUCT MIGRATION OPTIONS

The recommended replacements for the Cisco ONS 15454 OC-192 optics cards are shown in Table 3. The replacement cards require that the Cisco ONS 15454 network element system software be upgraded to at least Release 3.1.0 for SONET systems and Release 3.3.0 for SDH systems prior to installing the new optics card.

Table 3 Product Comparisons

Feature	Cisco End-of-Life Product	Cisco Replacement Product
Part number (SONET/ANSI)	15454-OC192LR1550	15454-OC192LR2
Part number (SDH/ETSI)	15454E-L64.2-1-HS	15454E-L64.2-1
Transmitter power (minimum)	+7 dBm	+4 dBm
Receiver sensitivity (minimum)	-21 dBm	-24 dBm
Power penalty	4 dB	2 dB
Chromatic dispersion tolerance	1360 ps/nm	1600 ps/nm
Minimum software release	Release 3.1.0 (SONET/ANSI) Release 3.3.0 (SDH/ETSI)	Release 4.0.0 (SONET/ANSI and SDH/ETSI)

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

Customers may be able to continue to purchase Cisco ONS 15454 OC-192 optics cards, versions 15454-OC192LR1550 and 15454E-L64.2-1-HS through the Cisco Authorized Refurbished Equipment program. Refurbished units of the Cisco ONS 15454 OC-192 long reach (LR)/STM-64 long haul (LH) 1550 nm optics cards, versions 15454-OC192LR1550 and 15454E-L64.2-1-HS are available in limited supply for sale in certain countries on a first-come, first-served basis. For information about the refurbished equipment program, go to: http://www.cisco.com/en/US/ordering/or6/or17/order_refurbished_equipment_program_description.html.



FOR MORE INFORMATION

For more information about the Cisco ONS 15454, visit: <http://cisco.com/en/US/products/hw/optical/ps2006/index.html> or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/prod_end_of_life.html. To subscribe to receive end-of-life/end-of-sale information, please go to:

<http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>

**Corporate Headquarters**

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters

Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems, Inc.
168 Robinson Road
#28-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the

Cisco Website at www.cisco.com/go/offices.

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica
Croatia • Cyprus • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR
Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico
The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia
Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan
Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2004 Cisco Systems, Inc. All rights reserved. Cisco, Cisco Systems, and the Cisco Systems logo are registered trademarks or trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0406R) ML/LW6646 0704

Printed in the USA