



## END-OF-SALE AND END-OF-LIFE ANNOUNCEMENT FOR THE CISCO OC-12C/STM-4 DYNAMIC PACKET TRANSPORT PORT ADAPTER SUPPORTED ON THE CISCO 7500 AND 7200 SERIES ROUTERS AND CISCO uBR7246VXR UNIVERSAL BROADBAND ROUTER

Cisco Systems® announces the end-of-sale and end-of-life dates for the Cisco Dual-Width OC-12c/STM-4 Dynamic Packet Transport (DPT) port adapter supported on the Cisco® 7500 and 7200 Series routers and Cisco uBR7246VXR Universal Broadband Router. The last day to order the port adapter is July 15, 2005. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) until July 15, 2010. Table 1 describes the end-of-life milestones, definitions, and dates for the affected port adapter. Table 2 lists the product numbers affected by this announcement.

There is no migration path to support OC-12c/STM-4 DPT on the Cisco 7500 and 7200 Series routers or on the Cisco uBR7246VXR Universal Broadband Router. Customers are encouraged to migrate to the Cisco 10720 Router, which supports OC-48c/STM-16 DPT. The Cisco 10720 is a principle building block in the next-generation metro IP network. The Cisco 10720 Router enables service providers to offer innovative and differentiated IP services to their customers at optical speeds. Equipped with Ethernet technology for customer access and DPT technology for metro optical connectivity, the Cisco 10720 allows service providers to offer IP services closer to the user, enabling them to better control admission to network resources.

Information about this product can be found at: <http://www.cisco.com/en/US/products/hw/routers/ps147/index.html>.

**Table 1.** End-of-Life Milestone Dates for the Dual Width OC-12c/STM-4DPT Port Adapter Supported on the Cisco 7500 and 7200 Series Routers and Cisco uBR7246VXR Universal Broadband Router

Milestone	Definition	Date
End-of-life announcement date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	January 15, 2005
End-of-sale date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	July 15, 2005
Last shipment date	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	October 15, 2005
End of software maintenance releases date	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	July 15, 2006
End of routine failure analysis date	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	July 15, 2006
End of new service attachment date	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	July 15, 2006
End of service contract renewal date	The last date to extend or renew a service contract for the product. The extension or renewal period cannot extend beyond the last date of support.	April 15, 2010
Last date of support	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	July 15, 2010

**Table 2.** Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description
PA-SRP-OC12MM	Dual-width OC-12c/STM-4 DPT port adapter that provides a shared, IP-over-optical, multimode standard capability in Cisco 7500 Series, Cisco 7200 Series, Cisco uBR7246VXR, or Cisco 7200 VXR Series routers
PA-SRP-OC12SMI	Dual-width OC-12c/STM-4 DPT port adapter that provides a shared, IP-over-optical, single-mode-fiber, intermediate-reach capability in Cisco 7500 Series, Cisco 7200 Series, Cisco uBR7246VXR, or Cisco 7200 VXR Series routers
PA-SRP-OC12SML	Dual-width OC-12c/STM-4 DPT port adapter that provides a shared, IP-over-optical, single-mode-fiber, long-reach capability in Cisco 7500 Series, Cisco 7200 Series, Cisco uBR7246VXR, or Cisco 7200 VXR Series routers
PA-SRP-OC12SMX	Dual-width OC-12c/STM-4 DPT port adapter that provides a shared, IP-over-optical, single-mode-fiber, extended-reach capability in Cisco 7500 Series, Cisco 7200 Series, Cisco uBR7246VXR, or Cisco 7200 VXR Series routers

## PRODUCT MIGRATION OPTIONS

The recommended replacement for the Cisco 7500 and 7200 Series and Cisco uBR7246VXR OC-12c/STM-4 DPT port adapter is the Cisco 10720 Router, which supports OC-48/STM 16 DPT.

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

## FOR MORE INFORMATION

For more information about the Cisco 10720 Router, visit:

[http://www.cisco.com/en/US/prod/collateral/routers/ps147/ps148/product\\_data\\_sheet09186a0080091b6b.html](http://www.cisco.com/en/US/prod/collateral/routers/ps147/ps148/product_data_sheet09186a0080091b6b.html) or contact your local account representative at [ask-10720-pm](mailto:ask-10720-pm).

For more information about the Cisco End-of-Life Policy, go to: [http://www.cisco.com/en/US/products/prod\\_end\\_of\\_life.html](http://www.cisco.com/en/US/products/prod_end_of_life.html).

To subscribe to receive end-of-life/end-of-sale information, go to: <http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>.



#### **Corporate Headquarters**

Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 526-4100

#### **European Headquarters**

Cisco Systems International BV  
Haarlerbergpark  
Haarlerbergweg 13-19  
1101 CH Amsterdam  
The Netherlands  
www-europe.cisco.com  
Tel: 31 0 20 357 1000  
Fax: 31 0 20 357 1100

#### **Americas Headquarters**

Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-7660  
Fax: 408 527-0883

#### **Asia Pacific Headquarters**

Cisco Systems, Inc.  
168 Robinson Road  
#28-01 Capital Tower  
Singapore 068912  
www.cisco.com  
Tel: +65 6317 7777  
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on **the Cisco Website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica  
Croatia • Cyprus • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR  
Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico  
The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia  
Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan  
Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992–2005 Cisco Systems, Inc. All rights reserved. Cisco, Cisco Systems, and the Cisco Systems logo are registered trademarks or trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0502R) Pa/LW8174 03/05

