

## End-of-Sale and End-of-Life Announcement for the Multiprocessor Forwarding (MPF) on Cisco 7200 NPE-G1 and Cisco 7301 for Broadband LAC, LNS, and PTA

EOL5501

Cisco Systems® announces the end-of-sale and end-of life dates for the Multiprocessor Forwarding (MPF) on Cisco 7200 NPE-G1 and Cisco 7301 for Broadband LAC, LNS, and PTA. The last day to order the Multiprocessor Forwarding (MPF) on Cisco 7200 NPE-G1 and Cisco 7301 for Broadband LAC, LNS, and PTA is December 28, 2007. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the Multiprocessor Forwarding (MPF) on Cisco 7200 NPE-G1 and Cisco 7301 for Broadband LAC, LNS, and PTA. Table 2 lists the product part numbers affected by this announcement.

**Table 1.** End-of-Life Milestones and Dates for the Multiprocessor Forwarding (MPF) on Cisco 7200 NPE-G1 and Cisco 7301 for Broadband LAC, LNS, and PTA.

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	June 29, 2007
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	December 28, 2007
Last Ship Date: OS SW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	March 27, 2008
End of SW Maintenance Releases Date: OS SW	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	December 27, 2008
End of New Service Attachment Date: OS SW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	December 27, 2008
End of Service Contract Renewal Date: OS SW	The last date to extend or renew a service contract for the product.	March 24, 2012
Last Date of Support: OS SW	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	December 26, 2012

HW = Hardware

OS SW = Operating System Software

App. SW = Application Software

**Table 2.** Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
CISCO7301BB-8K-MPF	7301, 1 G Mem, 64MB Fl, AC Pwr, MPF sw, up to 8k sub BBA lic	CISCO7201	Cisco 7201 Chassis, 1GB Memory, Dual P/S, 256MB Flash

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
FR-MPF72	MPF license for 7200	See the Product Migration Options section below for detailed information on replacing this product.	
FR-MPF72=	MPF license for 7200	See the Product Migration Options section below for detailed information on replacing this product.	
FR-MPF73	MPF License for 7301	See the Product Migration Options section below for detailed information on replacing this product.	
FR-MPF73=	MPF License for 7301	See the Product Migration Options section below for detailed information on replacing this product.	
MPF-1G=	7301 MPF sw w/ 1 G Mem	See the Product Migration Options section below for detailed information on replacing this product.	

### Product Migration Options

Customers are encouraged to migrate to the Cisco 7201 Router. The Cisco 7201 Router has a 1RU form factor of the Cisco 7200 Series Routers. The Cisco 7201 Router is based on the NPE-G2 Network Processing Engine, and it offers performance enhancements. In addition, it includes four built-in 10/100/1000 ports with a default memory of 1 GB upgradable to 2 GB and with dual field-replaceable AC/DC power supplies.

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

Customers may be able to continue to purchase the end-of-sale product through Cisco's Authorized Refurbished Equipment program. Refurbished units of the end-of-sale product are available in limited supply for sale in certain countries on a first-come, first-served basis. For information about the refurbished equipment program, go to: [http://www.cisco.com/en/US/ordering/or6/or17/order\\_refurbished\\_equipment\\_program\\_description.html](http://www.cisco.com/en/US/ordering/or6/or17/order_refurbished_equipment_program_description.html)

### For More Information

For more information about the Cisco 7201 Router, visit <http://www.cisco.com/en/US/products/ps7253/index.html>, contact your local account representative, or send an e-mail to [ask-sfs-pm@cisco.com](mailto:ask-sfs-pm@cisco.com).

For more information about the Cisco End-of-Life Policy, go to: [http://www.cisco.com/en/US/products/prod\\_end\\_of\\_life.html](http://www.cisco.com/en/US/products/prod_end_of_life.html)

To subscribe to receive end-of-life/end-of-sale information, go to: <http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>



**Americas Headquarters**  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 527-0689

**Asia Pacific Headquarters**  
Cisco Systems, Inc.  
155 Robinson Road  
#29-01 Capital Tower  
Singapore 068912  
www.cisco.com  
Tel: +65 6317 7777  
Fax: +65 6317 7799

**Europe Headquarters**  
Cisco Systems International BV  
Heerlenbergpark  
Heerlenbergweg 13-19  
1101 CH Amsterdam  
The Netherlands  
www.europe.cisco.com  
Tel: +31 20 600 020 0/91  
Fax: +31 20 657 1100

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).

©2007 Cisco Systems, Inc. All rights reserved. CCVP, the Cisco logo, and the Cisco Square Ridge logo are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn is a service mark of Cisco Systems, Inc.; and Access Registrar, Airnet, BPK, Catalyst, CCNA, CCDF, CCIE, CCR, CCNA, CCNP, CCSP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fax, Step, Follow Me, Browning, ForceShare, Go to Drive, HomeLink, Internet Quotient, IOS, iPhone, IPTV, IQ Expertise, the IQ logo, IQ Not, Roadnote, Scorecard, QuickStudy, SignStream, iInlays, Meeting Place, MGX, Networking Academy, Network Registrar, Packet, PIX, ProConnect, ScriptShare, SMARTnet, SsookWise, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (9705R)