



END-OF-SALE AND END-OF-LIFE ANNOUNCEMENT FOR SPECIFIC CISCO MGX 8800 SERIES SOFTWARE RELEASES, CARDS, AND CONNECTORS

Cisco Systems® announces the end-of-sale and end-of-life dates for the specific cards, connectors, and software licenses listed in Table 2 and associated with the Cisco® MGX® 8800 Series Switch. The last day to order these cards, connectors and software licenses is October 15, 2005. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) until October 15, 2010. Table 1 describes the end-of-life milestones, definitions, and dates for the Cisco product part numbers affected by this announcement. Table 2 lists the actual product part numbers.

This notice is tied to the release over the past year of several new hardware and software products intended to continue to enrich and refresh the Cisco MGX Family of products. Customers are encouraged to migrate to the respective product options listed in Table 3. Information about these products can be found at: <http://www.cisco.com>.

Table 1. End-of-Life Milestones and Dates for the Affected Cisco Products

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	October 15, 2004
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	October 15, 2005
Last Shipment Date	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	January 15, 2006
End of Software Maintenance Releases Date	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	October 15, 2007
End of Routine Failure Analysis Date	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	October 15, 2007
End of New Service Attachment Date	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	October 15, 2006
End of Service Contract Renewal Date	The last date to extend or renew a service contract for the product. The extension or renewal period cannot extend beyond the last date of support.	October 15, 2009
Last Date of Support	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	October 15, 2010

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description
PXM45/B	1 PXM45/B, 1 PXM-UI-S3 and 1 PXM-HD in system [processor/switch module]
PXM45/B=	45-Gbps processor/fabric, PXM45/B (no PXM-UI-S3 or PXM-HD)
PXM45/B-R	2 PXM45/B, 2 PXM-UI-S3, 2 PXM-HD in system [processor/switch module]
FRSM-12-T3E3	Double-height Frame SM, 12 unchanneled T3s or E3s
FRSM-12-T3E3=	Double-height Frame SM, 12 unchanneled T3s or E3s
SMB-6-T3E3	6 T3/E3 single height BC, SMB connectors
SMB-6-T3E3=	6 T3/E3 single height BC, SMB connectors
AX-CESM-8T1	Circuit Emulation Service Module, Eight T1 Ports
AX-CESM-8T1=	Circuit Emulation Service Module, Eight T1 Ports
MGX-APS-CON	Connector used to connect 2 single height BCs for APS
MGX-APS-CON=	Connector used to connect 2 single height BCs for APS
MGX8950-SW-2180	MGX 8950 System Software License—Release (Version 2.1.80)
MGX8950-SW-2180CD=	MGX 8950 System Software License—Spare CD (Version 2.1.80)
MGX8950-SW-2181	MGX 8950 System Software License—Release (Version 2.1.81)
MGX8950-SW-2181CD=	MGX 8950 System Software License—Spare CD (Version 2.1.81)
MGX8850-SW-2182	MGX 8850 System Software License—Release (Version 2.1.82)
MGX8850-SW-2182CD=	MGX 8850 System Software License—Spare CD (Version 2.1.82)
MGX8950-SW-2182	MGX 8950 System Software License—Release (Version 2.1.82)
MGX8950-SW-2182CD=	MGX 8950 System Software License—Spare CD (Version 2.1.82)
MGX8850-SW-3000	MGX 8850 System Software License—Release (Version 3.0)
MGX8850-SW-3000CD=	MGX 8850 System Software License—Spare CD (Version 3.0.00)
MGX8950-SW-3000	MGX 8950 System Software License—Release (Version 3.0)
MGX8950-SW-3000CD=	MGX 8950 System Software License—Spare CD (Version 3.0.00)
MGX8830-SW-3000	MGX 8830 System Software License—Release (Version 3.0)
MGX8830-SW-3000CD=	MGX 8830 System Software License—Spare CD (Version 3.0.00)
MGX8850-SW-3010	MGX 8850 System Software License—Release (Version 3.0.10)
MGX8850-SW-3010CD=	MGX 8850 System Software License—Spare CD (Version 3.0.10)
MGX8950-SW-3010	MGX 8950 System Software License—Release (Version 3.0.10)
MGX8950-SW-3010CD=	MGX 8950 System Software License—Spare CD (Version 3.0.10)
MGX8830-SW-3010	MGX 8830 System Software License—Release (Version 3.0.10)
MGX8830-SW-3010CD=	MGX 8830 System Software License—Spare CD (Version 3.0.10)
MGX8850-SW-3011	MGX 8850 System Software License—Release (Version 3.0.11)
MGX8850-SW-3011CD=	MGX 8850 System Software License—Spare CD (Version 3.0.11)
MGX8950-SW-3011	MGX 8950 System Software License—Release (Version 3.0.11)
MGX8950-SW-3011CD=	MGX 8950 System Software License—Spare CD (Version 3.0.11)
MGX8830-SW-3011	MGX 8830 System Software License—Release (Version 3.0.11)
MGX8830-SW-3011CD=	MGX 8830 System Software License—Spare CD (Version 3.0.11)

End-of-Sale Product Part Number	Product Description
MGX8850-SW-3020	MGX 8850 System Software License—Release (Version 3.0.20)
MGX8850-SW-3020CD=	MGX 8850 System Software License—Spare CD (Version 3.0.20)
MGX8950-SW-3020	MGX 8950 System Software License—Release (Version 3.0.20)
MGX8950-SW-3020CD=	MGX 8950 System Software License—Spare CD (Version 3.0.20)
MGX8830-SW-3020	MGX 8830 System Software License—Release (Version 3.0.20)
MGX8830-SW-3020CD=	MGX 8830 System Software License—Spare CD (Version 3.0.20)
MGX8850-SW-3021	MGX 8850 System Software License—Release (Version 3.0.21)
MGX8850-SW-3021CD=	MGX 8850 System Software License—Spare CD (Version 3.0.21)
MGX8950-SW-3021	MGX 8950 System Software License—Release (Version 3.0.21)
MGX8950-SW-3021CD=	MGX 8950 System Software License—Spare CD (Version 3.0.21)
MGX8830-SW-3021	MGX 8830 System Software License—Release (Version 3.0.21)
MGX8830-SW-3021CD=	MGX 8830 System Software License—Spare CD (Version 3.0.21)
MGX8850-SW-3023	MGX 8850 System Software License—Release (Version 3.0.23)
MGX8850-SW-3023CD=	MGX 8850 System Software License—Spare CD (Version 3.0.23)
MGX8950-SW-3023	MGX 8950 System Software License—Release (Version 3.0.23)
MGX8950-SW-3023CD=	MGX 8950 System Software License—Spare CD (Version 3.0.23)
MGX8830-SW-3023	MGX 8830 System Software License—Release (Version 3.0.23)
MGX8830-SW-3023CD=	MGX 8830 System Software License—Spare CD (Version 3.0.23)
MGX8850-SW-3025	MGX 8850 System Software License—Release (Version 3.0.25)
MGX8850-SW-3025CD=	MGX 8850 System Software License—Spare CD (Version 3.0.25)
MGX8950-SW-3025	MGX 8950 System Software License—Release (Version 3.0.25)
MGX8950-SW-3025CD=	MGX 8950 System Software License—Spare CD (Version 3.0.25)
MGX8830-SW-3025	MGX 8830 System Software License—Release (Version 3.0.25)
MGX8830-SW-3025CD=	MGX 8830 System Software License—Spare CD (Version 3.0.25)

PRODUCT MIGRATION OPTIONS

No migration programs are applicable.

Table 3. Product Comparisons

Cisco End-of-Life Product Part Number	Cisco Product Option Part Number
PXM45/B	PXM45/C
PXM45/B=	PXM45/C=
PXM45/B-R	PXM45/C-R
FRSM-12-T3E3	MPSM-T3E3-155
FRSM-12-T3E3=	MPSM-T3E3-155=
SMB-6-T3E3	BNC-3-T3E3
SMB-6-T3E3=	BNC-3-T3E3=
AX-CESM-8T1	MGX-CESM-8T1/B
AX-CESM-8T1=	MGX-CESM-8T1/B=
MGX-APS-CON	MGX-8850-APS-CON
MGX-APS-CON=	MGX-8850-APS-CON=
MGX8950-SW-2180	MGX8950-SW-5010
MGX8950-SW-2180CD=	MGX8950-SW-5010CD=
MGX8950-SW-2181	MGX8950-SW-5010
MGX8950-SW-2181CD=	MGX8950-SW-5010CD=
MGX8850-SW-2182	MGX8850-SW-5010
MGX8850-SW-2182CD=	MGX8850-SW-5010CD=
MGX8950-SW-2182	MGX8950-SW-5010
MGX8950-SW-2182CD=	MGX8950-SW-5010CD=
MGX8850-SW-3000	MGX8850-SW-5010
MGX8850-SW-3000CD=	MGX8850-SW-5010CD=
MGX8950-SW-3000	MGX8950-SW-5010
MGX8950-SW-3000CD=	MGX8950-SW-5010CD=
MGX8830-SW-3000	MGX8830-SW-5010
MGX8830-SW-3000CD=	MGX8830-SW-5010CD=
MGX8850-SW-3010	MGX8850-SW-5010
MGX8850-SW-3010CD=	MGX8850-SW-5010CD=
MGX8950-SW-3010	MGX8950-SW-5010
MGX8950-SW-3010CD=	MGX8950-SW-5010CD=
MGX8830-SW-3010	MGX8830-SW-5010
MGX8830-SW-3010CD=	MGX8830-SW-5010CD=
MGX8850-SW-3011	MGX8850-SW-5010
MGX8850-SW-3011CD=	MGX8850-SW-5010CD=
MGX8950-SW-3011	MGX8950-SW-5010
MGX8950-SW-3011CD=	MGX8950-SW-5010CD=
MGX8830-SW-3011	MGX8830-SW-5010
MGX8830-SW-3011CD=	MGX8830-SW-5010CD=

Cisco End-of-Life Product Part Number	Cisco Product Option Part Number
MGX8850-SW-3020	MGX8850-SW-5010
MGX8850-SW-3020CD=	MGX8850-SW-5010CD=
MGX8950-SW-3020	MGX8950-SW-5010
MGX8950-SW-3020CD=	MGX8950-SW-5010CD=
MGX8830-SW-3020	MGX8830-SW-5010
MGX8830-SW-3020CD=	MGX8830-SW-5010CD=
MGX8850-SW-3021	MGX8850-SW-5010
MGX8850-SW-3021CD=	MGX8850-SW-5010CD=
MGX8950-SW-3021	MGX8950-SW-5010
MGX8950-SW-3021CD=	MGX8950-SW-5010CD=
MGX8830-SW-3021	MGX8830-SW-5010
MGX8830-SW-3021CD=	MGX8830-SW-5010CD=
MGX8850-SW-3023	MGX8850-SW-5010
MGX8850-SW-3023CD=	MGX8850-SW-5010CD=
MGX8950-SW-3023	MGX8950-SW-5010
MGX8950-SW-3023CD=	MGX8950-SW-5010CD=
MGX8830-SW-3023	MGX8830-SW-5010
MGX8830-SW-3023CD=	MGX8830-SW-5010CD=
MGX8850-SW-3025	MGX8850-SW-5010
MGX8850-SW-3025CD=	MGX8850-SW-5010CD=
MGX8950-SW-3025	MGX8950-SW-5010
MGX8950-SW-3025CD=	MGX8950-SW-5010CD=
MGX8830-SW-3025	MGX8830-SW-5010
MGX8830-SW-3025CD=	MGX8830-SW-5010CD=

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

FOR MORE INFORMATION

For more information about these Cisco products, please visit: <http://www.cisco.com> or contact your local Cisco account manager and/or Cisco Channel Partner.

For more information about the Cisco End-of-Life Policy, go to:

http://www.cisco.com/en/US/products/prod_end_of_life.html

To subscribe to receive end-of-life/end-of-sale information, go to:

<http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>



Corporate Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters

Cisco Systems International
BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems, Inc.
168 Robinson Road
#28-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on **the Cisco Web site at www.cisco.com/go/offices.**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Cyprus
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland
Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland
Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden
Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2005 Cisco Systems, Inc. All rights reserved. CCSP, CCVP, the Cisco Square Bridge logo, Follow Me Browsing, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Access Registrar, Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, FormShare, GigaDrive, GigaStack, HomeLink, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MeetingPlace, MGX, the Networkers logo, Networking Academy, Network Registrar, *Packet*, PIX, Post-Routing, Pre-Routing, ProConnect, RateMUX, ScriptShare, SlideCast, SMARTnet, StrataView Plus, TeleRouter, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0502R) 204123.BN_ETMG_JC_9.05