

End-of-Sale and End-of-Life Announcement for the Cisco BTS 10200 Softswitch Release 4.4.0 and 4.4.1

EOL5489

Cisco Systems[®] announces the end-of-sale and end-of life dates for the Cisco BTS 10200 Softswitch Release 4.4.0 and 4.4.1. The last day to order the Cisco BTS 10200 Softswitch Release 4.4.0 and 4.4.1 is July 20, 2007. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the Cisco BTS 10200 Softswitch Release 4.4.0 and 4.4.1. Table 2 lists the product part numbers affected by this announcement.

Table 1. End-of-Life Milestones and Dates for the Cisco BTS 10200 Softswitch Release 4.4.0 and 4.4.1

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	January 19, 2007
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	July 20, 2007
Last Ship Date: App. SW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	October 18, 2007
End of SW Maintenance Releases Date: App. SW	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	July 19, 2008
End of New Service Attachment Date: App. SW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	July 19, 2008
End of Service Contract Renewal Date: App. SW	The last date to extend or renew a service contract for the product.	October 15, 2009
Last Date of Support: App. SW	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	July 19, 2010

HW = Hardware OS SW = Operating System Software App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description
BTS-SW-4.4.0	BTS 10200 Release 4.4.0 Software
BTS-SW-4.4.0V02K9	BTS 10200 R4.4.0V02 Software
BTS-SW-4.4.0V04K9	BTS 10200 Release 4.4.0V04 Software
BTS-SW-4.4.0V05K9	BTS 10200 R4.2.0V05 Software
BTS-SW-4.4.0V06K9	BTS 10200 Release 4.4.0V06 Software
BTS-SW-4.4.0V07K9	BTS 10200 Release 4.4.0V07 Software
BTS-SW-4.4.0V08K9	BTS 10200 Release 4.4.0V08 Software
BTS-SW-4.4.1	BTS 10200 Release 4.4.1 Software
BTS-SW-4.4.1V01K9	BTS 10200 R4.4.1V01 Software
BTS-SW-4.4.1V10K9	BTS 10200 Base Software - R4.4.1V10

BTS10200-SW-CAB-1	BTS 10200 DQOS, Event Messaging and Security - Version 1
BTS10200-SW-CEN-1	BTS 10200 Basic CENTREX - Version 1
BTS10200-SW-H323-1	BTS 10200 H.323 Protocol Support - Version 1
BTS10200-SW-LI-1	BTS 10200 Lawful Intercept Support - Version 1
BTS10200-SW-PRI-1	BTS 10200 PRI Access Side Support - Version 1
BTS10200-SW-SIP-1	BTS 10200 SIP Protocol Support - Version 1
BTS10200-SW-SPA1K9	BTS 10200 Subscriber Provisioning Application - Version 1

Product Migration Options

Customers are encouraged to migrate to the Cisco BTS 10200 Softswitch Release 4.5.1

Information about this product can be found at:

<http://www.cisco.com/en/US/products/hw/vcallcon/ps531/index.html>.

For More Information

For more information about the Cisco BTS 10200 Softswitch Release 4.5.1, visit

<http://www.cisco.com/en/US/products/hw/vcallcon/ps531/index.html>, contact your local account representative, or send an e-mail to bts-info@cisco.com.

For more information about the Cisco End-of-Life Policy, go to:

http://www.cisco.com/en/US/products/prod_end_of_life.html.

To subscribe to receive end-of-life/end-of-sale information, go to:

<http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>.



Americas Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-7033
USA
www.cisco.com
Tel: 408 526-4000
920 628-NETS (63637)
Fax: 408 527-0883

Asia Pacific Headquarters
Cisco Systems, Inc.
199 Robinson Road
#28-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Europe Headquarters
Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www.europe.cisco.com
Tel: +31 20 200 0700
Fax: +31 20 200 357 1100

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

©2006 Cisco Systems, Inc. All rights reserved. CDVR, the Cisco logo, and the Cisco Square Bridge logo are trademarks of Cisco Systems, Inc. Changing the Way We Work, Live, Play, and Learn is a service mark of Cisco Systems, Inc. and Access, Registrar, Aronol, BPX, Catalyst, CCDA, CCDP, CCIE, CDP, CCNA, CCNP, CCSP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, Follow Me Browsing, FormShare, GigaDrive, GigaStack, HomeLink, Internet Quotient, IOS, IP Phone, iTV, IQ Experience, the IQ logo, IQ Net Readiness Scorecard, iClick Study, LightStream, Linksys, MeetingPlace, MQX, Networking Academy, Network Registrar, Packet, PIX, ProConnect, RateMUX, ScriptShare, SlideCast, SMARtNet, StackWise, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (08129)