

End-of-Sale and End-of-Life Announcement for the Cisco PIX Security Appliance Software v8.0

EOL6327

Cisco® announces the end-of-sale and end-of life dates for the Cisco PIX Security Appliance Software v8.0. The last day to order the affected product(s) is July 28, 2008. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

Cisco PIX Security Appliance customers are encouraged to migrate to Cisco ASA 5500 Series Adaptive Security Appliances. Built on the same software foundation as Cisco PIX Security Appliances, the Cisco ASA 5500 Series offers more robust firewall and IPsec VPN capabilities, as well as many additional benefits, including:

- Significantly better performance and scalability
- Secure Sockets Layer (SSL) VPN support (including clientless, portal-based remote access)
- Advanced Unified Communications (voice/video) security
- A modular design that allows you to add features such as intrusion prevention (IPS), anti-virus, anti-spam, anti-phishing, and URL filtering.

Migration to the Cisco ASA 5500 Series is straightforward. Customers can take advantage of their knowledge and investment in Cisco PIX Security Appliances, because there are essentially no changes in user interface, operations, or training.

Table 1. End-of-Life Milestones and Dates for the Cisco PIX Security Appliance Software v8.0

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	January 28, 2008
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	July 28, 2008
Last Ship Date: OS SW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	October 26, 2008
End of SW Maintenance Releases Date: OS SW	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	July 28, 2009
End of New Service Attachment Date: OS SW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	July 28, 2009
End of Service Contract Renewal Date: OS SW	The last date to extend or renew a service contract for the product.	October 23, 2012

Last Date of Support	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	July 27, 2013
----------------------	------------------------------------------------------------------------------------------------------------------------------------------------------------------------	---------------

HW = Hardware

OS SW = Operating System Software

App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
SF-PIX-515-8.0	PIX OS 8.0 for the PIX 515E Chassis	SF-ASA-8.0-K8	ASA 5500 Series Software v8.0
SF-PIX-8.0	PIX OS 8.0 for the PIX 525 and 535 Chassis	SF-ASA-8.0-K8	ASA 5500 Series Software v8.0
PIX-SW-UPGRADE=	PIX One-Time Software Upgrade for Non-SMARTnet	ASA-SW-UPGRADE=	ASA 5500 Series One-Time Software Upgrade for Non-SMARTnet
PIX-VPN-CLNT-K9	Cisco VPN Client Software (Windows, Solaris, Linux, Mac)	ASA-VPN-CLNT-K9	Cisco VPN Client Software (Windows, Solaris, Linux, Mac)
PIX-VPN-CLNT-NONE	No Cisco VPN Client Software Included	ASA-VPN-CLNT-NONE	No Cisco VPN Client Software Included

Product Migration Options

Cisco PIX Security Appliance customers running version 8.0 software are encouraged to migrate to Cisco ASA 5500 Adaptive Security Appliances running version 8.0 software. A feature comparison summary is shown below. For more information, please review the release notes for each specific software release.

Table 3. Product Comparisons

Feature	Cisco PIX Security Appliance Software v8.0	Cisco ASA 5500 Adaptive Security Appliance Software v8.0
Encrypted SIP/SCCP Voice/Video Inspection via TLS Proxy	Not Supported	Supported
Enhanced Service Object Groups that Support TCP, UDP, and ICMP	Supported	Supported
Live ACL Hitcounts	Supported	Supported
EIGRP Dynamic Routing	Supported	Supported
Redundant Interface Support	Supported	Supported
Failover Pair AutoUpdate Support	Supported	Supported
Transparent Firewall NAT Support	Supported	Supported
IPv6 Support for SIP	Supported	Supported
SSL VPN: Clientless SSL VPN Portal with Customizable Group/User Homepages	Not Supported	Supported
SSL VPN: Integrated Endpoint Posture Assessment	Not Supported	Supported
SSL VPN: Dynamic Access Policies	Not Supported	Supported
SSL VPN: Single Sign On (SSO) Support via SAML Integration	Not Supported	Supported
Virtual IPS Sensor Support	Not Supported	Supported

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to

<http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

Customers may be able to continue to purchase the Cisco PIX Security Appliance Software v8.0 through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to <http://www.cisco.com/go/eos>.

For More Information

For more information about the Cisco ASA 5500 Adaptive Security Appliance Software v8.0, visit <http://www.cisco.com/go/asa>, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to http://www.cisco.com/en/US/products/prod_end_of_life.html.

To subscribe to receive end-of-life/end-of-sale information, go to <http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>.



Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV
Amsterdam, The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

CCDF, CCENT, Cisco Eos, Cisco StadiumView, the Cisco logo, DCE, and Welcome to the Human Network are trademarks. Changing the Way We Work, Live, Play, and Learn is a service mark and Access Registrar, Altnet, AsyncOS, Bringing the Meeting To You, Catalyst, CCBA, CDR, CCIE, CCIP, CCNA, CCNP, CCSP, CCVP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Collaboration Without Limitation, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Event Center, Fast Step, Follow Me Browsing, FormShare, GigaDrive, HomeLink, Internet Quotient, IOS, iPhone, IQ Experience, the IQ logo, IQ Net, Readiness Scorecard, IQQuick Study, IronPort, the IronPort logo, LightStream, Linksys, MediaTone, MeetingPlace, MBX, NetScout, Networking Academy, Network Registrar, PCNow, PIX, PowerPanels, ProConnect, ScriptShare, SenderBase, SNAF, Smart, Spectrum Expert, StackWise, The Fastest Way to Increase Your Internet Quotient, TransPath, WebEx, and the WebEx logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (080239)