



End-of-Life Notice

End-of-Sale and End-of-Life Announcement for the Cisco BPX 9.2, Cisco IGX 9.2, Cisco MGX 1.1.3x, Cisco MGX 2.x, Cisco Service Expansion Shelf (SES) 1.1.7x, Cisco WAN Manager 10.5, and Cisco Network Modeling Tool 9.3 Software Versions

Cisco Systems® announces the end of life of the Cisco® BPX® 9.2, Cisco IGX 9.2, Cisco MGX® 1.1.3x, Cisco MGX 2.x, SES 1.1.7x, Cisco IGX 9.2, MGX 1.1.3x, Cisco MGX 2.x, SES 1.1.7x, Cisco WAN Manager 10.5, and Cisco Network Modeling Tool 9.3 is July 28, 2004. Customers will continue to receive support from the Cisco Technical Assistance Center (TAC) until July 28, 2009. Table 1 describes the end-of-life milestones, definitions, and dates for the affected software versions.

Customers are encouraged to upgrade to the Cisco BPX 9.3 or 9.4; IGX 9.3 or 9.4, MGX 1.2.20, 3.0, or 4.0; and SES 4.0; Cisco WAN Manager 11 or 12, and Cisco Network Modeling Tool 11 or 12 (dependant on the Cisco WAN Manager software version) to take advantage of enhanced features and bug fixes.

Table 1 End-of-Life Milestones and Dates

Milestone	Definition	Date
End-of-life announcement date	The date the document announces the end of sale and end of life of a product is distributed to the general public.	July 28, 2003
End of sale date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	July 28, 2004
Last shipment date	The last possible date product shipment can be deferred to.	October 28, 2004
End of software maintenance releases date	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	July 28, 2005
End of new service attachment date	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	July 28, 2005
End of service contract renewal date	The last date to extend or renew a service contract for the product. The extension or renewal period cannot extend beyond the last date of support.	July 28, 2008
Last date of support	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	July 28, 2009

Table 2 Product Part Numbers Being Affected by This Announcement

End of Sales Product Part Number	Product Description
BPX-SW-9223	BPX Switch Software Version 9.2.23
BPX-SW-9230	BPX Switch Software Version 9.2.30
BPX-SW-9231	BPX Switch Software Version 9.2.31



Table 2 Product Part Numbers Being Affected by This Announcement

End of Sales Product Part Number	Product Description
BPX-SW-9232	BPX Switch Software Version 9.2.32
BPX-SW-9233	BPX Switch Software Version 9.2.33
BPX-SW-9234	BPX Switch Software Version 9.2.34
BPX-SW-9236	BPX Switch Software Version 9.2.36
BPX-SW-9237	BPX Switch Software Version 9.2.37
BPX-SW-9238	BPX Switch Software Version 9.2.38
BPX-SW-9240	BPX Switch Software Version 9.2.40
BPX-SW-9241	BPX Switch Software Version 9.2.41
BPX-SW-9243	BPX Switch Software Version 9.2.43
IGX-SW-9223	IGX Switch Software Version 9.2.23
IGX-SW-9230	IGX Switch Software Version 9.2.30
IGX-SW-9231	IGX Switch Software Version 9.2.31
IGX-SW-9232	IGX Switch Software Version 9.2.32
IGX-SW-9233	IGX Switch Software Version 9.2.33
IGX-SW-9234	IGX Switch Software Version 9.2.34
IGX-SW-9238	IGX Switch Software Version 9.2.38
IGX-SW-9240	IGX Switch Software Version 9.2.40
IGX-SW-9241	IGX Switch Software Version 9.2.41
MGX8230-SW-1132	MGX8230 System Software Version 1.1.32
MGX8230-SW-1134	MGX8230 System Software Version 1.1.34
MGX8230-SW-1135	MGX8230 System Software Version 1.1.35
MGX8250-SW-1132	MGX8250 System Software Version 1.1.32
MGX8250-SW-1134	MGX8250 System Software Version 1.1.34
MGX8250-SW-1135	MGX8250 System Software Version 1.1.35
MGX8850-SW-1132	MGX8850 System Software Version 1.1.32
MGX8850-SW-1134	MGX8850 System Software Version 1.1.34
MGX8850-SW-1135	MGX8850 System Software Version 1.1.35
SESSW-CNTL-1170	SES Controller Software License Version 1.1.70
SESSW-CNTL-1175	SES Controller Software License Version 1.1.75
MGX8850-SW-2170	MGX8850 System Software Version 2.1.70
MGX8850SW-2170	MGX8850 System Software Version 2.1.70



Table 2 Product Part Numbers Being Affected by This Announcement

End of Sales Product Part Number	Product Description
MGX8850-SW-2170CD=	MGX8850 System Software Spare Version 2.1.70
MGX8850-SW-2175	MGX8850 System Software Version 2.1.75
MGX8850-SW-2175CD=	MGX8850 System Software Spare Version 2.1.75
MGX8850-SW-2176	MGX8850 System Software Version 2.1.76
MGX8850-SW-2176CD=	MGX8850 System Software Spare Version 2.1.76
MGX8850-SW-2180	MGX8850 System Software Version 2.1.80
MGX8850-SW-2180CD=	MGX8850 System Software Spare Version 2.1.80
MGX8850-SW-2181	MGX8850 System Software Version 2.1.81
MGX8850-SW-2181CD=	MGX8850 System Software Spare Version 2.1.81
CWM-CDOC10.05.00	CWM documentation for release 10.5
CWM-S-AT10.05.00	CWM-Service Agent10.5.00(Solaris)
CWM-S-AT10.05.00JU	CWM-Service Agent10.5.00(Solaris)Major Upgrade
CWM-S-AT10.05.00NU	CWM-Service Agent10.5.00(Solaris)Minor Upgrade
CWM-S-AT10.05.10	CWM-Service Agent10.5.10(Solaris)
CWM-S-AT10.05.10JU	CWM-Service Agent10.5.10(Solaris)Major Upgrade
CWM-S-AT10.05.10NU	CWM Service Agent10.5.10(Solaris)Minor/Mtc Upgrade
CWM-S-EN10.05.00	CWM10.5.00 Enterprise Edition(Solaris)
CWM-S-EN10.05.00JU	CWM10.5.00 Enterprise Edition(Solaris)Major Upgrade
CWM-S-EN10.05.00NU	CWM10.5.00 Enterprise Edition(Solaris)Minor Upgrade
CWM-S-EN10.05.10	CWM10.5.10 Enterprise Edition(Solaris)
CWM-S-EN10.05.10JU	CWM10.5.10 Enterprise Edition(Solaris)Major Upgrade
CWM-S-EN10.05.10NU	CWM10.5.10 Enterprise Edition(Solaris)Minor/Mtc Upgrade
CWM-S-SC10.05.00	CWM-Standalone Stats Collector10.5.00(Solaris)
CWM-S-SC10.05.00JU	CWM-Standalone Stats Collector10.5.00(Solaris)Major Upgrade
CWM-S-SC10.05.00NU	CWM-Standalone Stats Collector10.5.00(Solaris)Minor Upgrade
CWM-S-SC10.05.10	CWM-Standalone Stats Collector10.5.10(Solaris)
CWM-S-SC10.05.10JU	CWM-Standalone Stats Collector10.5.10(Solaris)Major Upgrade
CWM-S-SC10.05.10NU	CWM Standalone Stats Collector10.5.10(Solaris)Minor/Mtc Upg
CWM-S-SP10.05.00	CWM10.5.00 Service Provider Edition(Solaris)
CWM-S-SP10.05.00JU	CWM10.5.00 Service Provider Edition(Solaris)Major Upgrade
CWM-S-SP10.05.00NU	CWM10.5.00 Service Provider Edition(Solaris)Minor Upgrade



Table 2 Product Part Numbers Being Affected by This Announcement

End of Sales Product Part Number	Product Description
CWM-S-SP10.05.10	CWM10.5.10 Service Provider Edition(Solaris)
CWM-S-SP10.05.10JU	CWM10.5.10 Service Provider Edition(Solaris)Major Upgrade
CWM-S-SP10.05.10NU	CWM10.5.10 Service Provider Edition(Solaris)Minor/Mtc Upg
WDT-S-IC02.02.00	WANDEST Informix Client R2.2.0 (CWM 10.5.1x, Solaris 2.7)
WDT-S-CT02.02.00	WANDEST Client R2.2.0 (CWM 10.5.1x, Solaris 2.7, 2.8)
WDT-S-SR02.02.00	WANDEST Server R2.2.0 (CWM 10.5.1x, Solaris 2.7)
NM-NMT-MODEXP.93	Cisco WAN Modeling Tools (NMT), supports CWM 10
NM-NMT-MODEXP.93U	Cisco WAN Modeling Tools, Upgrade to release 93
DOC-MODEXP.93=	Cisco WAN Modeling Tools documentation for release 93

Product Migration Options

The Cisco Technology Migration Program is not offered to upgrade the software versions being affected by this product bulletin. The software versions can be downloaded from the Software Center:

<http://www.cisco.com/public/sw-center/index.shtml>.

Please contact your Cisco account manager and/or Cisco Channel Partner for upgrade software version of the Network Modeling Tool.

Additional Information

For more information about Cisco products, please contact your Cisco account manager and/or Cisco Channel Partner.

For more information about the Cisco End-of-Life Policy, go to:

http://www.cisco.com/en/US/products/prod_end_of_life.html



Corporate Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters

Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems, Inc.
Capital Tower
168 Robinson Road
#22-01 to #29-01
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the Cisco Web site at www.cisco.com/go/offices

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992–2003 Cisco Systems, Inc. All rights reserved. BPX, Cisco, Cisco Systems, the Cisco Systems logo, and MGX are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0304R) KW/LW4843 07/03