

CPM Rel 2.1 / 2.2 End of Life



Table of Contents

INTRODUCTION3

LAST SOFTWARE VERSIONS3

PROPOSED IMPLEMENTATION PLAN3

END OF LIFE PRODUCT ID4

Introduction

This product bulletin serves as official notification that the following SW products belonging to the Product Family CISCO ONS 15801 will reach their End of Sales and End Of Life.

- Q3 Agent 1.4.x (Product Family CISCO ONS 15801)
- Q3 Agent 1.5.x (Product Family CISCO ONS 15801)
- CPM 2.1.x (Product Family CISCO ONS 15801)
- CPM 2.2.x (Product Family CISCO ONS 15801)

Last Software Versions

CPM	Q3 Agent	Mediation Device
Rel 2.3	Rel 2.0	Rel 2.3



Proposed Implementation Plan

Major Milestones	Effective Date	Description
Internal Announcement to Sales Force	5 June 01	Notification of plan approval to the team, sales force and distributors
End Of Production - Ensure backlog and service orders are produced	5 June 01	No more CD production in Salem (*)
End of Sales Announcement - Issue Product Bulletin	26 June 01 (MKT issue)	Issue product bulletin
End of Support Announcement	26 June 02 (MKT issue)	Announce that Cisco will no longer support these products
End of Sales - Turn Off Order-ability and Pricing	19 Dec 01	No more Product orderable
Discontinue Contract Renewal	19 June 02	No more contract renewal after the effective date
Last Software Support	19 June 02	Date of last SW support
Product Obsolete	19 June 02	-

(*) CD Copies already available for duplication in SALEM for the products still orderable.



End Of Life Product ID

Cisco Product Name	Cisco Product Description
EI-QD-2-INT *	EI-QD-2-INT *
EI-QSST *	EI-QSST *
CMP-Q3A-1.4.1 *	Q3 Agent (1.4) - ONS 15801 Rel 1.1 *
CMP-Q3A-1.4.1= *	Q3 Agent (1.4) -ONS 15801 Rel 1.1 *
CMP-Q3A-1.5.0 *	Q3 Agent for CMP-W-Release 1.5.0 *
CMP-Q3A-1.5.0= *	Q3 Agent for CMP-W-Release 1.5.0 *
CMP-Q3A-1.5.1	Q3 Agent (1.5) - ONS 15801 Rel 1.2
CMP-Q3A-1.5.1=	Q3 Agent (1.5) - ONS 15801 Rel 1.2
SW-CPM-2.1.1-AB *	Cisco Photonics Manager - Release 2.1.1 - AB *
SW-CPM-2.1.1-AB= *	Cisco Photonics Manager (WaveIQ)SW kit-HP platf. - Vers. 2.1 *
W-IQ-HP-2.1.1-AB *	Cisco Photonics Manager (HP) - Rel 2.1.1_AB *
SW-CPM-2.2-SUN	Cisco Photonics Manager -SUN Version - Release 2.2
SW-CPM-2.2-SUN=	Cisco Photonics Manager - SUN Version - Release 2.2
SW-CPM-RMT-GUI-22= *	CPM 2.2 Remote GUI *
SW-CPM-2.2.1	Cisco Photonics Manager - HP Version - Release 2.2
SW-CPM-2.2.1=	Cisco Photonics Manager - HP Version - Release 2.2
SW-MD-CPM-2.2	Mediation Device for CPM - HP & SUN Version - Release 2.2

***These products are already non orderable in ORACLE.**

**Corporate Headquarters**

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters

Cisco Systems Europe
11, Rue Camille Desmoulins
92782 Issy Les Moulineaux Cedex 9
France
www.cisco.com
Tel: 33 1 58 04 60 00
Fax: 33 1 58 04 61 00

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems Australia, Pty., Ltd
Level 17, 99 Walker Street
North Sydney
NSW 2059 Australia
www.cisco.com
Tel: +61 2 8448 7100
Fax: +61 2 9957 4350

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the Cisco.com Web site at www.cisco.com/go/offices.

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Czech Republic • Denmark • Dubai, UAE Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992–2001 Cisco Systems, Inc. All rights reserved. Important Notices and Privacy Statement. Printed in the USA. AccessPath, AtmDirector, Browse with Me, CCDA, CCDE, CCDP, CCIE, CCNA, CCNP, CCSI, CD-PAC, *CiscoLink*, the Cisco NetWorks logo, the Cisco Powered Network logo, Cisco Systems Networking Academy, the Cisco Systems Networking Academy logo, Discover All That's Possible, Fast Step, Follow Me Browsing, FormShare, FrameShare, GigaStack, IGX, Internet Quotient, IP/VC, iQ Breakthrough, iQ Expertise, iQ FastTrack, the iQ Logo, iQ Net Readiness Scorecard, MGX, the Networkers logo, Packet, PIX, RateMUX, ScriptBuilder, ScriptShare, SlideCast, SMARTnet, TransPath, Voice LAN, Wavelength Router, WebViewer are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, Empowering the Internet Generation, are service marks of Cisco Systems, Inc.; and Aironet, ASIST, BPX, Catalyst, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, the Cisco IOS logo, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Enterprise/Solver, EtherChannel, EtherSwitch, FastHub, FastSwitch, IOS, IP/TV, LightStream, MICA, Network Registrar, Post-Routing, Pre-Routing, Registrar, StrataView Plus, Stratum, SwitchProbe, TeleRouter, and VCO are registered trademarks of Cisco Systems, Inc. or its affiliates in the U.S. and certain other countries.

All other brands, names, or trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0101R)