



Cisco 12000 Series One-Port OC-192c/STM-64c POS/SDH Line Card with SR2 Optics End-of-Life Announcement

Cisco Systems is announcing the end of life (EOL) for the Cisco 12000 Series One-Port OC-192 Packet-over-SONET (POS) Line Card with the part number OC192/POS-SR2-SC. This line card was manufactured as a temporary replacement to the OC192/POS-SR-SC, which could not be shipped because of optics component issues. The Short Reach (SR) modules are now qualified and are in production. Production of the SR2 line card has ceased.

The part number OC192/POS-SR2-SC should be replaced by the part number OC192E/POS-SR-SC. Although the SR2 module provides 20 km of reach, most customers use this card for intra-point of presence (POP) applications, which require less than 2 km of reach.

Table 1 lists the product and part number that is no longer orderable. Table 2 lists the newer line card and associated part number that is available now and should be used in place of the product in Table 1.

Table 1 EOL Line Card and Associated Part Number

Line Card	Part Number
Cisco One-Port OC-192c/STM-64c POS Line Card 1310 nm SR2, SC	OC192/POS-SR2-SC

Table 2 Improved Line Cards and Associated Part Numbers Available Now

Line Card	Part Number	Minimum Cisco IOS [®] Software Release Required
Cisco 12000 Series One-Port OC-192c/STM-64c POS/Synchronous Digital Hierarchy (SDH) Enhanced Services Line Card, 1310 nm SR, SC	OC192E/POS-SR-SC	12.0(21)S/ST



Key Dates

Table 3 lists the key dates associated with this product bulletin.

Table 3 Key Dates for EOL Products

Milestone	Definitions	Date
End of life bulletin	This document is the EOL bulletin.	March 1, 2001
End of orderability and removal from Cisco price list	The product is no longer orderable and is no longer on the Cisco price list.	March 15, 2001
End of hardware support	Cisco will no longer provide hardware fixes to newly discovered hardware bugs.	April 1, 2004
End of software support	Cisco will no longer provide software fixes to newly discovered software bugs.	April 1, 2004
End of one-year service contract renewals	One-year service contracts for this product will not be renewed after this date.	April 1, 2004
End of six-month service contract renewals	Six-month service contracts for this product will not be renewed after this date.	October 1, 2004
End of support (product obsolescence)	Cisco will no longer support these products and they are considered obsolete. Cisco Customer Advocacy Service Logistics will no longer carry inventory for customer return material authorizations (RMAs). The Cisco Technical Assistance Center (TAC) will no longer support these products.	April 1, 2005

If you have questions or need more information, contact your Cisco account team.



Corporate Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters
Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters
Cisco Systems, Inc.
Capital Tower
168 Robinson Road
#22-01 to #29-01
Singapore 068912
www.cisco.com
Tel: +65 317 7777
Fax: +65 317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the
Cisco Web site at www.cisco.com/go/offices

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland
Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland
Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden
Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992–2002, Cisco Systems, Inc. All rights reserved. Cisco, Cisco IOS, Cisco Systems, and the Cisco Systems logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company.
(0206R) LW3427 0702