

Catalyst 2820 ATM Modules End-of-Life

Overview

Cisco is announcing the End-of-Life (EOL) of the asynchronous transfer mode (ATM) modules presently supported on the Catalyst 2820 platform.

Product Obsolescence Plan

- Last orderable date: August 11, 2000
- Last ship date: September 11, 2000
- Last support date: August 11, 2005

Affected Model Numbers and Replacement Product Summary

The most appropriate replacement solution would involve replacement of the Catalyst 2820 chassis with a Catalyst 2924M XL switch.

EOL Model Number	Replacement Product	Replacement Model Number
WS-X2851 ATM 155 UTP module	ATM 155 UTP module for Catalyst 2900 XL	WS-X2951
WS-X2861 ATM 155 MM Fiber module	ATM 155 MM Fiber module for Catalyst 2900 XL	WS-X2961
WS-X2871 ATM 155 SM Fiber (medium range) module	ATM 155 SM Fiber (medium range) module for Catalyst 2900 XL	WS-X2971
WS-X2872 ATM 155 SM Fiber (long range) module	ATM 155 SM Fiber (long range) module for Catalyst 2900 XL	WS-X2972

Chassis Replacement Information

Current Product Model Number	Replacement Product	Replacement Model Number
WS-C2820-EN	Catalyst 2924M XL switch	WS-C2924M-XL-EN
WS-C2820-A	Catalyst 2924M XL switch	WS-C2924M-XL-EN

The Cisco Catalyst® 2924M XL 10/100 autosensing Fast Ethernet switch combines outstanding performance, ease of use, and integrated Cisco IOS® software. The Catalyst 2924M XL is a flexible, scalable, and affordable solution, ideal for aggregating Ethernet and Fast Ethernet workgroups and delivering dedicated 10 or 100 Mbps connectivity for individual users and servers with high-speed uplink modules, including Gigabit Ethernet and ATM, to connect to servers and LAN backbones.

Customers can trade in current Catalyst 2820 products for Catalyst 2924M XL switches under the technology migration plan. For detailed trade-in information: http://www.cisco.com/offer/tic/TMP_PA.html

For More Information

Srini Chandrasekharan (srchandr@cisco.com)



Corporate Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
<http://www.cisco.com>
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters
Cisco Systems Europe
11, Rue Camille Desmoulins
92782 Issy Les Moulineaux
Cedex 9
France
<http://www-europe.cisco.com>
Tel: 33 1 58 04 60 00
Fax: 33 1 58 04 61 00

Americas Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
<http://www.cisco.com>
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters
Cisco Systems Australia Pty., Ltd.
Level 17, 99 Walker Street
North Sydney
NSW 2059 Australia
Tel: 61 2 8448 7100
Fax: 61 2 9957 4350

Cisco Systems has more than 200 offices in the following countries. Addresses, phone numbers, and fax numbers are listed on the
Cisco Connection Online Web site at <http://www.cisco.com/go/offices>.

Argentina • Australia • Austria • Belgium • Brazil • Canada • Chile • China • Colombia • Costa Rica • Croatia • Czech Republic • Denmark • Dubai, UAE
Finland • France • Germany • Greece • Hong Kong • Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia
Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Singapore
Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela