



End of Life for the Cisco Content Engine Storage Array 12

Overview

Cisco Systems announces the end of life (EOL) for the Cisco Content Engine Storage Array 12 (part number SA12-SHF-12DISK-AC). This product is no longer orderable effective immediately.

Note that the Cisco Storage Array 6 (product number SA6-SHF-6DISK-AC) is still available for Cisco content engines and is not affected by this EOL announcement.

Table 1 EOL Product Information

Part Number	EOS Date	EOL Date	Replacement Part
SA12-SHF-12DISK-AC	May 23, 2002	May 2007	None

Table 2 Models Covered by This EOL Announcement

Part Number	Product Description
SA12-SHF-12DISK-AC	Storage Array 12, (12) 18 GB disks, AC
SA12-OPT-AC	Storage Array 12 option, (12) 18 GB disks, AC
SA12-SHF-AC=	Complete disk shelf (no disks) for Storage Array 12, spare
SA12-DISK-18GB=	(1) 18 GB, SCSI drive for Storage Array 12, spare
SA12-COOLING=	Cooling module for Storage Array 12, spare
SA12-PWR-AC=	AC power supply for Storage Array 12, spare

Table 3 EOL Milestones for Cisco Storage Array 12

End of production	May 2002
End of support	To be announced in May 2005
Contract renewal	No contract renewals accepted as of September 2006
Date of obsolescence	May 2007

For More Information

For more information on Cisco storage array products for the Cisco Content Engine series, visit:

<http://www.cisco.com/warp/public/cc/pd/cxsr/ces/prodlit/index.shtml>



Corporate Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters
Cisco Systems Europe
11, Rue Camille Desmoulins
92782 Issy-les-Moulineaux
Cedex 9
France
www-europe.cisco.com
Tel: 33 1 58 04 60 00
Fax: 33 1 58 04 61 00

Americas Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters
Cisco Systems, Inc.
Capital Tower
168 Robinson Road
#22-01 to #29-01
Singapore 068912
www.cisco.com
Tel: 65 317 7777
Fax: 65 317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the
Cisco Web site at www.cisco.com/go/offices

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland
Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland
Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden
Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2002, Cisco Systems, Inc. All rights reserved. CCIP, the Cisco Powered Network mark, the Cisco Systems Verified logo, Cisco Unity, Follow Me Browsing, FormShare, Internet Quotient, iQ Breakthrough, iQ Expertise, iQ FastTrack, the iQ logo, iQ Net Readiness Scorecard, Networking Academy, ScriptShare, SMARTnet, TransPath, and Voice LAN are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, Discover All That's Possible, The Fastest Way to Increase Your Internet Quotient, and iQuick Study are service marks of Cisco Systems, Inc.; and Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, the Cisco IOS logo, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherSwitch, Fast Step, GigaStack, IOS, IP/TV, LightStream, MGX, MICA, the Networkers logo, Network Registrar, Packet, PIX, Post-Routing, Pre-Routing, RateMUX, Registrar, SlideCast, StrataView Plus, Stratm, SwitchProbe, TeleRouter, and VCO are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company.
(0203R)

Printed in the USA