

Cisco IOS™ Software Release 12.0(4)XM

Introduction

This Product Bulletin describes the new features introduced in Cisco IOS(TM) software release 12.0(4)XM.

New Platform

Cisco IOS release 12.0(4)XM is a short lived Early Deployment (ED) also known as X release. IOS X releases do not provide maintenance trail. Capabilities and functionality of X releases are ported to subsequent IOS consolidated release. This release is particularly focused on delivering the Cisco 805 Serial Routers. . It is recommended that ED release of software be first utilized in a test environment before full production network deployment.

Functionality and platform support delivered with this X release will be immediately incorporated into the consolidate release 12.0T starting with 12.0(6)T. As such, 12.0(6)T or later version of 12.0T is the logical migration path for IOS release 12.0(4)XM. For more information about the Cisco IOS software release process, please see Product Bulletin #537 .

Detailed Information

For more detailed information about the Cisco 805 Serial Router being delivered in 12.0(4)XM, please go to the following site:

<http://www.cisco.com/warp/customer/cc/cisco/mkt/access/800/index.shtml>

Features Sets, Images and Memory Requirements

Software Product Description	Image	Product Code	DRAM Required	Flash Required
Cisco 805 IOS IP	c805-y6-mw	S805C-12.0.4XM	8MB	4MB
Cisco 805 IOS IP Plus	c805-sy6-mw	S805CP-12.0.4XM	8MB	4MB
Cisco 805 IOS IP/IPX Plus	c805-nsy6-mw	S805BP-12.0.4XM	8MB	4MB
Cisco 805 IOS IP/FW	c805-oy6-mw	S805CH-12.0.4XM	8MB	4MB



Corporate Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
<http://www.cisco.com>
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters
Cisco Systems Europe s.a.r.l.
Parc Evolic, Batiment L1/L2
16 Avenue du Quebec
Villebon, BP 706
91961 Courtaboeuf Cedex
France
<http://www-europe.cisco.com>
Tel: 33 1 69 18 61 00
Fax: 33 1 69 28 83 26

Americas
Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
<http://www.cisco.com>
Tel: 408 526-7660
Fax: 408 527-0883

Asia Headquarters
Nihon Cisco Systems K.K.
Fuji Building, 9th Floor
3-2-3 Marunouchi
Chiyoda-ku, Tokyo 100
Japan
<http://www.cisco.com>
Tel: 81 3 5219 6250
Fax: 81 3 5219 6001

Cisco Systems has more than 200 offices in the following countries. Addresses, phone numbers, and fax numbers are listed on the

Cisco Connection Online Web site at <http://www.cisco.com/offices>.

Argentina • Australia • Austria • Belgium • Brazil • Canada • Chile • China • Colombia • Costa Rica • Croatia • Czech Republic • Denmark • Dubai, UAE
Finland • France • Germany • Greece • Hong Kong • Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia
Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Singapore
Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela