

# Cisco IOS™ 1600 Series 11.1 to 11.3 Upgrade Path

For Customers With SMARTnet Contracts

**Table 6:** 1600 Upgrade Path from 11.1 to 11.3 for Increased Functionality

		From: 11.1					
		IP	IP Plus	IP/IPX	IP/IPX/Plus	IP/AT	IP/AT Plus
To: 11.3	IP	—	—	—	—	—	—
	IP Plus	FL160-P=	—	—	—	—	—
	IP Plus 40	FL160-W=	FL160-W=	—	—	—	—
	IP Plus 56	FL160-Y=	FL160-Y=	—	—	—	—
	IP/IPX	FL160-C-B=	—	—	—	—	—
	IP/IPX/Plus	FL160-C-B= and FL160-P=	FL160-C-B=	FL160-P=	—	—	—
	IP/IPX/AT/IBM	FL160-C-AS=	FL160-C-AS=	FL160-B-AS=	FL160-B-AS=	FL160-E-AS=	FL160-A-AS=
	IP/IPX/AT/IBM Plus	FL160-C-AS= and FL160-P=	FL160-C-AS=	FL160-B-AS= and FL160-P=	FL160-B-AS=	FL160-E-AS= and FL160-P=	FL160-E-AS=
	IP/IPX/AT/IBM Plus 40	FL160-C-AS= and FL160-W=	FL160-C-AS= and FL160-P-W=	FL160-B-AS= and FL160-W=	FL160-B-AS= and FL160-P-W=	FL160-E-AS= and FL160-W=	FL160-E-AS= and FL160-P-W=
	IP/IPX/AT/IBM Plus 56	FL160-C-AS= and FL160-Y=	FL160-C-AS= and FL160-P-Y=	FL160-B-AS= and FL160-Y=	FL160-B-AS= and FL160-P-Y=	FL160-E-AS= and FL160-Y=	FL160-E-AS= and FL160-P-Y=

**Notes:**

- “Plus” feature sets include OSPF, IP MULTICAST, NHRP, NTP, NAT, RSVP, and Frame-Relay-SVC. AT image also include SMRP, ATIP, and AURP. IPX images also include NLSP and NHRP.

**Corporate Headquarters**

Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
<http://www.cisco.com>  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 526-4100

**European Headquarters**

Cisco Systems Europe s.a.r.l.  
Parc Evolic, Batiment L1/L2  
16 Avenue du Quebec  
Villebon, BP 706  
91961 Courtaboeuf Cedex  
France  
<http://www-europe.cisco.com>  
Tel: 33 1 6918 61 00  
Fax: 33 1 6928 83 26

**Americas**

**Headquarters**  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
<http://www.cisco.com>  
Tel: 408 526-7660  
Fax: 408 527-0883

**Asia Headquarters**

Nihon Cisco Systems K.K.  
Fuji Building, 9th Floor  
3-2-3 Marunouchi  
Chiyoda-ku, Tokyo 100  
Japan  
<http://www.cisco.com>  
Tel: 81 3 5219 6250  
Fax: 81 3 5219 6001

**Cisco Systems has more than 200 offices in the following countries. Addresses, phone numbers, and fax numbers are listed on the Cisco Connection Online Web site at <http://www.cisco.com>.**

Argentina • Australia • Austria • Belgium • Brazil • Canada • Chile • China (PRC) • Colombia • Costa Rica • Czech Republic • Denmark • England • France • Germany • Greece • Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Russia • Saudi Arabia • Scotland • Singapore • South Africa • Spain • Sweden • Switzerland • Taiwan, ROC • Thailand • Turkey • United Arab Emirates • United States • Venezuela

Copyright © 1997 Cisco Systems, Inc. All rights reserved. Printed in USA. AccessPath, AtmDirector, Cache Director System, CD-PAC, Cisco IOS, the Cisco IOS logo, CiscoLink, the Cisco Powered Network logo, ClickStart, ControlStream, Fast Step, FragmentFree, IGX, JumpStart, LAN<sup>2</sup>LAN Enterprise, LAN<sup>2</sup>LAN Remote Office, MICA, NetBeyond, NetFlow, Netsys Technologies, Packet, PIX, Point and Click Internetworking, RouteStream, SMARTnet, StrataSphere, StrataSphere BILLder, StrataSphere Connection Manager, StrataSphere Modeler, StrataSphere Optimizer, Stratum, StreamView, SwitchProbe, The Cell, TokenSwitch, TrafficDirector, VirtualStream, VlanDirector, Workgroup Director, Workgroup Stack, and XCI are trademarks; The Network Works. No Excuses. is a service mark; and BPX, Catalyst, Cisco, Cisco Systems, the Cisco Systems logo, EtherChannel, FastHub, FastPacket, ForeSight, IPX, LightStream, OptiClass, Phase/IP, StrataCom, and StrataView Plus are registered trademarks of Cisco Systems, Inc. in the U.S. and certain other countries. All other trademarks mentioned in this document are the property of their respective owners. 978R