

Cisco Unified IP Conference Station 7936

A.

Q. How does the Cisco Unified IP Conference Station 7936 accommodate larger room size?

A. The Cisco Unified IP Conference Station 7936 has two phone jacks that accommodate the addition of external microphones, also called “mics.” Cisco has also improved the quality and capacity of the sound, which has resulted in enhanced experience for the user.

Q. What room dimensions can the Cisco Unified IP Conference Station 7936 handle?

A. The Cisco Unified IP Conference Station 7936 can pick up and project voices in a room approximately 20 feet by 30 feet, depending on the acoustics in the room. The better the room acoustics are the better the performance is. Carpets, drapes, and other interior furnishings can enhance or detract from the performance.

Q. Do the microphones come with the Cisco Unified IP Conference Station 7936?

Q. The Cisco Unified IP Conference Station 7936 has three microphones in the base unit, which is like a star with only three points. Each point houses a microphone. There is also an optional microphone kit includes two microphones with six-foot cords. This means you can have a microphone every six feet spanning twelve feet of the room. Each microphone has a mute button that can mute all microphones.

Q. Why are external microphones an option?

A. The Cisco Unified IP Conference Station 7936 can operate without the optional microphones like the Cisco Unified IP Conference Station 7935. This allows you to

use the conferencing system in small to midsize private offices and conference rooms. If you need additional coverage, you can add the microphone kit initially or at a later time.

Q. In what other ways has Cisco upgraded the Cisco Unified IP Conference Station 7936 from the Cisco Unified IP Conference Station 7935?

A. Cisco has redesigned the speaker to improve frequency response. Not everyone will notice the improvement, but it generally improves the audio from the speaker. The LCD display now includes backlighting, which helps the meeting organizer keep track of participants if the call is taking place in a darkened conference room. The user can adjust the font size of the LCD display for easier reading.

Q. Is the Cisco Unified IP Conference Station 7936 more expensive?

A. The Cisco Unified IP Conference Station 7936 basic unit and user license costs the same as the Cisco Unified IP Conference Station 7935, and includes the required power kit. The optional microphone kit, which the user can purchase at any time to expand the Cisco Unified IP Conference Station 7936 room coverage, costs extra.

Q. What are the specifications and cost of the power kit?

A. The power kits for the Cisco Unified IP Conference Station 7936 and the Cisco Unified IP Conference Station 7935 are the same. The Cisco Unified IP Conference Station 7936 includes the power cube, the power integration

module, and LAN cords. The power cube AC cord and country-specific cord are optional. You can choose a cord choice for your country or region when you order. The power kit, CP-7936-PWR-KIT= is the part number for the power kit spare and works on both the Cisco Unified IP Conference Station 7935 and Cisco Unified IP Conference Station 7936.

A one-year warranty is standard, and Cisco SMARTnet® services are available.



Corporate Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters

Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems, Inc.
Capital Tower
168 Robinson Road
#22-01 to #29-01
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the Cisco Web site at www.cisco.com/go/offices

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992–2004 Cisco Systems, Inc. All rights reserved. Cisco, Cisco Systems, the Cisco Systems logo, and SMARTnet are registered trademarks or trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0304R) ETMG 203246—CM 02.04