

## END-OF-SALE AND END-OF-LIFE ANNOUNCEMENT FOR THE CISCO ONS 15454 BUNDLES COMMON-KIT AND 15454-COMMON2-KIT

Cisco Systems® announces the end of life of the Cisco® ONS 15454 Bundles COMMON-KIT and COMMON2-KIT. The last day to order the Cisco ONS 15454 Bundles COMMON-KIT and COMMON2-KIT is June 15, 2004. This announcement pertains to the specified bundle part numbers only and not to any other part of the Cisco ONS 15454 platform. Table 1 describes the end-of-life milestones, definitions, and dates for the Cisco ONS 15454 Bundles COMMON-KIT and COMMON2-KIT. Table 2 lists the product numbers affected by this announcement.

Customers are encouraged to migrate to the newer Cisco ONS 15454 Bundles 2GCOM1-KIT and 2GCOM2-KIT, which include the most advanced processor card, Timing, Communications and Control v.2 (TCC2). Information about the TCC2 processor card can be found at: [http://cisco.com/en/US/products/hw/optical/ps2006/products\\_data\\_sheet09186a0080154431.html](http://cisco.com/en/US/products/hw/optical/ps2006/products_data_sheet09186a0080154431.html)

Table 3 provides relevant information for migrating from the Cisco ONS 15454 Bundles COMMON-KIT and COMMON2-KIT to the Cisco ONS 15454 Bundles 2GCOM1-KIT and 2GCOM2-KIT.

**Table 1** End-of-Life Milestones and Dates for the Cisco ONS 15454 COMMON-KIT and COMMON2-KIT

Milestone	Definition	Date
End-of-life announcement date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	March 15, 2004
End-of-sale date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	June 15, 2004
Last shipment date	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead-time.	September 15, 2004
End of software maintenance releases date	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	Support provided as part of the bundle's individual component standard services and support contracts for the Cisco ONS 15454
Last date of support	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	Support provided as part of the bundle's individual component standard services and support contracts for the Cisco ONS 15454

**Table 2** Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description
15454-COMMON-KIT	Cisco ONS 15454 bundle, including two 15454-XC-VT and two 15454-TCC+
15454-COMMON2-KIT	Cisco ONS 15454 bundle, including two 15454-XC-VT, two 15454-TCC+ and one 15454-FTA3-T

### PRODUCT MIGRATION OPTIONS

The recommended replacement for the Cisco bundles affected by this end-of-life announcement is outlined in Table 3. The new Cisco ONS 15454 bundles include the latest processor card, model 15454-TCC2.

**Table 3** Product Comparisons

	End-of-Life Products	Replacement Product
<b>Part Number</b>	Cisco ONS 15454 Bundle 15454-COMMON-KIT	Cisco ONS 15454 Bundle 15454-2GCOM1-KIT
Bundle Includes	Two 15454-XC-VT and two 15454-TCC+	Two 15454-XC-VT and two 15454-TCC2
<b>Part Number</b>	Cisco ONS 15454 Bundle 15454-COMMON2-KIT	Cisco ONS 15454 Bundle 15454-2GCOM2-KIT
Bundle Includes	Two 15454-XC-VT, two 15454-TCC+, and one 15454-FTA3-T	Two 15454-XC-VT, two 15454-TCC2, and one 15454-FTA3-T

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

### ADDITIONAL INFORMATION

For more information about Cisco products, please contact your Cisco account manager and/or Cisco Channel Partner.

For more information about the Cisco End-of-Life Policy, go to:

[http://www.cisco.com/en/US/products/prod\\_end\\_of\\_life.html](http://www.cisco.com/en/US/products/prod_end_of_life.html)

To subscribe to receive EOL/EOS information please go to:

<http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>



Corporate Headquarters  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 526-4100

European Headquarters  
Cisco Systems International BV  
Haarlerbergpark  
Haarlerbergweg 13-19  
1101 CH Amsterdam  
The Netherlands  
www-europe.cisco.com  
Tel: 31 0 20 357 1000  
Fax: 31 0 20 357 1100

Americas Headquarters  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-7660  
Fax: 408 527-0883

Asia Pacific Headquarters  
Cisco Systems, Inc.  
168 Robinson Road  
#28-01 Capital Tower  
Singapore 068912  
www.cisco.com  
Tel: +65 6317 7777  
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the  
**Cisco Web site at [www.cisco.com/go/offices](http://www.cisco.com/go/offices)**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Cyprus  
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland  
Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland  
Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden  
Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992–2004 Cisco Systems, Inc. All rights reserved. CCIP, CCSP, the Cisco Arrow logo, the Cisco *Powered* Network mark, Cisco Unity, Follow Me Browsing, FormShare, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, the Cisco IOS logo, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherSwitch, Fast Step, GigaStack, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MGX, MICA, the Networkers logo, Networking Academy, Network Registrar, *Packet*, PIX, Post-Routing, Pre-Routing, RateMUX, Registrar, ScriptShare, SlideCast, SMARTnet, StrataView Plus, Stratm, SwitchProbe, TeleRouter, The Fastest Way to Increase Your Internet Quotient, TransPath, and VCO are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company.  
(0402R) MH/KC/LW5736 3/04