

8FE-FX-SC(=)

8FE-TX-RJ45(=)

End-of-Life Bulletin

On February 1, 2001, the eight-port Fast Ethernet line cards with part numbers 8FE-FX-SC(=) and 8FE-TX-RJ45(=) will no longer be offered by Cisco Systems. These products are being superseded by the 8FE-FX-SC-B(=) and 8FE-TX-RJ45-B(=) part numbers, which have identical functionality. The 8FE-FX-SC-B(=) and 8FE-TX-RJ45-B(=) versions of the eight-port Fast Ethernet line cards are orderable now. The new part numbers have Error-Correcting Code (ECC); the memory options will be the same as those of the original part numbers. The new eight-port Fast Ethernet line cards require a minimum Cisco IOS® version of 12.0(10)S or higher or 11.2(19)GS4 or higher. List price for the replacement line cards is \$31,000 (U.S.) for 8FE-FX-SC-B(=) and \$29,500 (U.S.) for 8FE-TX-RJ45-B(=).

Refer to the table below for important dates:

Milestone	Date
End-of-Life Announcement	8/1/00
End of Sales	2/1/01
End of Contract Renewals	10/31/04
End of Support (obsolescence)	12/1/05

End-of-Life Announcement

This document is the End-of-Life announcement.

End of Sales

This product will no longer be orderable after February 1, 2001. All last-time-buy orders by customers must be received on or before this date.

End-of-Contract Renewals

Service contracts on these products will not be renewed after October 31, 2004.

End of Support

These products will no longer be supported by Cisco after December 1, 2005.

For more information on Cisco 12000 Series platform, please visit <http://www.cisco.com/warp/customer/cc/pd/rt/12000/index.shtml>

If you have any further questions please contact your local sales team.



Corporate Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters
Cisco Systems Europe
11, Rue Camille Desmoulins
92782 Issy Les Moulineaux
Cedex 9
France
www.cisco.com
Tel: 33 1 58 04 60 00
Fax: 33 1 58 04 61 00

Americas
Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific
Headquarters
Cisco Systems Australia, Pty., Ltd
Level 17, 99 Walker Street
North Sydney NSW 2059
Australia
www.cisco.com
Tel: +61 2 8448 7100
Fax: +61 2 9957 4350

Cisco Systems has more than 190 offices in the following countries. Addresses, phone numbers, and fax numbers are listed on the

Cisco.com Web site at www.cisco.com/go/offices.

Argentina • Australia • Austria • Belgium • Brazil • Canada • Chile • China • Colombia • Costa Rica • Croatia • Czech Republic • Denmark • Dubai, UAE
Finland • France • Germany • Greece • Hong Kong • Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia
Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Singapore
Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela

Copyright © 2000, Cisco Systems, Inc. All rights reserved. Printed in the USA. Cisco, Cisco IOS, Cisco Systems, and the Cisco Systems logo are registered trademarks of Cisco Systems, Inc. or its affiliates in the U.S. and certain other countries. All other trademarks mentioned in this document are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0007R) 8/00 LW