



Limited Cisco IOS Software Support for Cisco 1400 Series Routers

Fewer software feature sets will be supported in Cisco IOS Software Release 12.3 mainline, and no feature sets will be supported in release 12.3T or later releases.

The Cisco 1400 Series routers have entered the end-of-life (EOL) cycle and can no longer be ordered. As such, there is less need to provide newer features and support to all Cisco IOS® Software feature sets created for the Cisco 1400 Series routers.

In accordance with standard Cisco support policy, the number of new IOS Software feature sets supported and available for download via Cisco.com will be reduced beginning with IOS Software Release 12.3 mainline. As of the 12.3T release, no new feature sets for the Cisco 1400 Series routers will be supported or available.

IOS Software Release 12.3 Mainline Availability

Cisco 1400 Series Feature Set	IOS Software 12.3 Mainline Support	Migration Path
IOS IP	Yes	N/A
IOS IP/FW PLUS IPSEC 56	Yes	N/A
IOS IP/IPX/FW PLUS	Yes	N/A
IOS IP PLUS	No	IOS IP/IPX/FW PLUS
IOS IP/IPX PLUS	No	IOS IP/IPX/FW PLUS
IOS IP/IPX	No	IOS IP/IPX/FW PLUS

IOS Software Release 12.3T Availability

Cisco 1400 Series Feature Set	IOS Software 12.3T Support	Migration Path
IOS IP	No	N/A
IOS IP/FW PLUS IPSEC 56	No	N/A
IOS IP/IPX/FW PLUS	No	N/A
IOS IP PLUS	No	N/A
IOS IP/IPX PLUS	No	N/A
IOS IP/IPX	No	N/A

Assistance

For questions concerning the Cisco 1400 Series routers, please contact:

Subbu Mahadevan, smahadev@cisco.com



Corporate Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters
Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters
Cisco Systems, Inc.
Capital Tower
168 Robinson Road
#22-01 to #29-01
Singapore 068912
www.cisco.com
Tel: +65 317 7777
Fax: +65 317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the
Cisco Web site at www.cisco.com/go/offices

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland
Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland
Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden
Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992-2002, Cisco Systems, Inc. All rights reserved. Cisco, Cisco IOS, Cisco Systems, and the Cisco Systems logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company.
(0208R) N2/LW3910 11/02