



# Cisco 1600R Series Routers to Offer Limited Cisco IOS Support

**Fewer Cisco IOS features sets to be supported in Version 12.3 Mainline; no Cisco IOS feature sets to be supported in Version 12.3T or later releases.**

The end of sale (EOS) for the Cisco 1600R Series routers will be effective in February 2003. Therefore, the need to provide newer features and support all Cisco IOS® feature sets created for the Cisco 1600R Series routers is reduced.

In accordance with standard Cisco support policy, the number of new Cisco IOS 1600R Series Router feature sets supported and available for purchase via price lists and download via Cisco.com will be reduced beginning with Cisco IOS Release 12.3 Mainline. As of Cisco IOS Release 12.3T, no new feature sets for the Cisco 1600R Series routers will be supported, nor will they be available (refer to Tables 1 and 2 for availability information).

**Table 1** Cisco IOS 12.3 Mainline Availability

Cisco 1600R Series Feature Set	Cisco IOS Software 12.3 Mainline Support	Migration Path
Cisco IOS IP	Yes	—
Cisco IOS IP PLUS	Yes	—
Cisco IOS IP/IPX/FW/PLUS	Yes	—
Cisco IOS IP/FW/PLUS/IPSEC 56	Yes	—
Cisco IOS IP/IPX/AT/IBM/PLUS	Yes	—
Cisco IOS IP/IPX/AT/IBM/FW/PLUS/IPSEC 56	Yes	—
Cisco IOS IP PLUS/IPSEC 56	No	Cisco IOS IP/FW/PLUS/IPSEC 56
Cisco IOS IP/FW	No	Cisco IOS IP/FW/PLUS/IPSEC 56
Cisco IOS IP/IPX/AT/IBM	No	Cisco IOS IP/IPX/AT/IBM/PLUS
Cisco IOS IP/IPX	No	Cisco IOS IP/IPX/FW/PLUS

**Table 2** Cisco IOS 12.3T Availability

Cisco 1600R Series Feature Set	Cisco IOS Software 12.3T Mainline Support	Migration Path
Cisco IOS IP	No	—
Cisco IOS IP PLUS	No	—
Cisco IOS IP/IPX/FW/PLUS	No	—
Cisco IOS IP/FW/PLUS/IPSEC 56	No	—
Cisco IOS IP/IPX/AT/IBM/PLUS	No	—
Cisco IOS IP/IPX/AT/IBM/FW/PLUS/IPSEC 56	No	—
Cisco IOS IP PLUS/IPSEC 56	No	—
Cisco IOS IP/FW	No	—
Cisco IOS IP/IPX/AT/IBM	No	—
Cisco IOS IP/IPX	No	—

### Assistance

For questions concerning the Cisco 1600R Series routers, please contact Lingling Zhang at: [llzhang@cisco.com](mailto:llzhang@cisco.com)



Corporate Headquarters  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
[www.cisco.com](http://www.cisco.com)  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 526-4100

European Headquarters  
Cisco Systems International BV  
Haarlerbergpark  
Haarlerbergweg 13-19  
1101 CH Amsterdam  
The Netherlands  
[www-europe.cisco.com](http://www-europe.cisco.com)  
Tel: 31 0 20 357 1000  
Fax: 31 0 20 357 1100

Americas Headquarters  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
[www.cisco.com](http://www.cisco.com)  
Tel: 408 526-7660  
Fax: 408 527-0883

Asia Pacific Headquarters  
Cisco Systems, Inc.  
Capital Tower  
168 Robinson Road  
#22-01 to #29-01  
Singapore 068912  
[www.cisco.com](http://www.cisco.com)  
Tel: +65 317 7777  
Fax: +65 317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the **Cisco Web site at [www.cisco.com/go/offices](http://www.cisco.com/go/offices)**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia  
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland  
Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland  
Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden  
Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992–2002, Cisco Systems, Inc. All rights reserved. Cisco, Cisco IOS, Cisco Systems, and the Cisco Systems logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0208R) N2/LW3910 11/02