

CISCO 1701, 1711, AND 1712 SECURITY ROUTERS INCREASE DEFAULT DRAM TO 96 MB; NO INCREASE TO LIST PRICES

Cisco® 1701, 1711, and 1712 security routers provide high-performance VPN and firewall solutions to small and midsize businesses and enterprise small branch offices. Effective February 16, 2004, the default DRAM memory configuration for these routers will be upgraded from 64 to 96 MB, while the Flash memory will remain unchanged at 32 MB. The additional 32 MB of DRAM is provided in the form of a 32-MB dual in-line memory module (DIMM) that will be inserted in the internal DIMM slot.

Additional DRAM is being provided to help ensure that Cisco 1701, 1711, and 1712 security routers will be able to support new versions of Cisco IOS® Software that deliver new and more powerful security features. The additional memory will allow customers, resellers, and service providers to greatly benefit from the enhanced capabilities that Cisco IOS Software offers, both today and in the future. Upgrading memory through software changes also protects investments because it removes the need to make truck rolls or send out service staff to manually upgrade hardware.

CISCO 1701, 1711, AND 1712 DRAM AND FLASH MEMORY INFORMATION

- Run from RAM architecture
- Flash—Ships with 32 MB Flash
 - Onboard (fixed/default): 32 MB
 - Maximum: 32 MB
 - Support for dual Flash bank
- DRAM—Ships with 96 MB DRAM (NEW!)
 - Onboard (fixed/default): 64 MB
 - One DIMM slot: Populated with a 32-MB DIMM
 - Maximum DRAM: 128 MB

ORDERING INFORMATION

Product number: CISCO1701-K9

List price: See published price list

Product number: CISCO1711-VPN/K9

List price: See published price list

Product number: CISCO1712-VPN/K9

List price: See published price list

For more information, contact your account team or authorized reseller.



Corporate Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters
Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters
Cisco Systems, Inc.
168 Robinson Road
#28-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the
Cisco Web site at www.cisco.com/go/offices

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Cyprus
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland
Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland
Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden
Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992–2004 Cisco Systems, Inc. All rights reserved. CCIP, CCSP, the Cisco Arrow logo, the Cisco *Powered* Network mark, Cisco Unity, Follow Me Browsing, FormShare, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, the Cisco IOS logo, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherSwitch, Fast Step, GigaStack, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MGX, MICA, the Networkers logo, Networking Academy, Network Registrar, *Packet*, PIX, Post-Routing, Pre-Routing, RateMUX, Registrar, ScriptShare, SlideCast, SMARTnet, StrataView Plus, Stratim, SwitchProbe, TeleRouter, The Fastest Way to Increase Your Internet Quotient, TransPath, and VCO are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company.
(0402R) EC/KC/LW5889 3/04