



# Cisco IOS 12.3 Mainline Feature Sets for Cisco 3631

This Product Bulletin details the IOS software packaging for Cisco 3631 Routers in Cisco IOS 12.3 Mainline and 12.3T.

Note: This Product Bulletin covers the packaging of functionality into feature sets. It does not cover individual new features. For information about new features in Cisco IOS 12.3 Mainline and 12.3T, refer to the Cisco IOS software pages on [cisco.com](http://cisco.com).

## Overview

There are currently no changes to the software packaging for the 3631 routers. This bulletin is issued solely to ensure completeness of information.

## Cisco IOS 12.3 Mainline

### Overview of available feature sets in Cisco IOS 12.3 Mainline

The following Cisco IOS 12.3 Mainline Feature Sets will be available for the Cisco 3631.

Feature Set	Image Filename
<b>Special Purpose Feature Sets</b>	
TELCO FEATURE SET	c3631-telco-mz

Feature Set	Image Filename
TELCO PLUS FEATURE SET	c3631-telcoent-mz
TELCO PLUS IPSEC 3DES	c3631-telcoentk9-mz

Cisco IOS 12.3T

### Overview of available feature sets in Cisco IOS 12.3T

The following Cisco IOS 12.3T Feature Sets will be available for the Cisco 3631.

Feature Set	Image Filename
<b>Special Purpose Feature Sets</b>	
TELCO FEATURE SET	c3631-telco-mz
TELCO PLUS FEATURE SET	c3631-telcoent-mz
TELCO PLUS IPSEC 3DES	c3631-telcoentk9-mz



Corporate Headquarters  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 526-4100

European Headquarters  
Cisco Systems Europe  
11 Rue Camille Desmoulins  
92782 Issy-les-Moulineaux  
Cedex 9  
France  
www-europe.cisco.com  
Tel: 33 1 58 04 60 00  
Fax: 33 1 58 04 61 00

Americas Headquarters  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-7660  
Fax: 408 527-0883

Asia Pacific Headquarters  
Cisco Systems, Inc.  
Capital Tower  
168 Robinson Road  
#22-01 to #29-01  
Singapore 068912  
www.cisco.com  
Tel: +65 317 7777  
Fax: +65 317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the **Cisco Web site at [www.cisco.com/go/offices](http://www.cisco.com/go/offices)**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia  
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland  
Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland  
Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden  
Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992–2003, Cisco Systems, Inc. All rights reserved. CCIP, the Cisco Powered Network mark, the Cisco Systems Verified logo, Cisco Unity, Fast Step, Follow Me Browsing, FormShare, Internet Quotient, iQ Breakthrough, iQ Expertise, iQ FastTrack, the iQ logo, iQ Net Readiness Scorecard, Networking Academy, ScriptShare, SMARTnet, TransPath, and Voice LAN are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, Discover All That's Possible, The Fastest Way to Increase Your Internet Quotient, and iQuick Study are service marks of Cisco Systems, Inc.; and Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, the Cisco IOS logo, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherSwitch, GigaStack, IOS, IP/TV, LightStream, MGX, MICA, the Networkers logo, Network Registrar, Packet, PIX, Post-Routing, Pre-Routing, RateMUX, Registrar, SlideCast, StrataView Plus, Stratm, SwitchProbe, TeleRouter, and VCO are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company.  
(0201R) 201640/ETMG 02/02