



## Cisco iSCSI Driver Version 2.1.2 for HP-UX 10.2

The Cisco SN 5420, SN 5428, and Cisco SN Family of storage routers continue to be the industry's leading products that implement the Internet Small Computer Systems Interface (iSCSI) standard. As with all Cisco products, there will be continued improvements to the product based on both internal and customer testing. This product bulletin announces the new release of the Cisco Storage Networking iSCSI Driver Version 2.1.2 for HP-UX 10.2.

### HP-UX 10.2

This release package contains the HP-UX 10.2 iSCSI driver for the Internet Engineering Task Force (IETF) iSCSI Draft 08. The version number is 2.1.2.

Regular feedback is key to providing continued product improvements. Customer feedback through the Cisco Technical Assistance Center (TAC) is encouraged to identify and correct product issues.

### Backward Compatibility

The iSCSI driver Version 2.1.2 for HP-UX 10.2 can connect to a Cisco SN 5420 Storage Router running Software Release 2.1.1 or later; this driver cannot connect to a Cisco SN 5420 Storage Router running Software Release 1.1.x.

### Availability

The Cisco SN iSCSI Driver Version 2.1.2 for HP-UX 10.2 will be downloadable from Cisco.com on October 11, 2002.

### Obtaining the iSCSI Driver and Updated Cisco SN 5420 Series System Software

From time to time, Cisco releases updated versions of Cisco SN 5420 Series system software and iSCSI drivers. Updated versions of Cisco SN 5420 Series system software and the Cisco storage networking iSCSI drivers, accompanying readme files, release notes, and an example configuration file are available for download.

You may download Cisco SN 5420 Series system software and iSCSI drivers only if you are a registered Cisco.com user.

You can access software as follows:

- Step 1.** At <http://www.cisco.com>, log in to Cisco.com. Under Service & Support, click Software Center.
- Step 2.** At the Software Center Web page, under Software Products & Downloads, click Storage Networking Software.

**Step 3.** At the Storage Networking Software Web page, click the appropriate link for your software.

**Step 4.** At the software download Web page, click the file that you want to download. Another software download Web page will be displayed with detailed information about the download file and Cisco's Software License Agreement. Follow instructions on that page to download the software.

**Step 5.** To install and configure an iSCSI driver, see the readme file that accompanies the iSCSI driver (in the downloaded driver archive file) and the appropriate release notes.

#### Ordering Information

This downloadable file is available for no charge and does not require an order.



Corporate Headquarters  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 526-4100

European Headquarters  
Cisco Systems International BV  
Haarlerbergpark  
Haarlerbergweg 13-19  
1101 CH Amsterdam  
The Netherlands  
www-europe.cisco.com  
Tel: 31 0 20 357 1000  
Fax: 31 0 20 357 1100

Americas Headquarters  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-7660  
Fax: 408 527-0883

Asia Pacific Headquarters  
Cisco Systems, Inc.  
Capital Tower  
168 Robinson Road  
#22-01 to #29-01  
Singapore 068912  
www.cisco.com  
Tel: +65 317 7777  
Fax: +65 317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the **Cisco Web site at [www.cisco.com/go/offices](http://www.cisco.com/go/offices)**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia  
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland  
Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland  
Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden  
Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992–2002, Cisco Systems, Inc. All rights reserved. Cisco, Cisco IOS, Cisco Systems, and the Cisco Systems logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0208R) LW3738 1002