



End-of-Sale and End-of-Life Announcement for the Cisco OSR-7609 Chassis

Cisco Systems® announces the end of life of the Cisco® OSR-7609 including the related bundles OSR-7609-AC and OSR-7609-DC. The last day to order Cisco OSR-7609 is January 31, 2004. Customers will continue to receive from the Cisco Technical Assistance Center (TAC) until January 31, 2009. Table 1 describes the end-of-life milestones, definitions, and dates for the Cisco OSR-7609, OSR-7609-AC, and OSR-7609-DC bundles.

Customers are encouraged to migrate to the new Cisco 7609 Router. The 7609 Router delivers design improvements incorporating:

- Redundant, tiered-speed fan trays for greater airflow
- Increased power options for future power-intensive hardware
- Improved cable management for dense, cable-intensive configurations

Configurable options for route processor, switch fabric, and power supply redundancy are also provided in the new Cisco 7609 model chassis. Additional information about this product can be found at:

http://www.cisco.com/en/US/products/hw/routers/ps368/products_data_sheet09186a0080169ead.html

Table 3 provides relevant information for migrating from the Cisco OSR-7609 to the Cisco 7609 Router.

Table 1 End-of-Life Milestones and Dates for the Cisco OSR-7609 chassis

Milestone	Definition	Date
End-of-life announcement date	The date the end-of-sale and end-of-life announcement is distributed to the general public.	July 10, 2003
End of sale date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale.	January 31, 2004
Last shipment date	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead-time.	April 28, 2004
End of software maintenance releases date	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	January 31, 2005
End of routine failure analysis date	The last possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	January 31, 2005



Table 1 End-of-Life Milestones and Dates for the Cisco OSR-7609 chassis

Milestone	Definition	Date
End of new service attachment date	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	January 31, 2005
End of service contract renewal date	The last date to extend or renew a service contract for the product. The extension or renewal period cannot extend beyond the last date of support.	January 31, 2008
Last date of support	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	January 31, 2009

Table 2 Product Part Numbers Affected by This Announcement

End-of-Sale Part Number	Product Description
OSR-7609=	OSR-7609 spare 9-slot chassis
OSR-7609-AC	7609 chassis, Supervisor Engine2/Multilayer Switch Feature Card 2, 2500W AC P/S, 512 MB DRAM
OSR-7609-DC	7609 chassis, Supervisor Engine2/Multilayer Switch Feature Card 2, 2500W DC P/S, 512 MB DRAM

Table 3 Migration Product Part Numbers

End-of-Sale Part Number	New Part Number
OSR-7609=	CISCO7609=
OSR-7609-AC	7609-AC-BUN or 7609-SUP720-PS
OSR-7609-DC	7609-DC-BUN-2500W or 7609-SUP720-PS

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to:

<http://www.cisco.com/go/tradein/>

Additional Information

For more information about Cisco products, contact your Cisco account manager and/or Cisco Channel Partner.

For more information about the Cisco End-of-Life Policy, go to:

http://www.cisco.com/en/US/products/prod_end_of_life.html



Corporate Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters
Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters
Cisco Systems, Inc.
Capital Tower
168 Robinson Road
#22-01 to #29-01
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the

Cisco Web site at www.cisco.com/go/offices

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland
Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland
Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden
Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992-2003 Cisco Systems, Inc. All rights reserved. Cisco, Cisco Systems, and the Cisco Systems logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company.
(0304R) DB/LW4560 0703