



End of Sale Announcement on Cisco 802-IDSL and 804-IDSL Routers

Introduction:

End of Sale for the Cisco 802-IDSL and Cisco 804-IDSL Model Routers Series (July 8, 2002) is the first step in the Cisco End of Life process. The product will remain orderable for 3 months (last day to order is October 8, 2002). This document includes important information on dates associated with this process, SKUs affected, and product substitution matrix.

The Cisco 802IDSL and Cisco 804IDSL model routers are the only models in the Cisco 800 Series that have reached End of Sales.

Timeline

Event	Date	Definition
End of Sale Announcement	07/08/02	Formal announcement; first step in End of Life Process
End of Orderability	10/08/02	Hardware, Software, and Feature packs no longer orderable
Last Shipment	12/08/02	Estimated last date for orders shipped to customers
End of Support, Hardware	10/08/05	No exchanges or repairs after this date
End of Support, Software	10/08/07	No software fixes after this date

End of Sales Models

SKU	Description
CISCO802-IDSL	Cisco 802 IDSL Router with Internet DSL
CISCO804-IDSL	Cisco 804 IDSL Router with Internet DSL

Product Substitutions

Model	Description	Suggested Replacement
Cisco 802-IDSL	One 10BaseT, console port and 1-IDSL	Cisco 802 ISDN BRI/ETHERNET ROUTER
Cisco 804-IDSL	One 10BaseT with 4-port hub, console port and 1-IDSL	Cisco 804 ISDN BRI/ETHERNET ROUTER, NT-1, 4-PORT HUB, 2 POTS

Additional Information

For more information please contact your Cisco account manager, or customer service representative.



Corporate Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters
Cisco Systems Europe
11 Rue Camille Desmoulins
92782 Issy-les-Moulineaux
Cedex 9
France
www-europe.cisco.com
Tel: 33 1 58 04 60 00
Fax: 33 1 58 04 61 00

Americas Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters
Cisco Systems, Inc.
Capital Tower
168 Robinson Road
#22-01 to #29-01
Singapore 068912
www.cisco.com
Tel: +65 317 7777
Fax: +65 317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the
Cisco Web site at www.cisco.com/go/offices

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland
Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland
Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden
Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992–2002, Cisco Systems, Inc. All rights reserved. CCIP, the Cisco *Powered* Network mark, the Cisco Systems Verified logo, Cisco Unity, Follow Me Browsing, FormShare, Internet Quotient, iQ Breakthrough, iQ Expertise, iQ FastTrack, the iQ logo, iQ Net Readiness Scorecard, Networking Academy, ScriptShare, SMARTnet, TransPath, and Voice LAN are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, Discover All That's Possible, The Fastest Way to Increase Your Internet Quotient, and iQuick Study are service marks of Cisco Systems, Inc.; and Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, the Cisco IOS logo, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherSwitch, Fast Step, GigaStack, IOS, IP/TV, LightStream, MGX, MICA, the Networkers logo, Network Registrar, *Packet*, PIX, Post-Routing, Pre-Routing, RateMUX, Registrar, SlideCast, StrataView Plus, Stratm, SwitchProbe, TeleRouter, and VCO are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0203R)