

# End of Life Announcement

## Cisco 6200 Series DSLAM

### Overview

The Cisco 6200 Series Digital Subscriber Line access concentrator (DSLAM) is discontinued effective immediately. Customers are encouraged to purchase the Cisco 6260 IP DSL Switch platform for continuing digital subscriber line (DSL) rollouts.

### End of Sale and End of Life Announcements

This document contains the following information:

- Official notification of discontinuation of Cisco 6200.
- Official notification that the Cisco Technical Assistance Center (TAC) stopped providing support on December 31, 2000.
- Official notification that engineering support of software and hardware was completed on December 31, 2000.
- Last scheduled maintenance for the Cisco 6200 was released in April 2000.

### EoL for Cisco 6200

No orders for new, upgrade, or replacement sales for Cisco 6200 will be accepted. The following parts are affected:

- Cisco 6200 chassis
- Cisco 6200 power entry modules (PEMs)
- Line cards (SLC-1-8DMT and SLC-1-8CAP)
- Network cards (NTC-1OC3-SM and NTC-1OC3-MM)
- Cable or other accessories, spares, or customer documentation

The Cisco 6200 will not be used in customer demos, customer displays, or any other forms of marketing and advertising including internal and external Web pages.

### End of Maintenance and End of Cisco TAC Support

All Cisco TAC support activities ended December 31, 2000. Customers using Cisco 6200 have been informed about the alternatives to the Cisco 6200 units in their networks.



Corporate Headquarters  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 526-4100

European Headquarters  
Cisco Systems Europe  
11, Rue Camille Desmoulins  
92782 Issy Les Moulineaux  
Cedex 9  
France  
www.cisco.com  
Tel: 33 1 58 04 60 00  
Fax: 33 1 58 04 61 00

Americas Headquarters  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-7660  
Fax: 408 527-0883

Asia Pacific Headquarters  
Cisco Systems Australia, Pty., Ltd  
Level 17, 99 Walker Street  
North Sydney  
NSW 2059 Australia  
www.cisco.com  
Tel: +61 2 8448 7100  
Fax: +61 2 9957 4350

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the  
**Cisco.com Web site at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Czech Republic • Denmark • Dubai, UAE  
Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia  
Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam •

Copyright © 2001, Cisco Systems, Inc. All rights reserved. Printed in the USA. Cisco, Cisco IOS, Cisco Systems, and the Cisco Systems logo are registered trademarks of Cisco Systems, Inc. or its affiliates in the U.S. and certain other countries. All other brands, names, or trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0102R)