



4xFlexi Line Card **End-of-Life** Announcement

Overview

Cisco Systems is announcing the End of Life for the ATUC-4-FLX-2, the four-port line card supporting CAP, DMT, and G.lite line-coding methods, as well as the PSC-6120-3=, 6120 basic telephone service (POTS) Splitter Card for the 4xFlexi, and higher, and the following associated 4xFlexi bundles: FLEXBUN-30-STM1-SM, FLEXBUN-05-STM1-SM, FLEXBUN-10, and FLEXBUN-05-E1. Customers are encouraged to participate in the Cisco *Technology Migration Program (TMP) at http://www.cisco.com/offer/tic/TMP_PA.html and migrate to ATUC-8-DMT-1 for continuing digital subscriber line (DSL) roll-outs. The ATUC-8-DMT-1 continues to feature interoperability with Globespan-based customer premises equipment (CPE) while providing higher density.

*Please note that flexi bundles (FLEXBUN-30-STM1-SM, FLEXBUN-05-STM1-SM, FLEXBUN-10, and FLEXBUN-05-E1) are NOT eligible for Cisco TMP.

Table 1 Table 1 End-of-Life Products

Definitions: LTB = Last-time buy, EOE = End of Engineering (no more features)

Product Name	Description	LTB Date	EOE Date
ATUC-4-FLX-2	4-port CAP/DMT/G.Lite line card	26-Apr-02	26-Apr-02
ATUC-4-FLX-2=	4-port CAP/DMT/G.Lite line card	26-Apr-02	26-Apr-02
6100-THERMAL-UPGD=	Thermal Upgrade Kit for Cisco6100	26-Apr-02	26-Apr-02
6100-NU-01=	6100 NEBS Upgrade Kit	26-Apr-02	26-Apr-02
6100-UPGD-NI2=	6100 NI-2 Upgrade Kit	26-Apr-02	26-Apr-02
6130-THERMAL-UPGD=	Thermal Upgrade Kit for Cisco6130	26-Apr-02	26-Apr-02
6130-UPGD-NI2=	6130 NI-2 Upgrade Kit	26-Apr-02	26-Apr-02
PSC-6120-3=	DMT/CAP 4x POTS splitter card for 6120, ATUC-4-FLX-2. and Higher	26-Apr-02	26-Apr-02
FLEXBUN-30-STM1-SM	6260 STM1(SM) bundle with 30 Flexi line cards	26-Apr-02	26-Apr-02
FLEXBUN-05-STM1-SM	6260 STM1(SM) bundle with 5 Flexi line cards	26-Apr-02	26-Apr-02
FLEXBUN-10	Bundle of 10 Flexi line cards	26-Apr-02	26-Apr-02
FLEXBUN-05-E1	6260 E1 bundle with 5 Flexi line cards	26-Apr-02	26-Apr-02

End of Sales

No hardware will be orderable after this date through Customer Service or Manufacturing.

End of Engineering

Date after which no scheduled features will be developed/added for the product. Maintenance software releases supporting the above hardware will still be available through FSO and CCO for customers under maintenance contract or for CSE support until they reach "End of Life." The customer is highly encouraged to migrate to new IP DSL products available at that time.

End of Life

A minimum of three years following End of Engineering; any issues with software or hardware beyond these dates will not be addressed. The customer will be required to migrate to new Cisco products available at that time.

Date for Discontinuing Renewal of Contracts

Existing service contracts will be honored. New contracts will not be honored beyond end-of-engineering dates.



Corporate Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters

Cisco Systems Europe
11, Rue Camille Desmoulins
92782 Issy-les-Moulineaux
Cedex 9
France
www-europe.cisco.com
Tel: 33 1 58 04 60 00
Fax: 33 1 58 04 61 00

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems, Inc.
Capital Tower
168 Robinson Road
#22-01 to #29-01
Singapore 068912
www.cisco.com
Tel: 65 317 7777
Fax: 65 317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the Cisco Web site at www.cisco.com/go/offices

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992–2002 Cisco Systems, Inc. All rights reserved. Cisco, Cisco IOS, Cisco Systems, and the Cisco Systems logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0110R) 1/02 LW2966