



End-of-Life Announcement for Cisco Service Expansion Shelf PNNI Controller Software Versions 1.0.x and 1.1.6.x

Cisco Systems is officially announcing the end of sales and end of life (EOS/EOL) for the Cisco Service Expansion Shelf (SES) Switch Software versions 1.0.x and 1.1.6x with an effective announcement date of June 28, 2002. Cisco customers may continue to receive software support for a longer period as set forth in the milestones and timelines in Table 1.

Cisco SES Switch Software Release 1.1.70 or later releases will replace the software versions affected by this announcement. Cisco SES Switch Software Release 1.1.70 or later software releases will have additional PNNI features, bug fixes, and support higher connection counts than previous SES 1.0.x software releases. Customers are encouraged to upgrade to the later software releases to take advantage of these enhancements.

In summary, the milestones, their definitions, and effective EOL dates for the Cisco SES Switch Software are listed in Table..

Table 1 Milestones and Effective End-of-Life Dates for Cisco Cisco SES Switch Software

Milestone	Definition	Effective Date
End-of-sales announcement	The date that the end of sales announcement will be released to the public.	June 28, 2002
End of sales	The last date to enter orders of the product in the Cisco Marketplace "Orderability" Tool.	December 27, 2002
End of production	The date that Cisco Manufacturing completed/will complete fulfillment and shipment of new equipment purchase orders.	January 27, 2003
End of hardware maintenance (engineering)	The date that Cisco Engineering ceased or will cease considering the repair/maintenance of confirmed hardware defects related to components within this system configuration.	_ ¹
End of software maintenance (engineering)	The date that Cisco Engineering ceased or will cease considering the repair/maintenance of confirmed operating system software defects or card download software defects within this system configuration.	June 28, 2005



Table 1 Milestones and Effective End-of-Life Dates for Cisco Cisco SES Switch Software

Milestone	Definition	Effective Date
Discontinue contract renewal	The date that renewing/extending a service contract for this system will discontinue.	–
End of support/end of life/product obsolescence	The date that Cisco Logistics will no longer have any obligation to support the products listed in this product bulletin. This includes processing RMA orders for components with this system configuration; it is also the date that the Cisco Technical Assistance Center (TAC) will no longer have any obligation to assist customers with any issues related to this software. Any assistance rendered by Cisco will be on an as available basis without warranties at the sole discretion of Cisco Systems.	June28, 2007

1 Not Applicable

Cisco SES Switch Software Part Numbers

Table 2 lists the Cisco SES Switch Software part numbers that are affected by this EOS/EOL announcement.

Table 2 Cisco SES Switch Software Part Numbers

Product Number	Product Description	EOS Last Order (Sales) Date	End of Production Last Shipment Date	End of Engineering Hardware Maintenance Date	End of Engineering Software Maintenance Date	Dis-continue Contract Renewal Date	End of Support/Product Obsolescence Date
SESSW-CNTL-1011 CD=	SES Controller SW License - Spare CD (Version 1011)	12/27/2002	1/27/2003	– ¹	6/28/2005	–	6/28/2007
SESSW-CNTL-1012	SES Controller SW License - Rel (Version 1012)	12/27/2002	1/27/2003	–	6/28/2005	–	6/28/2007
SESSW-CNTL-1013 CD=	SES Controller SW License - Spare CD (Version 1013)	12/27/2002	1/27/2003	–	6/28/2005	–	6/28/2007
SESSW-CNTL-1013	SES Controller SW License - Rel (Version 1013)	12/27/2002	1/27/2003	–	6/28/2005	–	6/28/2007
SESSW-CNTL-1014 CD=	SES Controller SW License - Spare CD (Version 1014)	12/27/2002	1/27/2003	–	6/28/2005	–	6/28/2007
SESSW-CNTL-1014	SES Controller SW License - Rel (Version 1014)	12/27/2002	1/27/2003	–	6/28/2005	–	6/28/2007
SESSW-CNTL-1015	SES Controller SW License - Rel (Version 1015)	12/27/2002	1/27/2003	–	6/28/2005	–	6/28/2007
SESSW-CNTL-1016 CD=	SES Controller SW License - Spare CD (Version 1016)	12/27/2002	1/27/2003	–	6/28/2005	–	6/28/2007
SESSW-CNTL-1016	SES Controller SW License - Rel (Version 1016)	12/27/2002	1/27/2003	–	6/28/2005	–	6/28/2007
SESSW-CNTL-1160 CD=	SES Controller SW License - Spare CD (Version 1160)	12/27/2002	1/27/2003	–	6/28/2005	–	6/28/2007
SESSW-CNTL-1160	SES Controller SW License - Rel (Version 1160)	12/27/2002	1/27/2003	–	6/28/2005	–	6/28/2007

¹ Not Applicable

Ordering Information

December 27, 2002 will be the last date to enter orders for Cisco Cisco SES Switching Software versions 1.0.x and 1.1.6x. Support for software will be provided according to the effective dates stated in Table 1.

For More Information

Peter Chang

Technical Leader

Phone:408 527-4768

E-mail: petchang@cisco.com

CISCO SYSTEMS



Corporate Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA

www.cisco.com

Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters

Cisco Systems Europe
11 Rue Camille Desmoulins
92782 Issy-les-Moulineaux
Cedex 9
France

www-europe.cisco.com

Tel: 33 1 58 04 60 00
Fax: 33 1 58 04 61 00

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA

www.cisco.com

Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems, Inc.
Capital Tower
168 Robinson Road
#22-01 to #29-01
Singapore 068912

www.cisco.com

Tel: +65 317 7777
Fax: +65 317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the Cisco Web site at www.cisco.com/go/offices

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992–2002, Cisco Systems, Inc. All rights reserved. Cisco, Cisco IOS, Cisco Systems, and the Cisco Systems logo, are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0201R)

LW3092 03/02