

# End-of-Life Announcement for Catalyst 5000 DC Power Supply

## Overview

Cisco Systems' Workgroup Business Unit is announcing the end of life (EOL) of the following Catalyst® 5000 DC power supply:

Table 1 End-of-Life Products

Cisco Part Number	Description
WS-C5068	Catalyst 5000 DC Power Supply
WS-C5068=	Catalyst 5000 DC Power Supply (spare)
WS-C5068/2	Catalyst 5000 Redundant DC Power Supply

End of sales date: December 8, 1998

## Ordering Information for Catalyst 5000

After December 8, 1998, orders for the above power supply should be replaced with the WS-C5068B power supply:

Table 2 Replacement Products for Catalyst 5000

Cisco Part Number	Description
WS-C5068B	Catalyst 5000/5505 DC Power Supply
WS-C5068B=	Catalyst 5000/5505 DC Power Supply (spare)
WS-C5068B/2	Catalyst 5000/5505 Redundant DC Power Supply

The WS-C5068B power supply has the same form, fit, and function as the WS-C5068 and can be substituted for WS-C5068 in all situations. WS-C5068 and WS-C5068B power supplies can be used together in redundant configurations. The only difference with WS-C5068B is its ability to handle more current than the WS-C5068; this increase is required for the Catalyst 5505 with Supervisor III.

## Ordering Information for LightStream 1010

After December 8, 1998, orders for the LightStream® 1010 DC power supply will have the same part numbers as before:

Table 3 Power Supply for LightStream 1010

Cisco Part Number	Description
L1010-PWR-DC	Power Supply – DC (default)
L1010-PWR-DC=	Spare Power Supply – DC (default)
L1010-PWR-DC/2	Redundant Power Supply – DC (installed)

A WS-C5068B power supply will be shipped when the above power supplies are ordered.

The WS-C5068B power supply has the same form, fit, and function as the L1010-PWR-DC and can substitute for L1010-PWR-DC in all situations. L1010-PWR-DC and WS-C5068B can be used together in redundant configurations. The only difference with the WS-C5068B is its ability to handle more current than L1010-PWR-DC.

## Ordering Information for Catalyst 8510

After December 8, 1998, orders for the Catalyst 8510 DC power supply will have the same part number as before:

Table 4 Power Supply for Catalyst 8510

Cisco Part Number	Description
C8510-PWR-DC	Catalyst 8510 CSR Power Supply – DC (installed)
C8510-PWR-DC/2	Catalyst 8510 CSR Redundant Power Supply – DC (installed)
C8510-PWR-DC=	Catalyst 8510 CSR Power Supply – DC (spare)

A WS-C5068B power supply will be shipped when the above power supplies are ordered.

The WS-C5068B power supply has the same form, fit, and function as the C8510-PWR-DC, and can substitute for C8510-PWR-DC in all situations. The C8510-PWR-DC and WS-C5068B can be used together in redundant configurations. The only difference with the WS-C5068B is its ability to handle more current than the C8510-PWR-DC.



### Corporate Headquarters

Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
<http://www.cisco.com>  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 526-4100

### European Headquarters

Cisco Systems Europe s.a.r.l.  
Parc Evolic, Batiment L1/L2  
16 Avenue du Quebec  
Villebon, BP 706  
91961 Courtaboeuf Cedex  
France  
<http://www-europe.cisco.com>  
Tel: 33 1 6918 61 00  
Fax: 33 1 6928 83 26

### Americas

**Headquarters**  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
<http://www.cisco.com>  
Tel: 408 526-7660  
Fax: 408 527-0883

### Asia Headquarters

Nihon Cisco Systems K.K.  
Fuji Building, 9th Floor  
3-2-3 Marunouchi  
Chiyoda-ku, Tokyo 100  
Japan  
<http://www.cisco.com>  
Tel: 81 3 5219 6250  
Fax: 81 3 5219 6001

Cisco Systems has more than 200 offices in the following countries. Addresses, phone numbers, and fax numbers are listed on the Cisco Connection Online Web site at <http://www.cisco.com>.

Argentina • Australia • Austria • Belgium • Brazil • Canada • Chile • China (PRC) • Colombia • Costa Rica • Czech Republic • Denmark • England • France • Germany • Greece • Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Russia • Saudi Arabia • Scotland • Singapore • South Africa • Spain • Sweden • Switzerland • Taiwan, ROC • Thailand • Turkey • United Arab Emirates • United States • Venezuela