

End-of-Sale Announcement for Cisco Secure IDS Token Ring and FDDI Sensors

Because of limited customer demand, Cisco System is discontinuing the sale of the Cisco Secure Intrusion Detection System (IDS) Token Ring and FDDI Sensors. Cisco will continue to develop and sell Ethernet and Fast Ethernet Sensors.

Affected Product Numbers

- IDS-4220-TR
- IDS-4230-SFDDI
- IDS-4230-DFDDI
- NRS-TR (replaced by IDS-4220-TR in January 2000)
- NRS-TR-DM (replaced by IDS-4220-TR in January 2000)
- NRS-SFDDI (replaced by IDS-4230-SFDDI in January 2000)
- NRS-SFDDI-DM (replaced by IDS-4230-SFDDI in January 2000)
- NRS-DFDDI (replaced by IDS-4230-DFDDI in January 2000)
- NRS-DFDDI-DM (replaced by IDS-4230-DFDDI in January 2000)

End of Order Availability for Token Ring and FDDI Sensors

October 1, 2000

Last Shipment of Token Ring and FDDI Sensors

October 31, 2000

Assistance

For questions about orders, please contact your customer service representative.

Support

End of sale refers to the time when certain products are no longer available for new purchases. It does not apply to the service and support programs for those products. Cisco will continue to provide hardware support for the Token Ring and FDDI Sensors through the SMARTnet™ program until October 1, 2003 (three years after this announcement). Customers with maintenance support contracts are entitled to 24-hour phone support through the Technical Assistance Center.



Corporate Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters
Cisco Systems Europe
11, Rue Camille Desmoulins
92782 Issy Les Moulineaux
Cedex 9
France
www.cisco.com
Tel: 33 1 58 04 60 00
Fax: 33 1 58 04 61 00

Americas
Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific
Headquarters
Cisco Systems Australia, Pty., Ltd
Level 17, 99 Walker Street
North Sydney NSW 2059
Australia
www.cisco.com
Tel: +61 2 8448 7100
Fax: +61 2 9957 4350

Cisco Systems has more than 190 offices in the following countries. Addresses, phone numbers, and fax numbers are listed on the

Cisco.com Web site at www.cisco.com/go/offices.

Argentina • Australia • Austria • Belgium • Brazil • Canada • Chile • China • Colombia • Costa Rica • Croatia • Czech Republic • Denmark • Dubai, UAE
Finland • France • Germany • Greece • Hong Kong • Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia
Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Singapore
Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela

Copyright © 2000, Cisco Systems, Inc. All rights reserved. Printed in the USA. SMARTnet is a trademark, and Cisco, Cisco IOS, Cisco Systems, and the Cisco Systems logo are registered trademarks of Cisco Systems, Inc. or its affiliates in the U.S. and certain other countries. All other trademarks mentioned in this document are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0007R) 7/00 LW