



## Mac OS Support Now Available for Cisco Aironet 5 GHz 54 Mbps Client Adapters

Cisco Systems® is pleased to announce that Mac operating system (OS) driver and utilities software release 3.0 for Mac OS 9.X and Mac OS X (10.2) provides support for Cisco® Aironet® 5 GHz 54 Mbps 802.11a client adapters and delivers two new end user features.

Cisco Aironet wireless LAN client adapter driver and utilities release version 3.0 for Mac OS provides support for the following new features:

- *Cisco Aironet Client Adapter Support*—This release supports both 2.4 GHz IEEE 802.11b and 5 GHz IEEE 802.11a client adapters:
  - Cisco Aironet 5 GHz 54 Mbps Cardbus 20A IEEE 802.11a wireless LAN client adapter support for Mac OS 9.X and Mac OS X (10.2 or later) when client adapter Firmware version 5.01.02 or later is installed.
  - Cisco Aironet 350, 340, and 4800 Series PCMCIA, LMC, and PCI IEEE 802.11b wireless LAN client adapter support for Mac OS 9.X and Mac OS X (10.1 or later) when client adapter Firmware version 4.25.30 or later is installed.
  - The client adapter software automatically detects the type of client adapter installed.
- *New Aironet Desktop Controls*—New desktop controls are now automatically installed with the client utility. Desktop controls provide a convenient way for end users to view client adapter status and initiate common client adapter tasks, such as location selection or Cisco LEAP logon.
- *Multuser Support*—Multiple users may now easily share a single computer with the new multuser feature available with this release.

Download this software release from the [Cisco Wireless Software Center](#).

## CISCO SYSTEMS



Corporate Headquarters  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
[www.cisco.com](http://www.cisco.com)  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 526-4100

European Headquarters  
Cisco Systems International BV  
Haarlerbergpark  
Haarlerbergweg 13-19  
1101 CH Amsterdam  
The Netherlands  
[www-europe.cisco.com](http://www-europe.cisco.com)  
Tel: 31 0 20 357 1000  
Fax: 31 0 20 357 1100

Americas Headquarters  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
[www.cisco.com](http://www.cisco.com)  
Tel: 408 526-7660  
Fax: 408 527-0883

Asia Pacific Headquarters  
Cisco Systems, Inc.  
Capital Tower  
168 Robinson Road  
#22-01 to #29-01  
Singapore 068912  
[www.cisco.com](http://www.cisco.com)  
Tel: +65 6317 7777  
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the  
**Cisco Web site at [www.cisco.com/go/offices](http://www.cisco.com/go/offices)**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia  
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland  
Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland  
Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden  
Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992-2003 Cisco Systems, Inc. All rights reserved. Aironet, Cisco, Cisco IOS, Cisco Systems, and the Cisco Systems logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0303R)