

# End-of-Life **Announcement** for Cisco Aironet Wireless LAN Antenna Cables



As part of our continuing effort to enhance the Cisco Aironet® product line, Cisco Systems is pleased to announce new, improved wireless LAN antenna cables and the End-of-Life of Cisco Aironet antenna cables as per the descriptions and schedules detailed below. The new cables are the suggested replacements for the discontinued cables.

EoL Part Numbers	Description	Last Order Date	Last Support Date	Suggested Replacements (New Cables)	Description of Suggested Replacements
AIR-420-003346-020	20 ft. cable with RP-TNC connectors	February 27, 2002	February 27, 2007	AIR-CAB020LL-R	20-ft. low-loss cable with RP-TNC connectors
AIR-420-003346-050	50 ft. cable with RP-TNC connectors	February 27, 2002	February 27, 2007	AIR-CAB050LL-R	50-ft. low-loss cable with RP-TNC connectors
AIR-420-003346-075	75 ft. cable with RP-TNC connectors	February 27, 2002	February 27, 2007	AIR-CAB100ULL-R	100-ft. ultra-low-loss cable with RP-TNC connectors
AIR-420-003346-100	100 ft. cable with RP-TNC connectors	February 27, 2002	February 27, 2007	AIR-CAB100ULL-R or AIR-CAB150ULL-R	100-ft. ultra-low-loss cable with RP-TNC connectors or 150-ft. ultra-low-loss cable with RP-TNC connectors

The new outdoor-rated, low-loss cables have improved insulation and are far less susceptible to water penetration than the previous cables. In addition, the new 100- and 150-foot ultra-low-loss cables now feature 4.4 dB loss per 100 feet, greatly improving the quality of the radio signal and range when applications require expanded cable lengths.



Corporate Headquarters  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 526-4100

European Headquarters  
Cisco Systems Europe  
11, Rue Camille Desmoulins  
92782 Issy-les-Moulineaux  
Cedex 9  
France  
www-europe.cisco.com  
Tel: 33 1 58 04 60 00  
Fax: 33 1 58 04 61 00

Americas Headquarters  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-7660  
Fax: 408 527-0883

Asia Pacific Headquarters  
Cisco Systems, Inc.  
Capital Tower  
168 Robinson Road  
#22-01 to #29-01  
Singapore 068912  
Tel: +65 317 7777  
Fax: +65 317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the

**Cisco Web site at [www.cisco.com/go/offices](http://www.cisco.com/go/offices)**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia  
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia  
Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru  
Philippines • Poland • Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa  
Spain • Sweden • Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2001, Cisco Systems, Inc. All rights reserved. Aironet, Cisco, Cisco IOS, Cisco Systems, and the Cisco Systems logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0110R)