



End-of-Sale and End-of-Life Announcement for Cisco Aironet Antenna AIR-ANT4121

Cisco Systems® announces the end of life of a Cisco® Aironet® 2.4 GHz antenna, with part number AIR-ANT4121. The last day to order the Cisco Aironet antenna with part number AIR-ANT4121 is November 3, 2003. Customers will continue to receive support from the Cisco Technical Assistance Center (TAC) until May 7, 2008. Table 1 describes the end-of-life milestones, definitions, and dates for the Cisco Aironet antenna.

Customers are encouraged to migrate to the Cisco Aironet antenna with part number AIR-ANT24120, which offers an efficiently designed fiberglass radome, which minimizes distortion and provides for maximum range and better coverage than the previous antenna (AIR-ANT4121). Table 2 compares the Cisco AIR-ANT4121 with the Cisco AIR-ANT24120.

Table 1 End-of-Life Milestones and Dates for the AIR-ANT4121

Milestone	Definition	Date
End-of-life announcement date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	May 7, 2003
End-of-sale date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	November 3, 2003
Last shipment date	The last-possible date that Cisco and/or its contract manufacturers will ship the affected product. Actual ship date is dependent on lead time.	February 1, 2004
Last Date of Support	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	May 7, 2008



Product Migration Options

Table 2 Product Comparisons

Part number	AIR-ANT4121	AIR-ANT24120
Description	2.4 GHz, 12 dBi omni mast mount antenna with RP-TNC connector	2.4 GHz, 12 dBi omni mast mount antenna with RP-TNC connector

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

Additional Information

For more information about Cisco products, please contact your Cisco account manager and/or Cisco Channel Partner.

For more information about the Cisco End-of-Life Policy, go to:

http://www.cisco.com/en/US/products/prod_end_of_life.html



Corporate Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters
Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters
Cisco Systems, Inc.
Capital Tower
168 Robinson Road
#22-01 to #29-01
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the **Cisco Web site at www.cisco.com/go/offices**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland
Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland
Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden
Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992–2003 Cisco Systems, Inc. All rights reserved. Aironet, Cisco, Cisco Systems, and the Cisco Systems logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0303R)