



Retraction of End-of-Sale and End-of-Life Announcement for the Cisco StadiumVision Director 2.3 and Earlier

EOL7986

Cisco has retracted the EOS and EOL announcement for the Cisco StadiumVision Director 2.3 and Earlier.

Cisco StadiumVision Director 2.3 and Earlier have been restored to their supported status. The products impacted by this announcement are in table 1 below.

Table 1. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description
SV-DIRECTOR-K9	StadiumVision Director Base License and Platform

For More Information

For more information about the Cisco StadiumVision Director, go to:

<http://www.cisco.com/en/US/products/ps11277/index.html>.

For more information about the Cisco End-of-Life Policy, go to:

http://www.cisco.com/en/US/products/prod_end_of_life.html.

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application:

http://www.cisco.com/web/feeds/products/end_of_life_rss.xml.



Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)