

Release Notes for Cisco RV110W Firmware Version 1.2.1.7

July 2016

These Release Notes describe the resolved and known issues in the Cisco RV110W firmware version 1.2.1.7.

Contents

This document includes the following topics:

- [Changes Since Firmware Version 1.2.0.14](#)
- [Related Information](#)

Changes Since Firmware Version 1.2.0.14

Issues Resolved

- Authenticated buffer overflow changing password (CSCux86664)
- Authenticated Cross Site Scripting (CSCux82567)
- Authenticated buffer overflow (CSCux82523)
- Command injection (CSCux82428)

Known Issues

Ref Number	Description
CSCur41420	<p>Traffic does not pass through the IPv6 6RD tunnel if the tunnel mode is set to Auto.</p> <p>Workaround Pullout the WAN cable then replug it, or use Manual tunnel mode.</p>
CSCur41425	<p>Downstream queues do not follow the specified priorities for the application service based QoS.</p> <p>Workaround None.</p>
CSCuq46880	<p>When restoring the configuration file from another RV215W device, the serial number is also copied from the new device.</p> <p>Workaround Reboot the device again to make the original serial number take effect.</p>
CSCuq47016	<p>The wireless MAC address filter settings are lost after the firmware is upgraded.</p> <p>Workaround Reconfigure the wireless MAC filter setting.</p>

Related Information

Support	
Cisco Support Community	www.cisco.com/go/smallbizsupport
Cisco Support and Resources	www.cisco.com/go/smallbizhelp
Phone Support Contacts	www.cisco.com/en/US/support/tsd_cisco_small_business_support_center_contacts.html
Cisco Firmware Downloads	www.cisco.com/go/smallbizfirmware Select a link to download firmware for Cisco Products. No login is required.
Product Documentation	
Cisco RV110W	www.cisco.com/go/rv110w
Cisco Partner Central (Partner Login Required)	www.cisco.com/web/partners/sell/smb

For EU lot 26 related test result, please check this web page: www.cisco.com/go/eu-lot26-results.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2014 Cisco Systems, Inc. All rights reserved.