

Release Notes for Cisco WRV210 Wireless-G VPN Router with RangeBooster Firmware Version 1.1.17

10/9/2009

These Release Notes describe the enhancements in the Cisco WRV210 firmware version 1.1.17.

Contents

This document includes the following topics:

- [Changes Since Cisco WRV210 Firmware Version 1.1.16](#)
- [Related Information](#)

Changes Since Cisco WRV210 Firmware Version 1.1.16

Changes to the GUI

In firmware version 1.1.17, the web-based configuration utility now supports the following languages:

- English
- Spanish
- French
- Italian

Release Notes

- Portuguese
- German

Known Issues

The following are known issues.

- When the router is set to the Router mode, the WAN port does not get a DHCP IP address.
- You must enable Windows Firewall on Windows Vista for QuickVPN Client to function properly.

This is because the IPSec service on Vista is disabled when Windows Firewall is disabled.

- There is a known issue with Windows XP SP2 Firewall where ICMP packets are always dropped by the Firewall when the Firewall is enabled.

The issue causes the QuickVPN Client to fail in establishing a tunnel with the remote QuickVPN Server.

Microsoft has released a patch to fix this issue. After you install the patch, the issue should be resolved.

<http://support.microsoft.com/kb/889527/en-us>

Related Information

Support	
Cisco Small Business Support Community	www.cisco.com/go/smallbizsupport
Online Technical Support and Documentation (Login Required)	www.cisco.com/support
Phone Support Contacts	www.cisco.com/en/US/support/tsd_cisco_small_business_support_center_contacts.html
Software Downloads (Login Required)	Go to tools.cisco.com/support/downloads , and enter the model number in the Software Search box.
Product Documentation	
Cisco WRV210 Wireless-G VPN Router with RangeBooster	www.cisco.com/en/US/products/ps9923/tsd_products_support_series_home.html
Cisco Small Business	
Cisco Partner Central for Small Business (Partner Login Required)	www.cisco.com/web/partners/sell/smb
Cisco Small Business Home	www.cisco.com/smb
Marketplace	www.cisco.com/go/marketplace

Cisco, Cisco Systems, the Cisco logo, and the Cisco Systems logo are registered trademarks or trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries. All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0705R)

© 2009 Cisco Systems, Inc. All rights reserved.

OL-20883-01