



# Cisco OptoStar II Console Release 3.0 Release Note

## Overview

This release supports the OptoStar II Console software. It incorporates the new features for the Console software.

## Purpose

This document lists the new features in Release 3.0, and provides instructions for downloading and installing the software.

## Audience

This document is intended for qualified and skilled personnel who configure the system. These personnel should understand basic optics, RF, and network monitoring operations.

## Qualified Personnel

Only appropriately qualified and skilled service personnel should attempt to install, operate, maintain, and service this product.



### **WARNING:**

**Allow only qualified and skilled personnel to install, operate, maintain, and service this product. Otherwise, personal injury or equipment damage may occur.**

## Related Publication

You may find the following publication useful as you implement the procedures in this document:

- *Cisco OptoStar II Console Software Installation and Operation Guide*, part number OL-29664

## Document Version

This is the first version of the release note.

## In This Document

■ Release Purpose .....	3
■ Changes in Functionality.....	4
■ Using the Bug Tool Kit.....	5
■ Installation Instructions .....	6
■ For Information.....	7

## Release Purpose

### **Hardware**

This release includes no hardware changes or updates.

### **Firmware**

This release includes software changes or updates.

## Changes in Functionality

This release contains functionality changes:

- In the parameter setting window of the 1310 nm Transmitter module, a note is added under the RF Input Level field: The RF input level increases by 12dB when there is only narrowcast input.
- In the parameter setting window of the Reverse Receiver/Forward Receiver module, a new MGC OFF option is added.

## Using the Bug Tool Kit

If you need information about a specific caveat that does not appear in this release note, you can use the Cisco Bug Toolkit to find caveats of any severity. Use the following URL to access the Bug Toolkit:

<http://tools.cisco.com/Support/BugToolkit/>

If you request a defect that cannot be displayed, the defect number might not exist, the defect might not yet have a customer-visible description, or the defect might be marked Cisco Confidential.


# Installation Instructions

## To Download the System Release

Complete the following steps to get the latest software releases.

1. Go to the support section of the Cisco website (<http://www.cisco.com>).  
**Note:** If you have not done so, you will need to set up an account to access the software releases.
2. From the Support menu, choose **All Downloads** and then use the selection tree to find the appropriate products.

The following figure shows the general layout of the software download page accessible from the Cisco website.



For example, OptoStar II Console Release 3.0 software is listed under Products > Video > Access/Edge > Optoelectronics > Cisco OptoStar II Products.

3. Download the appropriate files, depending on your needs.

## To Install the Latest Software

Double click the downloaded executable file, and then install the latest software according to the on-screen instructions. For detailed information, see the *Cisco OptoStar II Console Software Installation and Operation Guide*, part number OL-29664.

## For Information

### **If You Have Questions**

If you have technical questions, call Cisco Services for assistance. Follow the menu options to speak with a service engineer.



**Americas Headquarters**

Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA

<http://www.cisco.com>

Tel: 408 526-4000

800 553-6387

Fax: 408 527-0883

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL:

<http://www.cisco.com/go/trademarks>

Third party trademarks mentioned are the property of their respective owners.

The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Product and service availability are subject to change without notice.

© 2014 Cisco and/or its affiliates. All rights reserved.

First Published: 8/22/2014