

Release Notes for Cisco SPA8000 8-Port IP Telephony Gateway Firmware Version 6.1.11

June 2012

These Release Notes describe the new features and enhancements in the Cisco SPA8000 firmware version 6.1.11.

Contents

This document includes the following topics:

- [Changes Since Cisco SPA8000 Firmware Version 6.1.3](#)
- [Related Information](#)

Changes Since Cisco SPA8000 Firmware Version 6.1.3

- Added an option to reuse the Caller ID (phone number) as the caller name. See the *Voice > Line* page, *Supplementary Service Subscription* section, *Reuse CID Number As Name* field.
- Fixed an issue to support special characters in the Display Name. (CSCtr15943)
- Fixed an issue to ensure that the dial plan settings apply to phone numbers that a user enters for call forwarding. (CSCty20351)
- Fixed an issue in which the CoS settings for L3-L8 were not applied. (CSCsr15922)

Related Information

Support	
Cisco Small Business Support Community	www.cisco.com/go/smallbizsupport
Cisco Small Business Support and Resources	www.cisco.com/go/smallbizhelp
Cisco Small Business Firmware Downloads	www.cisco.com/go/smallbizfirmware
Product Documentation	
Cisco SPA8000	www.cisco.com/go/smallbizvoicegateways
Cisco Small Business	
Cisco Partner Central for Small Business (Partner Login Required)	www.cisco.com/web/partners/sell/smb
Cisco Small Business Home	www.cisco.com/smb

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2012 Cisco Systems, Inc. All rights reserved.

78-20815-01